# LICENSEE EVENT REPORT

Attachment 1

CONTROL BLOCK:
0 1 PATM 1 2 3 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 0 57 CAT 58 6
CON'T REPORT L 6 0 5 0 0 0 3 2 0 7 0 9 3 0 8 0 8 1 0 3 0 8 0 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 BEPORT DATE 80
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  [0 2 On Sept. 30, 1980 at 1030 hours the feeder breakers for busses 2-38 and 2-48 were re-
0 2 On Sept. 30, 1980 at 1030 hours the reeder ortaker
[0]3 moved from service for maintenance. Intodan the survived husses. Consequently, the out
[0]4 was not initiated for removal of the Tech. Spec. required busses. Consequently, the out
of Spec. condition exceeded the applicable Action period before the situation was cor-
[0]6] [rected. This was a violation of Tech. Spec. 3.8.1.2 and is considered reportable under]
O 7   Section 6.9.1.8(b). This event had no effect on the plant, its operation, or the
health and safety of the public.
7 8 9 SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBCODE
E B 11 A 12 A 13 C K T B R K 14 A (15) Z (16)  REVISION NO.
17) REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32 COMPONENT
ACTION FUTURE CFFECT SHUTDOWN HOURS 22 ATTACHMENT FORM SUB SUPPLIER SUBMITTED FORM SUB SUPPLIER SUBMITTED FORM SUB SUPPLIER SUPPLIER SUBMITTED FORM SUB SUPPLIER SUPPLIER SUBMITTED FORM SUB SUPPLIER SUBMITTED FORM SUB SUPPLIER SUPPLIER SUBMITTED FORM SUB SUB SUPPLIER SUBMITTED FORM SUB SUPPLIER SUBMITTED FORM SUB SUB SUPPLIER SUBMITTED FORM SUB
The event resulted from the Shift Foreman not checking the Tech. Specs. as appropriate.
[1] [and consequently, not initiating the time clock. Once identified, the buss feeder
To bolster the
[1] breakers were replaced and the basses [1] breakers were replaced and
1 3   foreman's knowledge, in the training type search search and search
[1] [qual Program will include a class in which all T.S. required equipment is identified.]
7 8 9 FACILITY STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32  1 15   X   (28)   0   0   (29) Recovery Mode   B   (31) Operator Observation
7 8 9 10 12 13 44 45 46
RELEASED OF RELEASE AMOUNT OF ACTIVITY 35  N/A  N/A  80
7 8 9 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) N/A
17 0 0 0 37 2 38
PERSONNEL INJURIES NUMBER DESCRIPTION 41
1 8 0 0 0 0 40
LOSS OF OR DAMAGE TO FACILITY 43  TYPE DESCRIPTION N/A  N/A
7 8 9 10 NRC USE ONLY
PUBLICITY   15SUED   DESCRIPTION (45)   N/A   68 69 80
8011040 45 Steven D. Chaplin PHONE: (717) 948-8461

# NARRATIVE REPORT

#### TMI-2

LER 80-046/01L-0 EVENT DATE - September 30, 1980

# I. EXPLANATION OF OCCURRENCE

-To perform maintenance on the breakers for busses 2-38 and 2-48, maintenance requested permission from the Shift Foreman to deenergize and remove these breakers. The Shift Foreman verified that no equipment was supplied from these busses, then gave his permission to deenergize and remove the breakers at 1030 on September 30, 1980. The Shift Foreman failed to realize at this time that these busses were required to be energized per Technical Specification 3.8.2.

On October 1, 1980, while performing a Tech. Spec. Surveillance, it was discovered that busses 2-38 and 2-48 were deenergized, contrary to the Tech. Spec. requirements. The busses had been deenergized greater than the 8 hours specified in the action statement to Technical Specification 3.8.2: therefore, this is a violation and is reportable under Section 6.9.1.8(b).

The busses were returned to service at 2000 hours on October 1, 1980.

#### II. CAUSE OF THE OCCURRENCE

The cause of this event was the Shift Foreman not realizing these busses were required by Technical Specifications, even though no equipment is presently powered from them.

# III. CIRCUMSTANCES SURROUNDING THE OCCURRENCE

At the time of the occurrence, the Unit 2 facility was in a long term cold shutdown state. The reactor decay heat was being removed via natural circulation to the "A" steam generator which is operating in a 'steaming' mode. Throughout the event there was no Loss of Natural Circulation heat removal in the RCS System.

## IV. CORRECTIVE ACTIONS TAKEN OR TO BE TAKEN

#### IMMEDIATE

The busses were returned to service as soon as possible after it was determined they were required to be energized.

#### \_LONG TERM

During the training cycle starting October 8, 1980, the operator requal program will include a class on the Recovery Mode Technical Specifications. One of the emphasis of this class will be to identify all the Tech. Spec. required equipment.

## V. COMPONENT FAILURE DATA