

APPENDIX A

NOTICE OF VIOLATION

Philadelphia Electric Company

Docket Nos. 50-277
50-278

Based on the results of an NRC inspection conducted on June 1-30, 1980, it appears that one of your activities was not conducted in full compliance with conditions of your NRC Facility License Nos. DPR-44 and DPR-56 as indicated below. This item is a deficiency.

Technical Specification 4.7.D.2 states in part... "Whenever an isolation valve listed in Table 3.7.1 is inoperable, the position of at least one other valve in each line having an inoperable valve shall be recorded daily."

Technical Specification Table 3.7.1 lists drywell purge inlet isolation valves as applicable valves. Surveillance Test 5.3 "Inoperable Isolation Valve Position Daily Log," Revision 3, dated August 14, 1979 references Technical Specification 4.7.D.2 and states in part, "The purpose of this log is to record the position of at least one other valve in each line having an inoperable isolation valve."

Contrary to the above, from May 24 to June 19, 1980, there was no valve position logged for three parallel lines, each of which was in-line with inoperable isolation valve AO-3520. The parallel lines for which no valve position was logged contained valves AO-3519, AO-3521A, and AO-3521B, respectively.

8011190244