

## NUCLE R REGULATORY COMMISSION REGION V

611 RYAN PLAZA DRIVE, SUITE 1000 ARLINGTON, TEXAS 76012

October 9, 1960

In Reply Refer To: RIV Docket No. 50-382/Rpt. 80-27

CH

Louisiana Power and Light Company
Attn: Mr. D L. Aswell
Vice President Power Production
142 Delaronde Street
New Orleans, Louisiana 70174

## Gentlemen:

This refers to the inspection conducted by Messrs. L. E. Martin and A. R. Johnson of our staff during the period September 23-26, 1980, of activities authorized by NRC Construction Permit No. CPPR-103 for Waterford Steam Electric Station, Unit No. 3, and to the discussion of our findings with Mr. L. L. Bass and other members of your staff at the conclusion of the inspection.

Areas examined during the inspection and our findings are discussed in the enclosed inspection report. Within these areas, the inspection consisted of selective examination of procedures and representative records, interviews with personnel, and observations by the inspectors.

Within the scope of the inspection, no items of noncompliance were identified.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room. If the report contains any information that you believe to be proprietary, it is necessary that you submit a written application to this office, within 20 days of the date of this letter, requesting that such information be withheld from public disclosure. The application must include a full statement of the reasons why it is claimed that the information is proprietary. The application should be prepared so that any proprietary information identified is contained in an enclosure to the application, since the application without the enclosure will also be placed in the Public Document Room. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.

Reactor Construction and

Engineering Support Branch

Enclosure:

IE Inspection Report No. 50-382/80-27