LICENSEE EVENT REPORT

CICENSEE CYCH.	
CONTROL BLOCK: PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)	
1 P A B V S 1 2 0 0 - 0 0 0 0 0 0 0	
CON'T SOURCE L 6 0 5 0 0 0 3 3 4 7 0 1 0 6 8 1 3 0 2 0 4 8 1 9	
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 During the performance of a surveillance test on the control room emergency supply	
fans, the air flow calculations indicated flow rates of 464 and 473 cfm.	
Technical specification 4.7.7.1 requires a system flow rate of 400 cfm ± 10%	
o during system operation. The health and safety of the general public and site	
personnel was not jeopardized.	
0 7	
0 8 1 80	
THE STE CAUSE CHUSE COMPONENT CODE SUBCODE SUBCODE	
S G 1 B 12 A 13 V A L V E X 14 N 15 G 16	
COOR TYPE	
NUMBER 21 22 23 24 26 27 28 29 30 31 32 COMPONENT ACTION FUTURE EFFECT SHUTDOWN HOURS 22 SUBMITTED FORM SUB. SUPPLIER MANUFACTURER ON PLANT METTOD HOURS 22 SUBMITTED FORM SUB. SUPPLIER	
TAXEN ACTION ON PLANT METHOD 2 2 9 9 9 26)
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)	
After an adjustment was made to the supply fans inlet damper, the flow rate was	
verified to be within acceptable limits. The surveillance test was completed	
satisfactorily at 1400 hours on January 6, 1981.	
113	
1 4	
FACILITY SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32	
115 6 (3) 10 10 10 10 10 10 10 10 10 10 10 10 10	
AMOUNT OF ACTIVITY (35) RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) N/A N/A	
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39	
17 0 0 0 0 0 0 X/A 80	
PERSONNEL INJURIES NUMBER DESCRIPTION (4)	
1 12 12 12 12 12 12 12 12 12 12 12 12 12	
1 9 Z 42 N/A	
PUBLICITY ISSUED DESCRIPTION 45	
2 0 N (44) S/A 68 69 80. 2 412-643-8525	0
NAME OF PREPARER W. S. Lacey PHONE	3
8102120171	-

Attachment To LER 81-04/03L Beaver Valley Power Station Duquesne Light Company Docket No. 50-334

No further information is available or needed to satisfy the reporting requirement.