LICENSEE EVENT REPORT

CONTROL BLOCK:
0 1 C O F S V 1 2 O O - O O O O O O O
CON'T O 1 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) During a maintenance shutdown, while performing routine surveillance testing of PCRV
[0]3 rupture disc, M-11702, its setpoint was found to be 826 psig. This is outside the
0 4 812 psig + 1% allowed by Fort St. Vrain Technical Specification LSSS 3.3.2(c) and is
[0]5 being reported per Fort St. Vrain Technical Specification AC 7.5.2(b)1. The reactor
0 6 had not been overpressurized during this surveillance interval and there was no ef-
[0]7 [fect on plant operation. No effect on public health or safety. Similar report
7 8 9 SYSTEM CAUSE CAUSE CAUSE COMP. VALVE
CODE CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCODE COMPONENT CODE CODE CODE CODE CODE CODE CODE CODE CODE C
SEQUENTIAL SCCURRENCE REPORT NO.
ACTION FUTURE ON PLANT METHOD HOURS 22 ATTACHMENT FORM SUB. PRIME COMP. COMPONENT MANUFACTURER E 18 Z 19 Z 20 Z 21 0 0 0 0 0 Y 23 N 24 N 25 C 0 2 6 2 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
Rupture disc movement setpoint out of tolerance due to drift of the Belleville washer
operating point. The threaded ring holding the Belleville washer was adjusted until
the rupture disc operated at the correct setpoint. No further corrective action is
13 anticipated or required.
1 4 6
FACILITY SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 1 5 G 28 0 0 0 0 29 N/A B 31 Scheduled Surveillance Test 2 3 3 10 12 13 44 45 46 46 80
ACTIVITY CONTENT RELEASED OF RELEASE 1 6 Z 33 Z 34 N/A N/A N/A N/A N/A N/A
PERSONNEL EXP. SURES NUMBER TYPE DESCRIPTION 39 1 7 0 0 0 37 Z 38 N/A
PERSONNEL INJURIES NUMBER DESCRIPTION 41
LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION 1 9 Z 42 N/A
PUBLICITY NAC USE ONLY SSUED DESCRIPTION (45) 80 10 2 10 7/9
7 8 9 10 NAME OF PREPARED SWIFT PHONE: (303) 785-2253