617-746-7900

NRC FQ (7-77) LICENSEE EVENT REPORT (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) CONTROL BLOCK: - 0 0 0 0 0 - 0 CON'T 3 7 1 10 10 12 18 10 8 11 0 1 0 18 10 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) On October 2, 1980 Boston Edison Co. Engineering Dept. notified Pilgrim Station 0 2 that an an lytical re-analysis of "B" RHR System indicated that the as built con-0 3 figurations of the "B" RHR System would not remain functional during a Safe Shut-0 4 down Earthquake. The Station was in a cold shutdown condition at this time. 0 7 SYSTEM CAUSE CAUSE VALVE COMPONENT CODE SUBCODE U P O R T (14 A (13) OCCURRENCE REVISION REPORT SEQUENTIAL CODE REPORT NO. NO. LER/RO 16 17 T 0 REPORT NUMBER COMPONENT NPRD-4 HOURS (22) FORM SUB MANUFACTURER 0 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27 This event resulted from a design error. The unit was maintained in a shutdown 1 0 condition and a seismic anchor was modified to allow the system to meet the safe shutdown earthquake criteria. The modification was completed and the unit started up on October 5, 1980. 1 4 METHOD OF DISCOVERY DESCRIPTION (32) OTHER STATUS N.A. Support Inspection C (31) CONTENT ACTIVITY LOCATION OF RELEASE (36) AMOUNT OF ACTIVITY (35) N.A. N.A. EXPOSURES DESCRIPTION (39) N.A. PERSONNEL INJURIES DESCRIPTION (41) N.A. LOSS OF OR DAMAGE TO FACILITY 43 0 (42) N.A. PUBLICITY NRC USE ONLY DESCRIPTION (45) 8010210724 0 44 N.A.

E. T. Graham