

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | 0 | H | D | B | S | 1 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
0 1 | L | 6 | 0 | 5 | 0 | - | 0 | 3 | 4 | 6 | 7 | 0 | 0 | 8 | 8 | 0 | 8 | 1 | 1 | 0 | 5 | 8 | 0 | 9
7 8 REPORT SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2 | (NP-33-80-92) On 10/8/80 at 0520 hours maintenance personnel discovered that the inner
0 3 | door of the containment personnel lock could not be latched. The door was declared
0 4 | inoperable, and the station entered the action statement of Technical Specification
0 5 | 3.6.1.3a. There was no danger to the health and safety of the public or station per-
0 6 | sonnel. Unit personnel were able to use the emergency air lock while repairs were be-
0 7 | ing conducted on the personnel lock. The other door of the personnel lock was
0 8 | operable.
7 8 9

0 9 | S | D | 11 | E | 12 | B | 13 | P | E | N | E | T | R | 14 | A | 15 | Z | 16
7 8 SYSTEM CODE 9 10 CAUSE CODE 11 12 CAUSE SUBCODE 13 14 COMPONENT CODE 15 16 VALVE SUBCODE 17 18
17 | LER/RO | 8 | 0 | 0 | 7 | 3 | 0 | 3 | L | 0 | 0
7 8 LER/RO REPORT NUMBER 21 22 EVENT YEAR 23 24 SEQUENTIAL REPORT NO. 25 26 OCCURRENCE CODE 27 28 REPORT TYPE 29 30 REVISION NO. 31 32
A | 18 | Z | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | Y | 23 | N | 24 | A | 25 | C | 3 | 1 | 0 | 26
7 8 ACTION TAKEN 33 34 FUTURE ACTION 35 36 EFFECT ON PLANT 37 38 SHUTDOWN METHOD 39 40 HOURS 41 42 ATTACHMENT SUBMITTED 43 44 NPRD-4 FORM SUB. 45 46 PRIME COMP. SUPPLIER 47 48 COMPONENT MANUFACTURER 49 50

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
1 0 | The cause was two broken CAMROL cam follower bearings in the control linkage of the
1 1 | door operating mechanism. The numerous operations of the personnel lock mechanism
1 2 | during this outage, coupled with rough operation contributed to the failure. Under
1 3 | MWO 80-3370 the broken cam follower bearings were replaced. ST 5061.04 was success-
1 4 | fully performed at 1610 hours on 10/10/80 and the personnel lock was declared operable.
7 8 9

1 5 | H | 28 | 0 | 0 | 0 | 29 | NA | 30 | A | 31 | Discovered during normal operation | 32
7 8 9 FACILITY STATUS 10 11 % POWER 12 13 OTHER STATUS 14 15 METHOD OF DISCOVERY 16 17 DISCOVERY DESCRIPTION 18 19

1 6 | Z | 33 | Z | 34 | NA | 35 | NA | 36
7 8 9 ACTIVITY CONTENT 10 11 RELEASED OF RELEASE 12 13 AMOUNT OF ACTIVITY 14 15 LOCATION OF RELEASE 16 17

1 7 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39
7 8 9 PERSONNEL EXPOSURES 10 11 NUMBER 12 13 TYPE 14 15 DESCRIPTION 16 17

1 8 | 0 | 0 | 0 | 40 | NA | 41
7 8 9 PERSONNEL INJURIES 10 11 NUMBER 12 13 DESCRIPTION 14 15

1 9 | Z | 42 | NA | 43
7 8 9 LOSS OF OR DAMAGE TO FACILITY 10 11 TYPE 12 13 DESCRIPTION 14 15

2 0 | N | 44 | NA | 45 | 8011110322 | 46
7 8 9 PUBLICITY 10 11 ISSUED 12 13 DESCRIPTION 14 15

GPO 917-926

TOLEDO EDISON COMPANY
DAVIS-BESSE NUCLEAR POWER STATION UNIT ONE
SUPPLEMENTAL INFORMATION FOR LER NP-33-80-92

DATE OF EVENT: October 8, 1980

FACILITY: Davis-Besse Unit 1

IDENTIFICATION OF OCCURRENCE: The inner door of the containment personnel lock could not be latched.

Conditions Prior to Occurrence: The unit was in Mode 3 with Power (MWT) = 0 and Load (Gross MWE) = 0.

Description of Occurrence: On October 8, 1980 at 0520 hours, a problem was discovered during normal operation of the personnel lock for transport of maintenance personnel and equipment. The inner door of the containment personnel lock could not be latched. The door was declared inoperable, and the station entered the action statement of Technical Specification 3.6.1.3a. The technical specification requires the air lock to be operable in Modes 1, 2, 3, and 4. The action statement requires the airlock to be restored to operable status within 24 hours or be in at least hot standby within the next six hours and in cold shutdown within the following 30 hours.

Designation of Apparent Cause of Occurrence: The cause of this problem was two broken CAMROL cam follower bearings in the control linkage of the door operating mechanism. The cam follower bearings are the link between the door roller chain drive shaft and the door operating interlock mechanism. The numerous operations of the personnel lock door mechanism during the outage coupled with rough operation contributed to the failure. Rough operation would result in severe shocking of the cam follower bearings which could cause failures such as were found in this occurrence. Rough is being defined as operating the mechanism too fast.

Analysis of Occurrence: There was no danger to the health and safety of the public or to station personnel. Unit personnel were able to use the emergency air lock while repairs were being conducted on the personnel lock. The other door of the personnel lock was operable.

Corrective Action: Under Maintenance Work Order 80-3370, the broken cam follower bearings were replaced and all the interlock mechanism cams were reset in their proper positions. ST 5061.05 was successfully performed at 1610 hours on October 10, 1980, and the personnel lock was declared operable.

Signs cautioning slow, careful operation of the personnel lock doors have been in place for more than a year and were still in place prior to this reported failure.

Failure Data: A previous similar occurrence was reported in Licensee Event Report NP-33-77-18.