

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

LICENSEE CODE: NYJAE1; LICENSE NUMBER: 00-0000-0000; LICENSE TYPE: 41111; CAT: 58

REPORT SOURCE: L; DOCKET NUMBER: 05000333; EVENT DATE: 1011180; REPORT DATE: 110780

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

During normal operation, while conducting surveillance, primary containment isolation valve 10-MOV-57 from RHR to Radwaste would not close when required to be operable by TS 3.7.D. The other valve in the same line was verified closed and 10-MOV-57 was manually closed. No significant hazard existed.

SYSTEM CODE: SA; CAUSE CODE: A; CAUSE SUBCODE: E; COMPONENT CODE: 777777; COMP. SUBCODE: 7; VALVE SUBCODE: 7; EVENT YEAR: 80; SEQUENTIAL REPORT NO.: 080; OCCURRENCE CODE: 03; REPORT TYPE: L; REVISION NO.: 0; ACTION TAKEN: XH; EFFECT ON PLANT: Z; SHUTDOWN METHOD: Z; HOURS: 0000; ATTACHMENT SUBMITTED: N; NPRO-4 FORM SUB.: N; PRIME COMP. SUPPLIER: Z; COMPONENT MANUFACTURER: Z999

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

Installation of scaffolding for modifications in the area caused the motor operator clutch to be disengaged. Removal of the scaffold of concern restored the valve to operable status. Event was discussed with construction personnel to prevent recurrence. No additional action is required.

FACILITY STATUS: E; % POWER: 100; OTHER STATUS: NA; METHOD OF DISCOVERY: R; DISCOVERY DESCRIPTION: Surveillance Test

ACTIVITY CONTENT: Z; AMOUNT OF ACTIVITY: NA; LOCATION OF RELEASE: NA

PERSONNEL EXPOSURES: NUMBER: 000; TYPE: Z; DESCRIPTION: NA

PERSONNEL INJURIES: NUMBER: 000; DESCRIPTION: NA

LOSS OF OR DAMAGE TO FACILITY: TYPE: Z; DESCRIPTION: NA

PUBLICITY ISSUED: N; DESCRIPTION: NA

8011120549 W. Verne Childs (315) 342-3840 X207