

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | C | O | F | S | V | I | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 2 | 0 | 4 | \_\_\_\_\_ | 5  
7 8 9 14 15 25 26 30 57 CAT 58  
LICENSEE CODE LICENSE NUMBER LICENSE TYPE

CON'T  
0 1 | R | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 6 | 7 | 7 | 1 | 1 | 2 | 1 | 8 | 0 | 8 | 1 | 2 | 1 | 9 | 8 | 0 | 9  
7 8 60 61 58 69 74 75 80  
REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During normal operation, in order to control circulating water system foaming caused by  
0 3 | biocide treatment, anti-foam agent was added to the circulating water system.  
0 4 | Discharge of effluent from the site via the Goosequill Ditch exceeded the LCO NR 1.1  
0 5 | allowable concentration of anti-foam agent for about three hours. Reportable per  
0 6 | AC 7.5.2(b)2. There was no effect on the health or safety of the public. No ac-  
0 7 | companying occurrence. No similar reports.  
0 8 | \_\_\_\_\_  
7 8 9

0 9 | H | F | 11 | X | 12 | Z | 13 | Z | Z | Z | Z | Z | Z | 14 | Z | 15 | Z | 16 |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20  
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE  
17 | L | R | 18 | 0 | 19 | 8 | 20 | 0 | 21 | 0 | 22 | 7 | 23 | 3 | 24 | 0 | 25 | 3 | 26 | L | 27 | 0 | 28 | 3 | 29 | L | 30 | 0 | 31 | 0 | 32 | 0 |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NRPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  
Z 18 X 19 Z 20 Z 21 0 0 0 0 0 Y 23 N 24 Z 25 Z 19 19 19 26  
13 34 35 36 37 40 41 42 43 44 47  
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The cause of this event was the fact that the blowdown flow rate, at the concentra-  
1 1 | tion of anti-foam agent required to suppress foaming, gave a concentration in the  
1 2 | Goosequill Ditch above the limit allowed by LCO NR 1.1. No corrective action was  
1 3 | taken at the time of the event. A procedure will be implemented to prevent  
1 4 | reoccurrence.  
7 8 9

1 5 | E | 28 | 0 | 6 | 9 | 29 | N/A | 30 | B | 31 | Found during calculation after event | 32  
7 8 9 10 11 12 13 44 45 46 80  
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

1 6 | Z | 33 | Z | 34 | N/A | 35 | N/A | 36  
7 8 9 10 11 44 45 80  
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

1 7 | 0 | 0 | 0 | 37 | Z | 38 | N/A | 39  
7 8 9 10 11 12 13 80  
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

1 8 | 0 | 0 | 0 | 40 | N/A | 41  
7 8 9 10 11 12 80  
PERSONNEL INJURIES NUMBER DESCRIPTION

1 9 | Z | 42 | N/A | 43  
7 8 9 10 80  
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

2 0 | N | 44 | N/A | 45  
7 8 9 10 80  
PUBLICITY ISSUED DESCRIPTION