



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION I  
631 PARK AVENUE  
KING OF PRUSSIA, PENNSYLVANIA 19406

Docket Nos. 50-352  
50-353

DEC 17 1980

Philadelphia Electric Company  
ATTN: Mr. John S. Kemper  
Vice President  
Engineering and Research  
2301 Market Street  
Philadelphia, Pennsylvania 19101

Gentlemen:

The enclosed IE Information Notice No. 80-45, "Potential Failure of BWR Backup Manual Scram Capability," is forwarded to you for information. No written response is required. If you desire additional information regarding this matter, please contact this office.

Sincerely,

*Gary Snyder*  
for Soyce H. Grier  
Director

Enclosures:

1. IE Information Notice No. 80-45
2. List of Recently Issued IE Information Notices

CONTACT: D. L. Capton  
(215-337-5266)

cc w/encls:

V. S. Boyer, Senior Vice President, Nuclear Power

Q 8101060123

SSINS No.: 6835  
Accession No.:  
801216002  
IN 80-45

UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
OFFICE OF INSPECTION AND ENFORCEMENT  
WASHINGTON, D.C. 20555

December 17, 1980

IE Information Notice No. 80-45: POTENTIAL FAILURE OF BWR BACKUP MANUAL SCRAM  
CAPABILITY

The primary purpose of this Notice is to advise BWR licensees that a mechanism exists which could defeat one of the backup manual scram (reactor trip) features normally available to the reactor operator. In some GE-designed reactors, placing the Mode Selector Switch (MSS) in "Shutdown" should actuate a scram. This feature is used at some facilities as part of a normal reactor shutdown, and for certain plant situations the Technical Specifications require placing the MSS in the "Shutdown" position as a means of attaining immediate shutdown. As described below, a situation may arise that blocks this scram.

The Pilgrim Nuclear Power Station has reported that following the loss of power from a vital M-G set and manual transfer to the alternate power source, the annunciator "Shutdown Scram Reset Permissive" came on and stayed on. Since such an annunciator may not be provided for all BWRs, some facilities may not be able to detect this condition. Subsequent investigation revealed that when one RPS bus power supply is lost and the MSS is in the "Run" mode, relay K-17 is immediately deenergized and after two seconds one of two series bypass contacts in the MSS scram circuit is closed. Upon restoration of RPS bus power, it is possible for relay K-16 to be energized before K-17 (i.e., a relay race). If this occurs, the following conditions will result: (1) the normally open K-16 contact in the MSS scram bypass circuit is closed, thereby bypassing the MSS in "Shutdown" Scram; and (2) relay K-17 will be kept deenergized.

Even with this condition (i.e., the bypass circuit made up and the MSS in "Run") a Scram should occur if the MSS is turned in a deliberate manner to "Shutdown" with a pause in either the "Startup" or "Refuel" mode; however, if the MSS is turned to "Shutdown" quickly such that relay K-17 is not energized, a Scram due to MSS manipulation may not occur.

We understand that General Electric has been informed of this potential for bypassing the MSS and that General Electric is preparing a Service Information Letter (SIL) containing recommendations for preventing such bypassing.

This Information Notice is provided as an early notification of a possibly significant matter that is still under review by the NRC staff. Recipients should review the information for possible applicability to their facilities. No specific action or response is requested at this time; however, if NRC evaluations so indicate, further licensee actions may be requested or required.

If you have any question regarding this matter, please contact the director of the appropriate NRC Regional Office.

IE Information Notice No. 80-45  
December 17, 1980

Enclosure 2

RECENTLY ISSUED  
IE INFORMATION NOTICES

Information Notice No.	Subject	Date Issued	Issued to
80-44	Actuation of ECCS in the Recirculation Mode While in Hot Shutdown	12/14/80	All holders of a PWR power reactor OL or CP
80-43	Failures of the Continuous Water Level Monitor for the Scram Discharge Volume at Dresden Unit No. 2	12/5/80	All holders of a BWR power reactor OL or CP
80-29 Supplement No. 1	Broken Studs on Terry Turbine Steam Inlet Flange	11/26/80	All holders of a power reactor OL or CP
80-42	Effects of Radiation on Hydraulic Snubber Fluid	11/24/80	All holders of a power reactor OL or CP
80-41	Failure of Swing Check Valve in the Decay Heat Removal System at Davis-Besse Unit No. 1	11/10/80	All holders of a power reactor OL or CP
80-40	Excessive Nitrogen Supply Pressure Activates Safety-Relief Valve Operation to Cause Reactor Depressurization	11/6/80	All holders of a power reactor OL or CP
80-39	Malfunctions of Solenoid Valves Manufactured by Valcor Engineering Corporation	10/31/80	All holders of a power reactor OL or CP
80-38	Cracking in Charging Pump Casing Cladding	10/30/80	All holders of a PWR power reactor OL or CP
80-37	Containment Cooler Leaks and Reactor Cavity Flooding at Indian Point Unit 2	10/24/80	All holders of a power reactor OL or CP