



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION I
631 PARK AVENUE
KING OF PRUSSIA, PENNSYLVANIA 19406

12
DEC 31 AM 8 54
REGISTRATION
SERVICES

Docket Nos. 50-354
50-355

DEC 17 1980

Public Service Electric and Gas Company
ATTN. Mr. T. J. Martin
Vice President
Engineering and Construction
80 Park Plaza - 17C
Newark, New Jersey 07101

Gentlemen:

The enclosed IE Information Notice No. 80-45, "Potential Failure of BWR Backup Manual Scram Capability," is forwarded to you for information. No written response is required. If you desire additional information regarding this matter, please contact this office.

Sincerely,

Boyce H. Gryer
for Boyce H. Gryer
Director

Enclosures:

1. IE Information Notice No. 80-45
2. List of Recently Issued IE Information Notices

CONTACT: D. L. Capton
(215-337-5266)

cc w/encls:
J. Boettger, General Manager, Corporate QA

8101000 145

UNITED STATES
NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT
WASHINGTON, D.C. 20555

December 17, 1980

IE Information Notice No. 80-45: POTENTIAL FAILURE OF BWR BACKUP MANUAL SCRAM
CAPABILITY

The primary purpose of this Notice is to advise BWR licensees that a mechanism exists which could defeat one of the backup manual scram (reactor trip) features normally available to the reactor operator. In some GE-designed reactors, placing the Mode Selector Switch (MSS) in "Shutdown" should actuate a scram. This feature is used at some facilities as part of a normal reactor shutdown, and for certain plant situations the Technical Specifications require placing the MSS in the "Shutdown" position as a means of attaining immediate shutdown. As described below, a situation may arise that blocks this scram.

The Pilgrim Nuclear Power Station has reported that following the loss of power from a vital M-G set and manual transfer to the alternate power source, the annunciator "Shutdown Scram Reset Permissive" came on and stayed on. Since such an annunciator may not be provided for all BWRs, some facilities may not be able to detect this condition. Subsequent investigation revealed that when one RPS bus power supply is lost and the MSS is in the "Run" mode, relay K-17 is immediately deenergized and after two seconds one of two series bypass contacts in the MSS scram circuit is closed. Upon restoration of RPS bus power, it is possible for relay K-16 to be energized before K-17 (i.e., a relay race). If this occurs, the following conditions will result: (1) the normally open K-16 contact in the MSS scram bypass circuit is closed, thereby bypassing the MSS in "Shutdown" Scram; and (2) relay K-17 will be kept deenergized.

Even with this condition (i.e., the bypass circuit made up and the MSS in "Run") a Scram should occur if the MSS is turned in a deliberate manner to "Shutdown" with a pause in either the "Startup" or "Refuel" mode; however, if the MSS is turned to "Shutdown" quickly such that relay K-17 is not energized, a Scram due to MSS manipulation may not occur.

We understand that General Electric has been informed of this potential for bypassing the MSS and that General Electric is preparing a Service Information Letter (SIL) containing recommendations for preventing such bypassing.

This Information Notice is provided as an early notification of a possibly significant matter that is still under review by the NRC staff. Recipients should review the information for possible applicability to their facilities. No specific action or response is requested at this time; however, if NRC evaluations so indicate, further licensee actions may be requested or required.

If you have any question regarding this matter, please contact the director of the appropriate NRC Regional Office.

RECENTLY ISSUED
IE INFORMATION NOTICES

| Information Notice No. | Subject | Date Issued | Issued to |
|------------------------|--|-------------|---|
| 80-44 | Actuation of ECCS in the Recirculation Mode While in Hot Shutdown | 12/14/80 | All holders of a PWR power reactor OL or CP |
| 80-43 | Failures of the Continuous Water Level Monitor for the Scram Discharge Volume at Dresden Unit No. 2 | 12/5/80 | All holders of a BWR power reactor OL or CP |
| 80-29 Supplement No. 1 | Broken Studs on Terry Turbine Steam Inlet Flange | 11/26/80 | All holders of a power reactor OL or CP |
| 80-42 | Effects of Radiation on Hydraulic Snubber Fluid | 11/24/80 | All holders of a power reactor OL or CP |
| 80-41 | Failure of Swing Check Valve in the Decay Heat Removal System at Davis-Besse Unit No. 1 | 11/10/80 | All holders of a power reactor OL or CP |
| 80-40 | Excessive Nitrogen Supply Pressure Activates Safety-Relief Valve Operation to Cause Reactor Depressurization | 11/6/80 | All holders of a power reactor OL or CP |
| 80-39 | Malfunctions of Solenoid Valves Manufactured by Valcor Engineering Corporation | 10/31/80 | All holders of a power reactor OL or CP |
| 80-38 | Cracking in Charging Pump Casing Cladding | 10/30/80 | All holders of a PWR power reactor OL or CP |
| 80-37 | Containment Cooler Leaks and Reactor Cavity Flooding at Indian Point Unit 2 | 10/24/80 | All holders of a power reactor OL or CP |