

UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

November 14, 1980

Those on Attached Address Listing:

Enclosed is IE Bulletin No. 80-23 which requires action by you with regard to your nuclear power facility.

In order to assist the NRC in evaluating the value/impact of each bulletin on licensees, it would be helpful if you would provide us an estimate of the manpower expended in conduct of the review and preparation of the report(s) required by the bulletin. Please estimate separately the manpower associated with corrective actions necessary following identification of problems through the bulletin.

Should you have any questions regarding this bulletin or the actions required by you, please contact this office.

Sincerely,

James G. Keppler

Director

Enclosure: IE Bulletin

No. 80-23

cc w/encl:
Mr. D. W. Kane,
Sargent & Lundy
Mr. Gary N. Wright, Chief
Division of Nuclear Safety
Reproduction Unit NRC 20b

RIII's CORPORATE ADDRESSES FOR OPERATING LICENSEES AND CONSTRUCTION PERMIT HOLDERS (BWR's and PWR's)

W

Docket No. 50-341

The Detroit Edison Company ATTN: Mr. Edward Hines, Assistant Vice President and Manager Quality Assurance

2000 Second Avenue Detroit, MI 48226

cc w/encl:
Central Files
Director, NRR/DPM
Director, NRR/DOR
AEOD
Resident Inspector, RIII
PDR
Local PDR
NSIC
TIC
Ronald Callen, Michigan Public
Service Commission
Eugene B. Thomas, Jr.,
Attorney

Docket No. 50-461 Docket No. 50-462

Illinois Power Company
ATTN: Mr. W. C. Gerstner
Executive Vice President
500 South 27th Street
Decatur, IL 62525

SSINS No.: 6820 Accession No.: 8008220257 IEB 80-23

UNITED STATES NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT WASHINGTON, D.C. 20555

November 14, 1980

IE Bulletin No. 80-23: FAILURES OF SOLENOID VALVES MANUFACTURED BY VALCOR

ENGINEERING CORPORATION

Introduction:

Valcor Engineering Corporation (Valcor) has submitted 10 CFR Part 21 Reports addressing failures of Valcor solenoid valves used at nuclear power facilities. These failures have occurred at nuclear facilities owned by Duke Power Company and Omaha Public Power District, and are purportedly limited to solenoid valves having part numbers (P/N's) V70900-21-1 and V70900-21-3.

The information presented in this bulletin is intended to shed light on the defective solenoid valves so that appropriate actions can be taken to circumvent the degradation of any safety-related system using such solenoid valves.

DISCUSSION:

The specific Valcor solenoid valves addressed herein were purportedly designed as Class IE components. However, in light of the reported failures, it appears that neither the design nor the qualification tests were adequate for Class IE service. Valcor has attributed the failures to a latent defect in the magnet wire. Valcor believes that this defect manifests itself when the solenoid valves are continuously energized at elevated temperatures by an incompatability between the magnet wire's polyvinyl varnish coating and the wire's polyimide insulation which causes a dielectric breakdown leading to turn-toturn shorts within the coil.

Valcor states that the above incompatability is limited to solenoid valves having P/N's V70900-21-1 and V70900-21-3, and that all customers affected by the aforementioned defect have been notified. A listing of Valcor customers so notified and valves purchased follows.

CUSTOMER	P.O. NO.	VALVE P/N	QTY
Anchor-Darling	P-827	V70900-21-1,-3	24
Anchor-Darling	N663	V70900-21-1	6
Cesare Bonetti (Italy)	1535/79	V70900-21-3	10
Duke Power Company	E95188-11	V70900-21-3	100
Duke (Mill Power)	C-97733	V70900-21-1,-3	335
Duke Power Company	E97822-11	V70900-21-3	70
Ralph Hiller	HA-18		
Mill Power Omaha Public Power Dist. Stone and Webster Copes Vulcan	E5246: 43472 L000 i 911,5!	DUPLICATE DOCUMENT Entire document pre-	viously
		entered into system	under:
	ANO 800822025		257
		No. of pages:	