



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

TERA

December 18, 1980


Gentlemen:

Enclosed is IE Supplement No. 4 to Bulletin No. 80-17 which requires action by you with regard to your power reactor facility(ies) with an operating license.

In order to assist the NRC in evaluating the value/impact of each Bulletin on licensees, it would be helpful if you would provide an estimate of the manpower expended in conduct of the review and preparation of the report(s) required by the Bulletin. Please estimate separately the manpower associated with corrective actions necessary following identification of problems through the Bulletin.

Should you have any questions regarding this Bulletin or the actions required by you, please contact this office.

Sincerely,


James G. Keppler
Director

Enclosure: IE Supplement No. 4
to Bulletin No. 80-17

8101150240

Q

Docket Nos. 50-10, 50-237,
50-249; 50-254, 50-265

Commonwealth Edison Company
ATTN: Mr. Cordell Reed
Vice President
Post Office Box 767
Chicago, IL 60690

cc w/encl:

J. S. Able, Director
of Nuclear Licensing

D. T. Scott, Station
Superintendent

N. Kalivianakis, Plant
Superintendent

Central Files

AD/Licensing

AD/Operating Reactors

AEOD

Resident Inspectors, RIII

PDR

Local PDR

✓ NSIC

TIC

Dean Hansell, Office of

Assistant Attorney General

UNITED STATES
NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT
WASHINGTON, D.C. 20555

December 18, 1980

IE Supplement 4 to Bulletin No. 80-17: FAILURE OF CONTROL RODS TO INSERT
DURING A SCRAM AT A BWR

NRC staff evaluation of failures of the continuous monitoring system (CMS) for the scram discharge volume (SDV) at an operating BWR has identified the need for licensee actions in addition to those requested by IEB 80-17 and Supplements 1-3. The purpose of these actions is to provide assurance that the CMS has been tested to demonstrate operability as installed, remains operable during plant operation, and is periodically surveillance tested to demonstrate continued operability.

The occurrence of CMS failures at Dresden Nuclear Power Station was discussed in IE Information Notice 80-43, which was issued on December 5, 1980 to those operating BWR's with CMS recently installed. Subsequently, investigation into the cause of the failure to receive the alarm with the SDV essentially full revealed several items which required correction, including:

1. Excess portions of transducer cable were placed in physical positions which would increase external noise sensitivity.
2. The UT transducers were not placed in a physical position to optimize system sensitivity.
3. A certain amount of "cross-talk" was occurring between redundant transducers located a few feet apart on the same run of 4" pipe.

Station and vendor personnel shortened and rerouted transducer cables to improve noise rejection. Vendor specialists optimized transducer placement and synchronized both transducers to the same ultrasonic instrument internal clock to minimize cross-talk and improve signal to noise characteristics. Following these actions the CMS appeared to function properly.

Further difficulties were encountered when apparently minor quantities of water leaked into the SDV as a result of control rod drive scram valve maintenance activities and minor scram outlet valve leakage. It appears that the transducers are located on a section of SDV piping which forms a local low point. Accordingly, small amounts of water can accumulate to a depth which triggers the high level alarm (at 1-1/4") before the water drains to the instrument volume. The licensee in conjunction with the NSSS vendor, performed a unit specific analysis for a conservative high level point to 2-1/2". The system now appears to function properly. An alarm time delay was also installed to

DUPLICATE DOCUMENT

Entire document previously
entered into system under:

ANO 8006190074

No. of pages: 4