11.11 LICENSEE EVENT REPORT 2 CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REGUIRED INFORMATION) 0 0 0 0 0 0 - 0 0 3 4 LICENSE NUMBER NP 0 CON'T 17 () 1 12 10 9 8 10 0 110 7 8 EVENT DATE 74 75 REPORT DATE REPOHT 0 1 6 SOURCE DOCKET NUMBER EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) in mode 5, an evaluation of start-up calorimetric data identified that the With Unit 0 2 high steamflow safeguard program and the steam/feedwater flow mismatch bistable set-0 3 tings had been less conservative than the allowable values specified by Technical 0 4 Specifications 3.3.2.1 (Table 3.3-4) and 2.2.1 (Table 2.2-1). There was no effect on 0 5 public health or safety. No previous occurrences. 0 6 0 7 COMP SYSTEM CAUSE CAUSE SUBCODE CODE CODE SUBCODE COMPONENT CODE SUBCODE T IS B 1(13) N IA A 019 OCCURRENCE REVISION SEQUENTIAL REFOR LODE EVENT YEAR REPORT NO. TYPE NO LER/RO 81 01 11919 0 3 01 HEPORT NUMBER 12 PRIME COMP COMPONENT FUTURE ACTION EFFECT METHOD SUBMITTED NPF D.4 HOURS (22) FORKISUS B 0 8 0 101010 N 24 L 25 1Y 18) E Z (20) Z (21) 10 (23) 26 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27 The actual differential pressure produced at the steam flow transmitter for 75% rated 1 0 steam low was less than expected. The calorimetric data was used to recalibrate the high steam flow program and the steam/feedwater flow mismatch bistable setpoints. A final calibration of the steam flow loops will be performed using data obtained from 1 3 100% power testing. 1 4 20 9 METHOD OF FALILITY STATU (30) OTHER STATUS DISCOVERY DESCRIPTION " POWER 0 0 10 Review of calorimetric data 5 NA (31 ACTIVITY 0 80 13 CONTENT AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36) OF RELEASE RELEASED 12 (34) NA Z (33) NA 6 60 PERSONNEL EXPOSURES DESCRIPTION (30) NUMBER TYPE (38) NA 80 13 PERSONNEL INJURIES DESCRIPTION (41) NUMBER 0 0 (40) NA 01 1 8 80 LOSS OF OR DAMAGE TO FACILITY (43) DESCRIPTION 19 (42) NA 20 PURLICITY NAC USE ONLY 1ED (14) DESCRIPTION (45 2 0 8101160483 ·* ·· 4 842-8261 Phone (615)

Tennessee Valley Authority Sequoyah Nuclear Plant

LER SUPPLEMENTAL INFORMATION

SQR0-50-327/80199 Technical Specification Involved: 2.2.1 and 3.3.2.1

Reported Under Technical Specification: 6.9.1.12.a

Date of Occurrence: 12/09/80 Time of Occurrence: 1430 CST

Identification and Description of Occurrence:

An evaluation of start-up calorimetric data identified that the high steamflow safeguard program and the steam/feedwater flow mismatch bistable settings had been less conservative than the allowable values specified by the Technical Specifications.

Conditions Prior to Occurrence:

Unit in mode 5 at time of discovery.

Apparent Cause of Occurrence:

The actual differential pressure produced at the flow transmitter for 75% rated steam flow was less than expected.

Analysis of Occurrence:

The differential pressure error at the flow transmitter resulted in an actual high steam flow setpoint of 121.5% rated steam flow and a mismatch setpoint of 48.3% rated steam flow at full load. Allowable technical specification values are 111.5% and 42.5% respectively.

Corrective Action:

The calorimetric data was used to recalibrate the high steam flow and steam/ feedwater flow mismatch setpoints to compensate for the transmitter inaccuracy. A final calibration of the steam flow loops will be performed using data to be obtained during 100% power testing.