



LER ATTACHMENT - RO # 2-80-109

Facility: BSEP Unit No. 2

Event Date: 12-15-80

An inspection of the other CAC monitors on both units has revealed that high moisture in the sample lines to these monitors is presently affecting the sensitivity of the monitor's photohelic units. In order to maintain reliable operation of the CAC monitors, they are presently checked for proper operation on a daily basis and replacement photohelic units are on order should any of the monitors experience photohelic failures in the future. Due to a history of similar problems involving these monitors they will be replaced with others of a more reliable design during the next scheduled refueling outage.