

LER SUPPLEMENTAL INFORMATION

BFRO-50- 259 / 8092 Technical Specification Involved 3.7.B.3

Reported Under Technical Specification 6.7.2.b(2)

Date of Occurrence 12/30/80 Time of Occurrence 2330 Unit 1

Identification and Description of Occurrence:

Operations personnel observed that "C" SBTG train relative humidity heaters did not function properly. This report is applicable to unit 2 and 3 also.

Conditions Prior to Occurrence:

Unit 1 @ 80% power.

Unit 2 @ 100% power

Unit 3 Refueling

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

SI 4.7.B.3 was performed on trains "A" and "B".

Apparent Cause of Occurrence:

Open switch circuit.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity, no damage to plant or equipment and no resulting significant chain of events.

Corrective Action:

Repaired switch circuit, performed SI 4.7.B-3 to prove operability of "C" train and returned to service.

Failure Data:

None

*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

*Revision: 