LICENSEE EVENT REPORT

LICENSEE EVENT REPORT
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 1 L Q A D 2 2 0 0 0 - 0 0 0 - 0 0 0 3 4 1 1 1 1 1 4 5 5 15 LICENSE NUMBER 25 26 LICENSE TYPE JO 57 CAT 58
CON'T O 1 8 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) After pumping the Drywell Equipment Drain Sump, outboard isolation valve A0-2-2001-16
o 3 required approximately 15 minutes to give closed indication. Technical
Specifications require a closure time of less than or equal to 20 seconds. The
redundant isolation valve A0-2-2001-15 was placed in the closed position.
Isolation capability of the Equipment Drain Sump was always intact.
07
7 8 9
SYSTEM CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCOD
TO REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32
ACTION FUTURE ON PLANT SHUTDOWN HOURS 22 ATTACHMENT SUBMITTED FORM SUB. PRIME GOMP SUPPLIER MANUFACTURER LE 18 Z 19 Z 20 Z 21 0 0 0 0 0 V Y 23 Y 24 N 25 C 6 6 5 26 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
The position indication limit switch and the length of valve stem travel were out of
1 adjustment. The stroke of the valve stem was lengthened, the packing was adjusted,
and the limit switches were adjusted. The A0-2-2001-16 valve was cycled three
times satisfactorily with a closure time of 4.2 seconds.
7 8 9
FACILITY STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 1 5 E 28 0 7 9 29 NA
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA LOCATION OF RELEASE 36 NA
PERSONNEL EXPOSURES NUMBER TYPE 0 0 0 0 37 Z 38 NA 7 8 9 11 12 13
PERSONNEL INJURIES NUMBER DESCRIPTION 41 NA
LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION NA NA
PUBLICITY ISSUED DESCRIPTION 45 NA NA NA NA NA NA NA NA NA N
8102020445 R C Tubbs PHONE: 309-654-2241, ext 174

I. LER NUMBER: _ER/RO 80-35/03L

11. LICENSEE NAME: Commonwealth Edison Company

Quad-Cities Nuclear Power Station

III. FACILITY NAME: Unit Two

IV. DOCKET NUMBER: 050-265

V. EVENT DESCRIPTION:

On December 28, 1980, at 1600, the Drywell Equipment Drain Sump was undergoing routine pump down. Upon conclusion of the evolution it was noted that the outboard isolation valve, A0-2001-16, had an excessive closure time of approximately 15 minutes. Technical Specification Table 3.7-1, requires that the closure time shall be less than or equal to 20 seconds. Attempts were made to open the valve with no apparent success. Personnel were sent to the location of the valve and another attempt was made. It was reported that there was not enough travel to actuate the limit switches. There are no recorded instances of this valve failing in this mode.

VI. PROBABLE CONSEQUENCES OF THE OCCURRENCE:

Per Technical Specification 3.7.D.2., continued reactor operation is allowed, provided that at least one valve in that line is closed. The redundant outboard isolation valve, A0-2-2001-15, was closed. At all times the reactor was operated within the requirements of the Technical Specification.

Impact upon the system was also minimal. The recirculation through the Drywell Equipment Drain Sump coolers was in no way impaired, and the sump had been pumped down immediately prior to the occurrence. Coolant leakages were within Technical Specification limits.

VII. CAUSE:

Failure of the valve to close within the required time was due to a limit switch and the length of valve stem travel that were out of adjustment. The valve is a 3 inch 150 Cast Steel Gate valve manufactured by Crane Company.

VIII. CORRECTIVE ACTION:

The Drywell Equipment Drain Sump pumps were out of service during the repair and the following items were performed. The stroke of the valve stem was lengthened, packing was adjusted, and both the open and shut limit switches were reset. At 2200 the valve AO-2-2001-16 was cycled three times satisfactorily with a closure time of 4.2 seconds.