

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | C O F S V I | 2 | 0 0 0 - 0 0 0 0 0 0 - 0 0 0 | 3 | 4 1 1 2 0 | 4 | _____ | 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T
0 1 | REPORT SOURCE | L | 6 | 0 5 0 0 0 0 2 6 7 | 7 | 0 1 2 7 8 1 | 8 | 0 2 2 6 8 1 | 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2 | During test, six of twelve "Steam Pipe Rupture (Pipe Cavity)" ultrasonic noise chan-
0 3 | nels were identified as being inoperable. Surveillance Test SR 5.4.1.2.1j-R revealed
0 4 | that the six channels had unacceptably low response to a known noise source. Degraded
0 5 | mode of LCO 4.4.1, Table 4.4-2. Reportable per Fort St. Vrain Technical Specification
0 6 | AC 7.5.2(b)2. No affect on public health or safety. No accompanying occurrence.
0 7 | Redundant systems available and operable. Similar event reported as RO 80-48.
0 8 | _____
7 8 9

0 9 | SYSTEM CODE | I B | 11 | CAUSE CODE | X | 12 | CAUSE SUBCODE | Z | 13 | COMPONENT CODE | I N S T R U | 14 | COMP. SUBCODE | E | 15 | VALVE SUBCODE | Z | 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.

17 | LER RO REPORT NUMBER | 8 1 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | 32 |
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
0 18 | Z | 19 | Z | 20 | Z | 21 | 0 0 0 0 | 22 | Y | 23 | N | 24 | N | 25 | G 2 9 0 | 26
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Microphone and/or transmitter gain had been reduced to prevent spurious trips. The
1 1 | gain of the microphones and transmitters were returned to acceptable levels, and the
1 2 | Surveillance Test satisfactorily completed. Reduction of gain will not be used to pre-
1 3 | vent spurious trips in the future. Twice yearly calibration checks will be performed
1 4 | to detect system drift. System evaluation has been requested from Nuclear Project
7 8 9 Department. _____
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)
1 5 | G | 29 | 0 0 0 | 29 | N/A | 30 | B | 31 | Scheduled Surveillance Test | 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)
1 6 | Z | 33 | Z | 34 | N/A | 35 | N/A | 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
1 7 | 0 0 0 | 37 | Z | 38 | N/A | 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

PERSONNEL INJURIES NUMBER DESCRIPTION (41)
1 8 | 0 0 0 | 40 | N/A | 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43)
1 9 | Z | 42 | N/A | 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

PUBLICITY ISSUED DESCRIPTION (45)
2 0 | N | 44 | N/A | 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40