LICENSEE EVENT REPORT

0	CONTROL BLOCK: PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION
0 1	V T V 1 S 1 2 0 0 - 0 0 0 0 - 0 0
O I	SOURCE SO 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
0 2	During normal operation while performing surveillance testing per 0.P. 4342 the
0 3	ATWS/RPT high pressure trip points from PT-2-3-56Bm, 56Cm, & 56Dm were found to trip
0 4	1 to 2 psi higher than allowed in Tech. Spec. Table 3.2.1. There were no signifi-
0 5	cant effects as a result of this event, nor were there any adverse affects to public
0 6	health or safety. This event is not repetative.
0 7	
08	9 SYSTEM CAUSE CAUSE COMP. VALVE
0 9	CODE SUBCODE S
	TREPORT SEQUENTIAL REPORT NO. SEQUENTIAL REPORT NO. SEQUENTIAL REPORT NO. SUBMITTED SEQUENTIAL REPORT NO. SUBMITTED SUBMIT
	CAUSE DESCRIPTION AND CORFECTIVE ACTIONS (27)
1 0	The instruments involved are all master trip units associated with a Rosemount model
1 1	510 DU Trip/Calibration System which was installed during the past refueling outage.
1 2	The cause for the out-of-specification condition is instrument drift. The instru-
1 3	ments were immediately adjusted to the required setpoints.
1 4 7 8	9 80
1 5	FACILITY SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 NA B 31 Surveillance Testing
	ACTIVITY CONTENT DELEASED OF RELEASE AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36) NA N
1 7 7 8	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 NA 9 11 12 13
1 8	PERSONNE INJURIES NUMBER DESCRIPTION 41 O O O O O O O O
7 8	SO LOSS OF OR DAMAGE TO FACILITY 43
1 3	Z 42 NA NA SO SECULAR CALLY
2 0	NA DESCRIPTION (45)
7 a	NAME OF PREPARER Warren P. Murphy PHONE (802) 257-7711