stor

## DUKE POWER COMPANY

POWER BUILDING 422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR. VICE PRESIDENT STEAM PRODUCTION September 4, 1980

TELEPHONE: AREA 704 373-4083

Mr. Harold R. Denton, Director Office of Nuclear Reactor Regulation U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Attention: Mr. B. J. Youngblood, Chief Licensing Projects Branch No. 1

Re: McGuire Nuclear Station Docket No. 50-369

Subject: Low Pressure Turbine Disc Integrity

Dear Mr. Denton:

Please find attached information on the low pressure turbine disc integrity as requested by a letter dated August 27, 1980 from Mr. Robert L. Tedesco of your Staff. Please advise us if you have any questions.

Very truly yours,

William O. Parker, Jr.

W. Tanks

LJB:scs Attachment

POS SEVELTO:

PROPLES

YORK

S P.M.

## MCGUIRE NUCLEAR STATION UNIT 1

Response to NRC Telecopy of August 21, 1980 Low Pressure Turbine Disc Integrity

I.

A. Westinghouse turbine - 1800 RPM Tandem Compound, Sextuple Flow

Serial Numbers: Unit 1

No. 1 LP 23-A-4352 No. 2 LP 23-A-4353 No. 3 LP 23-A-4354

- B. Enclosure 1, attached, is a computer printout of the requested data. This information is proprietary and is accompanied by an affidavit signed by Mr. R. W. Gaul of Westinghouse which requests that this information be withheld from public disclosure. Enclosure 2 is a non-proprietary version of the information.
- II. Preservice inspection has not been performed on any of the McGuire LP turbine rotors.
- III. Westinghouse has indicated that LP turbine discs 1 thru 4 have sufficient moisture in the hub to cause a propensity for stress corrosion cracking.
- IV. Critical structures exposed to turbine missiles were designed to withstand their impact. To minimize exposed structures, a peninsular turbine orientation was used. Refer to the following McGuire FSAR sections for a description of our analysis and evaluation.

Sections 3.5.1.2, 3.5.2.7, 3.5.5, 3.5.6

Sections 10.2.2, 10.2.3, 10.2.4, 10.2.5