

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | M | O | C | C | N | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 56

CON'T
0 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 1 | 7 | 7 | 0 | 8 | 12 | 0 | 8 | 0 | 8 | 0 | 9 | 0 | 8 | 3 | 0 | 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2 | During normal power range operation it was discovered that Cntmt sump drain
0 3 | valves had been open for about 55 minutes. During this time, the cntmt sump
0 4 | level alarm system was essentially inoperable (T.S. 3.4.6.1.b) since it may
0 5 | not have detected a small RCS leak to the cntmt sump. Increases in offsite
0 6 | dose rates were essentially zero; no Rms alarms were received. The valves
0 7 | were shut immediately. The cntmt atmosphere particulate and gaseous radio-
0 8 | activity monitoring systems were operable during this event.
7 8 9

0 9 | C | I | 11 | A | 12 | A | 13 | V | A | L | V | E | I | X | 14 | E | 15 | P | 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

17 | 8 | 0 | 21 | 22 | 0 | 4 | 4 | 24 | 26 | 0 | 3 | 28 | 29 | L | 30 | 0 | 32
LER RC REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.

ACTION TAKEN FUTURE ACTION EFFECT IN PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRO-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
H 18 7 19 7 20 0 0 0 0 22 Y 23 N 24 A 25 L 2 0 0 0 25
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
1 0 | The containment sump drain valves were inadvertently left open by the Operator
1 1 | after a routine sump draining evolution. Upon discovery, the valves were immediately
1 2 | shut, thereby ending the event. Operations personnel on shift at the time of the
1 3 | incident have been counselled concerning responsibility to pay close attention
1 4 | to plant evolutions in their unit.
7 8 9

1 5 | F | 28 | 0 | 9 | 1 | 29 | NA | 30 | A | 31 | Operator Observacion | 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

1 6 | G | 33 | M | 34 | 0.625 curies | 35 | Main Vent Stack | 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

1 7 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

1 8 | 0 | 0 | 0 | 40 | NA | 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
PERSONNEL INJURIES NUMBER DESCRIPTION

1 9 | Z | 42 | NA | 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

2 0 | N | 44 | NA | 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
PUBLICITY ISSUED DESCRIPTION NRC USE ONLY

NAME OF PREPARER R. L. Wenderlich PHONE (301)269-4776

8000180318

LER NO. 80-44/3L
DOCKET NO. 50-317
EVENT DATE 08/20/80
REPORT DATE 09/08/80
ATTACHMENT

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES:

During normal power range operation, it was discovered that the Containment Sump Drain Valves had been open for approximately 55 minutes. During this time, the cntmt sump level alarm system was essentially inoperable (T.S. 3.4.6.1.b) since it would not have detected a small RCS leak to the cntmt sump. Increase in offsite dose rate was essentially zero and no RMS alarms were received. The valves were shut immediately. The cntmt atmosphere particulate and gaseous radioactivity monitoring systems were operable during this event. Additionally, both sump valves automatically shut on SIAS and CIS signals. Therefore, this event had no appreciable impact upon the public health or safety. This is not a repetitive occurrence.

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS:

The cntmt sump drain valves were inadvertently left open by the Operator after a routine sump draining evolution. Upon discovery, the valves were immediately shut, thereby ending the event. Operations personnel on shift at the time of the incident have been counselled concerning their responsibility to pay close attention to plant evolutions in their unit. The control switches for these valves will be modified to cause them to spring return to the shut position.