

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | C | T | M | N | S | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

CON'T 01 | L | 0 | 5 | 0 | 0 | 0 | 3 | 3 | 6 | 7 | 0 | 8 | 1 | 2 | 8 | 0 | 8 | 0 | 9 | 0 | 8 | 8 | 0 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
02 | During routine power operation the containment air temperature was found to be in excess
03 | of the limit of 120°F as specified by Tech. Spec. 3.6.1.5. The service water temper-
04 | ature control valve to Reactor Building Closed Cooling Water (RBCCW) heat exchangers was
05 | found to be set too high. The temperature control valve required adjustments to lower
06 | containment temperature to less than 120°F within 8 hours. Maximum temperature was
07 | 120.4 degrees. Similar events: LER 80-03, 78-31.

09 | W | A | 11 | A | 12 | B | 13 | V | A | L | V | E | X | 14 | B | 15 | G | 16
17 | 8 | 0 | 0 | 3 | 0 | 0 | 3 | L | 0
18 | Z | 19 | Z | 20 | 0 | 0 | 0 | 0 | N | 23 | N | 24 | A | 25 | K | 1 | 2 | 5 | 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10 | Plant conditions prior to refueling resulted in increased heat load on RBCCW with
11 | resultant decrease in cooling availability to containment. The temperature control
12 | valve was readjusted and normal containment temperatures restored.

15 | E | 28 | 1 | 0 | 0 | 29 | NA | 30 | A | 31 | Operator Observation | 32
16 | Z | 33 | Z | 34 | NA | 35 | NA | 36
17 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39
18 | 0 | 0 | 0 | 40 | NA | 41
19 | Z | 42 | NA | 43
20 | N | 44 | NA | 45

8009160469

J.S. Harris

PHONE 203/447-1791

NRC USE ONLY