PART 21 IDENTIFICATION NO	80 - 285 - 001 COM	PANY NAME belaved
DATE OF LETTER 11/11/60	DOCKET NO. 80-361,	2tc
DATE DISTRIBUTED WINTED	original REPORT	SUPPLEMENTARY 🗶
DISTRIBUTION:		55
REACTOR (R) X	FUEL CYCLE &	SAFEGUARDS (S)
IE FILES	MATERIALS (M)	IE FILES
AD/ROI	IE FILES	AD/SG
AD/RCI	AD/FRYSI	AD/ROI 8
REGIONS I, II, III, IV, V	REGIONS I, II, III, IV, V	REGIONS I, II, III, IV, V
VENDOR BR, R-IV	VENDOR BR. R-IV	VENDOR BR. R-IV
LOEB / MPA MVB 5715	NMSS / FOMS SS-395	NRR/DOL
AEOD MNB 7602	LOEB / MPA MVB 5715	NMSS / SG SS-881
NRR/DOE	AEOD MNB 7602	LOEB / MPA MVB 5715
NRR/DSI	ASLBP E/N 450	AEOD MNB 7602
NRR/DST -	SAP/SP. MVB-7210A	ASLBP E/W 450
NRR/DOL -	CENTRAL FILES 016	CENTRAL FILES 016
ASLBP E/W 450	CENTRAL FILES ("CHRON)	CENTRAL FILES (CHRON)
CENTRAL FILES 016	PDR	CENTRAL FILES SS-395
CENTRAL FILES (CHRON)	LPDR .	PDR ·
PDR	TERA	LPDR
LPDR		TERA
TERA		
ACTION:		
PRELIMINARY EVALUATION OF THE	ATTACHED REPORT INDICATES	LEAD RESPONSIBILITY FOR
FOLLOWUP AS SHOWN BELOW:		- I I I I I I I I I I I I I I I I I I I
IE 🗓	NRR	NMSS OTHER
RCI ROI SG ELS FITNSI		
8011210		REV. 8/1/80
8011210432	: 102 2 2 2	



Engine and Compressor Division 550 85th Avenue P.O. Box 2161 Oakland California 94621 (415) 577-7400

nec Put zi ID # 80-285-001

November 11, 1980

50-361, etc.

Director Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Dear Sir:

Please refer to Transamerica Delaval's letter of September 19, 1980. In this letter a report of a potential defect in a component of the DSRV standby diesel generator was reported, as required by 10CFR21.

Due to site conditions the schedule for inspection which we recommended in the September 19 letter has not been met. All of the sites are in various stages of construction which makes it impractical to open up the engines for this inspection.

At every site we will have Service Engineers present for a considerable time witnessing all the final detailed installation and pre-start checking. During this period the inspeciton will be completed. Any replacement parts required will be installed before any units are started. We have a written procedure, SIM No. 349, detailing the link rod inspection procedure. This procedure will be made part of the pre-start procedure for all the sites involved.

At the one site which is in an operating condition (Southern California Edison, San Onofre) the inspection was performed September 20 and September 22. The engines were found to be satisfactory. A copy of Southern California Edision's letter of October 9, 1980 reporting this inspection is attached.

Sincerely,

D. Martini

Vice President and General Manager Transamerica Delaval, Inc.

DM/ds

Enc: (1)

cc: R.C. Haynes
Nuclear Regulatory Commission
1990 N. California Blvd.
Walnut Creek, CA 94596

To all affected sites (11)

POOR ORIGINAL

Southern California Edison Company



SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 926'2

October 9, 1980

Enclosure (2)

Transamerica DeLaval Inc. Engine & Compressor Division Post Office Box 2161 Oakland, California 94621

Attention: Mr. John Wilder

Engineer Customer Service

Subject:

Engine S/N 75041/42

Gentlemen:

This communication is in response to your letter dated September 22, 1980.

On September 18, 1980, we were informed by telephone through Mr. Hartwick of a potential 10 CFR 21 problem with our two standby diesel-generators.

On September 20 and 22 your Mr. Lindstrom, assisted by station personnel made the prescribed inspection of our generator engines and they were found to be in good working order.

If any more information is required, please do not hesitate to call.

Very truly yours,

R. R. Brunet

No. 1 Unit Superintendent

RRB/ap

Enclosure: Copies of Service Representative

Inspection Report