

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 T N S N P 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

CON'T 01 REPORT SOURCE L 6 0 5 0 0 0 3 2 7 7 1 0 1 6 8 0 8 1 1 1 4 8 0 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 Unit 1 in mode 4. While performing SI-28, containment air return fan B-B damper
03 would not open with the required torque of 68.1 inch pounds. The action statement
04 of LCO 3.6.5.6 was entered. There was no effect upon public health or safety.
05 Previous occurrences - none.

09 SYSTEM CODE S C 11 CAUSE CODE E 12 CAUSE SUBCODE B 13 COMPONENT CODE V A L V E X 14 COMP. SUBCODE L 15 VALVE SUBCODE A 16

17 LER/RO REPORT NUMBER 8 10 EVENT YEAR 8 10 SEQUENTIAL REPORT NO. 1 7 5 26 OCCURRENCE CODE 0 3 28 29 REPORT TYPE L 30 REVISION NO. 0 32

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 The damper bearings needed lubrication. The damper bearings were lubricated and the
11 damper retested satisfactorily. The corrective action was performed within the
12 allowable time limit of LCO 3.6.5.6. A periodic lubrication program will be established
13 to prevent future occurrences.

15 FACILITY STATUS G 28 % POWER 0 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Failed surveillance test 32

16 ACTIVITY CONTENT 2 33 2 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 35

17 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39

18 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43

20 PUBLICITY ISSUED N 44 DESCRIPTION NA 45

POOR ORIGINAL

NRC USE ONLY

Name of Preparer W. T. Corzle/G. B. Kirk

Phone 615-842-8261

8011210574