		Gilbert Commonw
PART 21 IDENTIFICATION NO. 80-317-001 COPANY NAME Engineers & Consul		
DATE OF LETTER 1211/60	DOCKET NO. 50 - 39.5	<u> </u>
DATE DISTRIBUTED 12/17/60	a.m. ORIGINAL REPORT	SUPPLEMENTARY
DISTRIBUTION:		
REACTOR (R)	FUEL CYCLE &	SAFEGUARDS (S)
" IE FILES "	MATERIALS (M)	IE FILES
EES	IE FILES	
	AD/FRYSI	AD/SG AD/ROI
REGIONS I, II, III, IV, V	REGIONS I, II, III, IV, V	당 양 첫
VENDOR BR. R-IV	VENDOR BR. R-IV	REGIONS I, IE, III, IV, V
LOEB / MPA MNB 5715	NYSS / FCMS SS-395	VENDOR BR. RIV
AEOD MNB 7602	LOEB / MPA MVB 5715	NRR/DOL
NRR/DOE	AEOD MNB 7602	NMSS / SG SS-881
		LOEB / MPA MVB 5715
NRR/DSI	ASLBP E/W 450	AEOD MVB 7602
NRR/DST	SAP/SP. MB-7210A	ASLBP E/W 450
NRR/DOL -	CENTRAL FILES 016	CENTRAL FILES 016
ASLBP E/W 450	CENTRAL FILES ( CHRON)	CENTRAL FILES (CHRON)
CENTRAL FILES 016	PDR	CENTRAL FILES SS-395
CENTRAL FILES (CHRON)	LPDR	PDR
PDR	TERA	LPDR
LPDR		TERA
TERA		
ACTION:		
PRELIMINARY EVALUATION OF THE	E ATTACHED DEDORT INDICATES	LEAD DECOMMEND
FOLLOWUP AS SHOWN BELOW:	ATTACHED REPORT INDICATES	LEAD RESPONSIBILITY FOR
:- <b>-</b>	NRR 🗀	IMCC CT CTUTTO CT
下木	mut	NYSS OTHER
EES 247		
8012240047	5	PEV. 8/1/80
		9/17/80

# nrc Part 21 ID + 80-317-001



## Gilbert/Commonwealth engineers and consultants

GILBERT ASSOCIATES, INC., P. O. Box 1498, Reading, PA 19603 Tel. 215-775-2600/Cable Gilasoc/Telex 836-431

50-395

December 11, 1980

United States Nuclear Regulatory Commission Region I 631 Park Avenue King of Prussia, PA 19406

ATTENTION: Mr. Boyce H. Grier

Director

SUBJECT: Potential Reportable Event

Service Water Pump Speed Switch Control

Dear Mr. Grier:

In accordance with 10CFR21 requirements, this is to document that Mr. S. D. Ebneter of Region I was notified by telephone on December 10, 1980, at approximately 8:15 a.m., of a potential reportable event.

### Name of Individual Who Reported

Stephen J. Torma - Manager, Inspection & Material Services, who was acting for the Quality Assurance Division General Manager, made tie call.

### Activity Involved

Gilbert Associates, Inc. (GAI) design of control circuitry for service water pump speed switch.

### Components Involved

Not applicable.

## Facility Involved

V. C. Summer Nuclear Station, Unit 1, being constructed by the South Carolina Electric & Gas Company.

GLEERT 45500 4765 (N.) 1 0 Est MER Repring PA 19600 Tel 215 775-2800 Cabe Glason Tales 606-431

US Nuclear Regulatory Commission Mr. B. H. Grier

N. R. Barker

December 11, 1980 Page 2

#### Nature of Defect

The signal from the load sequencer for the service water pump speed switch to go to high speed on loss of off-site power was a momentary contact. The speed switch operated, but then dropped back to low speed when the contact dropped out. This deficiency was discovered and documented during routine testing.

The safety hazard which could be created, is possible inadequate service water flow.

#### Date Information Obtained

A written report indicating this to be potentially reportable, was received by the Quality Assurance Division on December 4, 1980, from GAI Engineering.

#### Corrective Action

The circuitry has been redesigned to include a seal-in interlock. We have determined that this condition does not exist on any of our other design projects. No further action is planned.

If you require any further information on this matter, please contact me at (215) 775-2600, extension 2285.

Very truly yours,

General Manager

Quality Assurance Division

cc: H. Lorenz

T. M. Demers

V. Stello, Director, Office of Inspection & Enforcement - 3 copies Nuclear Regulatory Commission, Washington, D.C. 20555

RCH: NRB: 1sa