

KANSAS GAS AND ELECTRIC CON TIC-

PDR LPDR TIC NSIC CENTRAL FILES

GLENN L KOESTER

February 18, 1981

Mr. W.C. Seidle, Chief Reactor Construction and Engineering Support Branch U.S. Nuclear Regulatory Commission Region IV 611 Ryan Plaza Drive Suite 1000 Arlington, Texas 76012

Dear Mr. Seidle:

In December, 1980, we received a letter from General Electric Co. (GE) which advised us that failures had been experienced with certain lexan coil spools supplied with their HFA type relays. Mr. ECreel advised Mr. WACrossman of this letter on December 23, 1980.

On January 15, Information Notice 81-01 was issued to advise the industry of this problem.

On February 4, Mr. ECreel advised Mr. Crossman that an investigation had been initiated to determine if any of the potentially defective coils were installed in safety-related relays at Wolf Creek, and that several of the potentially defective coils had been found.

At this time an inspection to determine if the coils are cracked is not planned because we will replace the relays as recommended by GE, regardless of the present condition of the coils. Our schedule for replacing the coils will be dependent upon the availability of replacement relays from GE.

Please advise if you need additional information.

Yours very truly,

8103240132

Lien i the Til

GLK:bb cc: TVandel (NRC Site Inspector) Director Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, D.C. 20555 Attach 15 copies