

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: [ ][ ][ ][ ][ ][ ][ ][ ] ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | AIR | AN | 0 | 2 | 0 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

CONT

0 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 6 | 8 | 7 | 0 | 3 | 2 | 8 | 8 | 1 | 8 | 0 | 4 | 2 | 4 | 8 | 1 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES ⑩

0 2 | During Mode 1 operation, with a normal power reduction in progress in  
0 3 | preparation for a refueling outage, a routine operator inspection  
0 4 | identified excessive packing leakage from the Emergency Feedwater Pump  
0 5 | (2P7B) and water in the bearing lubricating oil. The redundant Emergency  
0 6 | Feedwater pump remained operable. Similar to LER 50-368/80-089. Report-  
0 7 | able per T.S. 6.9.1.9.b.  
0 8 |

0 9 | C | H | 11 | E | 12 | B | 13 | P | U | M | P | I | X | 14 | B | 15 | Z | 16 | 8 | 1 | 0 | 1 | 4 | 0 | 3 | L | 0 | 18 | F | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | 0 | N | 23 | Y | 24 | A | 25 | B | 5 | 8 | 0 | 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS ⑰

1 0 | Water in the bearing lubricating oil was due to the excessive shaft  
1 1 | packing leakages during pump idle time. Packing is to be replaced with  
1 2 | mechanical seals on both Emergency Feedwater Pumps, 2P7A & 2P7B. More  
1 3 | frequent inspections will be conducted until installation of the mechanical  
1 4 | seal.

1 5 | F | 28 | 0 | 3 | 1 | 5 | 29 | Power Reduction | A | 31 | Operator Observation | 32  
1 6 | Z | 33 | Z | 34 | NA | NA | 36  
1 7 | 0 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39  
1 8 | 0 | 0 | 0 | 0 | 40 | NA | 41  
1 9 | Z | 42 | NA | 43  
2 0 | N | 44 | NA | 45

NAME OF PREPARER Chris N. Shively PHONE 501-968-2519

8105050 597