



SUPPLEMENTARY INFORMATION

1. Report No.: 50-302/78-045/03L-0
2. Facility: Crystal River Unit #3
3. Report Date: 27 September 1978
4. Occurrence Date: 7 September 1978
5. Identification of Occurrence:

Failure to have two operable Control Room emergency ventilation systems which is contrary to Technical Specification 3.7.7.1.

6. Conditions Prior to Occurrence:

Mode 4 hot shutdown.

7. Description of Occurrence:

At 1600, during the performance of Surveillance Procedure, SP-417, Refueling Interval Integrated Plant Response to Engineered Safeguards Actuation, it was discovered that the Control Complex air supply damper D-1, did not respond to a close command. This was substantiated by observing that a closed position indication had not been received in the Control Room. Operability was restored on 8 September 1978, after a successful post maintenance test.

8. Designation of Apparent Cause:

This occurrence was caused by the mechanical binding of the air supply damper, D-1, which prohibited it from closing and making contact with closed limit switch.

9. Analysis of Occurrence:

The health and safety of plant and public was not endangered as no accident conditions existed at the time of this occurrence.

10. Corrective Action:

Preventive maintenance will identify the requirement for frequent lubrication as corrective action.

11. Failure Data:

No previous occurrence of this event.

/rc