

POOR ORIGINAL

THIS DOCUMENT CONTAINS
POOR QUALITY PAGES


In the Matter of:

ACRS-FLUID DYNAMICS SUBCOMMITTEE MEETING

DATE: August 20, 1980 PAGES: 237 thru 361

AT: Inglewood, California

T-0776

ALDERSON  REPORTING

400 Virginia Ave., S.W. Washington, D. C. 20024

Telephone: (202) 554-2345

8008260 595

1 Staff. On my right is Herb Abercrombie. He is
2 Superintendent of the Browns Ferry plant. Sitting next to
3 him is Tom Knight, who is Chief of the Reactor Engineering
4 Branch, the Division of Nuclear Power.

5 Over on the right we have Bert Morris, who works
6 in Tom's Branch, and we have Pelar Metcalf, who works in
7 Engineering Design. We have Ed Edmonson, who has worked at
8 Browns Ferry, and John Rathjen, who is also in the Division
9 of Nuclear Power. I believe that covers all of the TVA
10 people.

11 We have got three people from General Electric:
12 Hank Pfefferlen, who is directly behind me; Monte Ross and
13 Dick Gridley. So they will be prepared to address any
14 questions.

15 MR. PLESSET: Since many of you were not here
16 yesterday, I might introduce some of the people up here. Of
17 ACRS members, Mr. Etherington and Mr. Ebersole. Dr. Bates
18 is a Federal designated employee for this subcommittee
19 meeting. Then we have consultants, Dr. Catton, Dr. Zudans,
20 Dr. Theofanus, Dr. Wu and Dr. Acosta. So now you know us,
21 and why don't you proceed?

22 MR. DOMER: We have a lot of ground to cover here
23 this morning. I want to emphasize that we want to answer
24 any and all questions you might have; but we do have a lot
25 of information we want to pass along to you, so we will do

1 our best to keep it moving as much as we can.

2 We are pleased to be here and meet with you, and
3 that is all I have to say. With that, I would like to
4 introduce Ed Edmonson, who will give you a presentation on
5 the description of the normal operations of the scram system.

6 MR. EDMONSON: If there is anyone here who can't
7 hear me, I am Ed Edmonson. I wish you would just call me
8 Ed. And please ask any questions.

9 I am going to try to explain to you the normal
10 operation of the control rod system and what is supposed to
11 happen and tell you what is going on out there. I am sure
12 all of you know that the BWR control rods go in from the
13 bottom, so what I have got right here is just a little
14 drawing that shows the typical control rod and normal
15 operation of the thing. Reactor control moves the rods in
16 and out and causes the control rods to enter.

17 We have drive water coming in. Right here we have
18 got a little representation of control rod drive, and I want
19 to talk about the normal operation of the drive when the
20 operator moves the rods.

21 The insert. We have drive water coming in, a
22 direction control valve which opens and lets the water under
23 the piston, approximately 260 pounds above reactor pressure,
24 which moves the rod in here, coming out through this valve.
25 We go to exhaust.

1 On a withdrawal it is a little bit different. The
2 drive water -- this withdrawal valve will open and push this
3 down on the piston. The exhaust path is right out through
4 this way. Now, that is the normal operation of the control
5 rods.

6 I am going to change a little bit now and just
7 talk about the system as a scram system. We know the
8 operator, if we get into trouble, something that the
9 operator can't respond to, we want all of those rods to
10 insert and shut the plant down.

11 I have taken away the direct control valves, so
12 right now we are just talking about the scram system. All
13 we have got to do, underneath of the piston here you see a
14 scram inlet valve and scram outlet valve, and you see that
15 they are normally closed. Now, these things, they are
16 closed. We have 1500 pounds of reactor water coming in. It
17 charges the accumulator. This 1500 pounds will push the
18 piston all the way down in this accumulator.

19 The nitrogen, which started off around 560 pounds
20 -- the piston with the bottom out is going to now have about
21 1100 pounds here and 1500 pounds, and the valves are
22 closed. You have got the scram inlet and scram outlet
23 valves. On the scram, all we have to do is open this and the
24 water is going to go in and the rod will go in.

25 These things are spring loaded so that when we

1 take the air away from them, the scram outlet valve will
2 open prior to the scram inlet valve. That prevents
3 excessive pressure on the walls of the control rod drive.
4 These valves on the shelf condition are to be open. It
5 requires air pressure to maintain them closed. Everything
6 is fail safe. This is a fail safe function. So you want to
7 keep air on these things.

8 Here you see the scram pilot valves. Now, this
9 portion of it, what we are talking about right here, this is
10 typical of 185 rods. When we get over to the backup scram
11 valve, that is common to all of them.

12 MR. CATTON: What would happen if you got water in
13 the air side?

14 MR. EDMONSON: Water in this?

15 MR. CATTON: Yes. Would they still unload if
16 pressure was decreased?

17 MR. EDMONSON: Yes, I think they would. Also,
18 Browns Ferry has got drivers on those. I had never seen any
19 water in them. Like I said --

20 MR. CATTON: I don't think anybody plans on the
21 water. I was just curious.

22 MR. ZUDANS: When you open the scram valves, where
23 does the air go?

24 MR. EDMONSON: Out into the room.

25 MR. ZUDANS: Out into the room.

1 MR. EDMONSON: Yes.

2 MR. ZUDANS: The drain is then next to the valve,
3 the opening is right there next to the valve?

4 MR. EBERSOLE: Just a little hole right in the
5 side of the valve.

6 MR. EDMONSON: Yes, about the size of my fist,
7 electrically fitted. You have a solenoid that holds this
8 valve closed in the condition we see right here. Now, the
9 normal path to the air is through -- these are common to all
10 of them. The air supply comes through here, through here,
11 really into here. This is an electrical solenoid.

12 The electrical part of the thing, once again, is
13 fail safe. The reactor protection system would deenergize
14 that coil and will let this thing open.

15 MR. ZUDANS: Where does the air go when it opens,
16 out right there into the room or back through a series of
17 blinds?

18 MR. EDMONSON: It goes out into the room. The
19 actual path, what I am showing you right here, you will see
20 that the air is coming right in through this wall.

21 MR. ZUDANS: That I understand, but where does it
22 go when the solenoid opens?

23 MR. EDMONSON: Right out into the room.

24 MR. ZUDANS: Right at the body of the valve?

25 MR. EDMONSON: Yes.

1 MR. ZUDANS: Without any lines?

2 MR. EDMONSON: Yes.

3 MR. ZUDANS: So the water would not matter.

4 MR. EDMONSON: No. The actual path at that point
5 of the scram is going to be like so, routed through here,
6 and the two valves. This is a pipe, this one, and this was
7 the discharge and this one is still open. It will keep the
8 scram valves open. But yes, it discharges right into the
9 room of the valve. The same is true with these backup
10 valves. They are over on the wall.

11 MR. CATTON: How big is the hole that the air
12 discharges through?

13 MR. EDMONSON: I would say about half an inch, a
14 pretty good size.

15 MR. EBERSOLE: So each valve is like half an
16 inch? I thought it was about a pencil head or thereabout.
17 Is it a half-inch?

18 MR. EDMONSON: When you get inside of the valve
19 and you look at those diagrams, the actual exhaust port you
20 can stick your finger in. These are the smaller ones.
21 These are much larger.

22 MR. EBERSOLE: Each valve, then, has about a
23 half-inch exhaust port into the atmosphere local to the
24 valve, then.

25 MR. EDMONSON: Yes.

1 MR. EBERSOLE: And if I take an enthusiastic
2 painter and paint all over all of these things, he would not
3 close them, would he?

4 MR. EDMONSON: No.

5 MR. EBERSOLE: I believe you said that the air is
6 dry so you don't have water in it.

7 MR. EDMONSON: That is right.

8 MR. EBERSOLE: So it runs through a dessicant of
9 some sort.

10 MR. EDMONSON: Yes.

11 MR. EBERSOLE: You know these things are supposed
12 to be seismically designed. I am going to shake your can of
13 dessicant. Is there any normal flow through these lines
14 that would carry this debris into the valve which would
15 cause a failure? In the normal mode of operation, is the
16 air system flowing at all through normal leakage?

17 MR. EDMONSON: Yes.

18 MR. EBERSOLE: It is leaking some, isn't it?

19 MR. EDMONSON: Yes.

20 MR. EBERSOLE: But if I shook the can of dessicant
21 up, I would provide entrainment to this -- is there a filter
22 downstream of the dessicant?

23 MR. EDMONSON: There is a filter there.

24 MR. EBERSOLE: Downstream of the dessicant? So it
25 would stop the dessicant.

1 MR. EDMONSON: Really what they have done, we have
2 only shown two valves here. This is the backup circuit.
3 Actually there is a parallel path disk identical to this
4 where we can go in and take this one out of service to clean
5 the filters and do whatever, so I don't see any problems at
6 all there.

7 MR. EBERSOLE: Really you are protected from the
8 dessicant by filters.

9 MR. EDMONSON: Yes.

10 MR. PLESSET: Go on.

11 MR. EDMONSON: We just talked about the electrical
12 part, taking the voltage right here and showing the
13 discharge path. These are typical for each of the 185 rods
14 locally. Now, this one, these are back over on the wall at
15 the CRD system. They are a little bit different. Anyhow,
16 when they discharge, you see, we have one discharge path
17 here, and due to this check valve right here, when this one
18 opens we have a parallel discharge there.

19 Here we deplete the air to each hydraulic control
20 unit. Here we deplete the entire header.

21 MR. EBERSOLE: Is there any crosstie between the
22 instrument air supply and the normal air supply for
23 emergency use?

24 MR. EDMONSON: At the dry wall area?

25 MR. EBERSOLE: No.

1 MR. CATTON: The plant service area.

2 MR. EBERSOLE: Do you have an emergency crosstie?

3 MR. EDMONSON: I don't know about that.

4 MR. ABERCROMBIE: It is all one source.

5 MR. EBERSOLE: You don't have an emergency
6 crosstie to service air into the instrument air system,
7 then, do you? Some plants do that.

8 MR. ABERCROMBIE: There is another set of air
9 compressors which supply service air, but they still have
10 the same criteria for nonlube, nonoil.

11 MR. EBERSOLE: Dry air.

12 MR. ABERCROMBIE: Yes.

13 MR. EDMONSON: I am going to go a little further
14 here and talk about these vent valves.

15 MR. ZUDANS: Before you leave that, could you
16 explain the function of the backup scram?

17 MR. EDMONSON: That is pretty simple. Let us say
18 that these --

19 MR. ZUDANS: What is it backup to? Just the air
20 system?

21 MR. EDMONSON: Well, there is a backup to these.
22 If these valves right here do not discharge properly, if you
23 deplete the entire header, these are going to open anyhow.

24 MR. ZUDANS: Okay, but there are no hydraulics
25 except the fluid or the water backup lines or backup wells

1 for discharge. Just those two scram valves. That is all you
2 have, right? Only the controls have the backup. Only the
3 air system is backed up. There are just two scram --

4 MR. EDMONSON: There is only one scram inlet and
5 one scram outlet valve.

6 MR. ZUDANS: That is all you have?

7 MR. EDMONSON: Right.

8 MR. EBERSOLE: Has there been any recorded
9 incidence of the 1500 pound water that extends into these
10 valves managing to get itself into the air systems?

11 MR. EDMONSON: There is no way to do that. That
12 air system -- I mean --

13 MR. EBERSOLE: It really depends on the internal
14 design of the valves, and I don't know what that is.

15 MR. EDMONSON: Are you talking about this thing?

16 MR. EBERSOLE: Yes. There is no way for the air
17 to become waterlogged. Not at that point, anyway.

18 MR. EDMONSON: It doesn't work that way.

19 MR. EBERSOLE: Well, TMI got into trouble because
20 they got water into the air system through an unusual route,
21 and here --

22 MR. EDMONSON: That would be unusual. They would
23 have to come up through half-inch steel bar. Right here is
24 your valve, so there is no way for water to get in.

25 MR. EBERSOLE: Are there any other possible sources?

1 It is an open structure, what it is, so there is no access
2 of water to air in that particular device. Are there any
3 other devices within the air system where water is separated
4 by a diaphragm or whatever?

5 MR. EDMONSON: Not to my knowledge.

6 MR. EBERSOLE: And you feel there is no way to get
7 water into that system, that air system.

8 MR. EDMONSON: Any time you compress air, you have
9 a chance for moisture.

10 MR. EBERSOLE: No, I am talking about foreign
11 sources of water. There is none.

12 MR. EDMONSON: No.

13 MR. EBERSOLE: I know you get condensation. You
14 have your dessicant to do that, and then you have got to
15 prevent the system from getting dessicant in it, which you
16 do with filters. All right, I am done.

17 MR. EDMONSON: We have just talked about
18 deenergizing the scram pilot valves. That is done by the
19 reactor protection system. And you see coming off here -- I
20 am going to go ahead and open the scram inlet and scram
21 outlet valve, and here is the idea.

22 We are going to electrically deenergize these and
23 discharge air, and the valves are going to open. The scram
24 outlet valves are going to open first. Immediately after
25 that, the scram inlet valve. The water is going to go under

1 the piston. It has got to go somewhere. It comes through
2 the outlet valve to the six-inch header, the Scram Discharge
3 Volume.

4 I have drawn it simply here. Here is your
5 six-inch header. Here is your two-inch drain line going
6 into the instrument volume. We deenergized here.
7 Electrically we also deenergize the vent and drain autoclose
8 solenoids. These are going to discharge atmosphere the same
9 way that these did. They are going to take the air off of
10 the vent and drain valves, and they will close also.

11 Right here I have shown a manual oscillation valve
12 from the control room. The operator has a hand switch. He
13 can open this valve. It will block the air here, deplete
14 the air to these things, and he can close those valves if
15 there is no scram signal in them. If the scram signal is
16 in, naturally this air header would be depleted and he could
17 not reopen the valves. I have also shown our 3 gallon, 25
18 gallon and 50 gallon switches on the instrument volume.

19 Now, what we just talked about is the way the
20 thing is supposed to work. We deenergize here. These
21 valves open. The water pushes the drive in. That is what
22 happens. It works.

23 Now, in talking, within an hour after the
24 happening, with the operators, and the shift technical
25 adviser was there, what they saw on the vertical core

1 display -- this is typical, once again, of this 185 of
2 these. It shows the control rod position. It is probably
3 also the revision number of my drawing, but anyway it shows,
4 in addition to that position, it has four small lights there.

5 Here is a blowup of what you see. You can see the
6 positions of that rod. It has got four lights there. Now,
7 the first one is the accumulator. We have a pressure switch
8 and a level switch down here, and since you have got 1500
9 pounds over here, 1100 pounds here, any passage will be
10 water into the gas. We have a level switch. If we get
11 water in there, you get some enunciation.

12 If this pressure should sag and drop down, he also
13 gets an enunciation, a little amber accumulator light. Here
14 is a rod identification number. If it drifts, if you ever
15 get a drift alarm, the thing is right here. You have a
16 little blue scram light, a direct indication of what the
17 scram valves did.

18 There are switches actually on the valve that are
19 in series. When both of these valves come off of their
20 seats, and it requires both of them, they turn on this blue
21 scram light.

22 Now, what the guys observed on the east side was
23 that those control rods were sitting there, the blue scram
24 lights were on. They knew that the valves had to be opened
25 from that, but the key was that there was a recognizable

1 position in the window right there. That told me that that
2 rod not only had stopped going in but it settled out. And
3 it settled out at the time that it had a full scram signal.
4 The water had a path in, no doubt about that. Since it did
5 not go anywhere, that header was full of water.

6 MR. EBERSOLE: There is no pressure indication on
7 the dump volume per se for the dump volume pressure.

8 MR. EDMONSON: Down here.

9 MR. EBERSOLE: Yes.

10 MR. EDMONSON: No.

11 MR. EBERSOLE: Why not? Would you like to have
12 it? If not, why not? It is cheap.

13 MR. EDMONSON: It does not matter to me.

14 MR. EBERSOLE: Well, that would have quickly
15 verified your problem. Anyway, you don't have it. Carry on.

16 MR. EDMONSON: I'm not so sure. I'm an electrical
17 man. Those faucets and valves are beyond me. Anyhow, that
18 is the operation of the system.

19 Now, you notice I haven't talked about
20 electrically how we deenergize these. I believe I have
21 satisfied all of the guys before that that works, and in
22 your handout I gave you a writeup and a little sketch of
23 justification for the proper electrical operation.

24 Has anybody got any questions?

25 MR. PLESSET: Does that complete your presentation?

1 MR. ZUDANS: I would just like to make sure. The
2 backup on scram is only on the head portion of it?

3 MR. EDMONSON: That is correct.

4 MR. ZUDANS: It drains the air from the scram
5 valves so that they can open up.

6 MR. EDMONSON: Yes.

7 MR. ZUDANS: There is no backup on water lines of
8 any kind. In order to get the scram you have to move those
9 two valves.

10 MR. EDMONSON: That is correct. I think you were
11 talking about a problem with just one valve.

12 MR. ZUDANS: I understand. There is no backup
13 also on normal insert and withdrawal. You have to operate
14 the pair of valves, and they are the same valves all of the
15 time. So the whole thing depends on these valves being able
16 to function properly, right?

17 MR. EDMONSON: Yes.

18 MR. ZUDANS: Thank you.

19 MR. EDMONSON: In a worst case, it would be one
20 route. The redundancy in that thing --

21 MR. ZUDANS: We understand that.

22 MR. PLESSET: I think we should go on. I think
23 you have answered Mr. Zudans' question three or four times.
24 That should be enough.

25 MR. DOMER: The next subject is the as-built

1 design, the scram system, and John Rathjen is going to make
2 that presentation.

3 MR. RATHJEN: My name is John Rathjen. I am with
4 the Nuclear Maintenance Branch of the TVA. In presenting
5 the as-built configuration of Browns Ferry Scram Discharge
6 System, we prepared these handouts which duplicate all of
7 the Vu-graphs which I will be working with this morning.
8 They are in the same order as I will be presenting them
9 except for one insert I see you have found.

10 Because of the detail that was included on it, it
11 had to be slightly larger than the Vu-graph. There are also
12 some additional drawings which had a great deal of detail on
13 them, and because of the reproduction, we lost some detail.
14 However, we do have the full-size drawings available, and
15 you will have the complete detail of those.

16 By way of introduction to the mechanical
17 configuration, I would like to digress a little bit by going
18 over part of it that Mr. Edmonson went over by starting off
19 with a simplified control rod drive hydraulic control
20 system. Represented here within the dotted lines is a
21 schematic of an individual hydraulic control unit.

22 There is an individual unit provided for each
23 drive, and each hydraulic control unit in turn contains all
24 of the valving and hardware necessary to correct the flow of
25 the normal insert and withdrawal to direct the movement of

1 an individual rod. Under normal operation, the control rod
2 drive hydraulic pump provides pressure that is routed in the
3 proper direction through the directional control solenoid
4 valves to either of the insert or the withdrawal side of the
5 double acting piston on the control rod drive.

6 However, under the situation which we are
7 discussing, the scram conditions, when a rapid insertion is
8 desired this pressure is provided by a more direct route
9 from a precharged accumulator which will direct pressure
10 into the insert side of the control rod drive to the inlet
11 scram valve, which we have already discussed.

12 More importantly for rapid insertion you require
13 rapid evacuation of any hydraulic fluid from the opposing
14 side of the double acting piston. This is accomplished by
15 the opening of the Scram Discharge Valve, which slightly
16 leads the insert valve in the opening.

17 Each rod as driven will displace approximately
18 three-quarters of a gallon of water, and it is this volume
19 which adds up to approximately 140 gallons for all 185
20 rods. And where it goes and what receives it, that we call
21 the Scram Discharge System and we will look at it next.

22 This corresponds to page 2 of your handout, and it
23 is a simplified isometric of the Scram Discharge Volume,
24 which is a system of two headers, all located on the east
25 and west side of the reactors, which is represented in red

1 here, these two banks, made up of six-inch diameter piping.

2 These are located on the 565 elevation of Browns
3 Ferry, and they are located directly above two banks of the
4 hydraulic control units. So on the east side directly below
5 this header system are 93 hydraulic control units, on the
6 west side, 92 hydraulic control units. Each of these
7 hydraulic control units is routed by one-inch stainless
8 steel, direct discharge water into this header system,
9 running from both header systems to an individual instrument
10 volume tank.

11 Also shown in red is a two-inch line coming from
12 the east approximately 170 feet long to get to its
13 instrument volume connection. Shown in yellow off both
14 banks is a vent system for each header which directs down to
15 an individual vent valve for both the east and the west
16 sides.

17 Also coming off of the instrument volume tank on
18 this drain line is an individual drain valve. The two vent
19 valves are both one-inch valves that are schematically
20 operated by a diaphragm. They are normally closed. They are
21 spring loaded to the closed position. And the drain valve
22 is a similar valve except that it is a two-inch valve.

23 Not shown on this drawing are the flows that occur
24 downstream from the vent and drain valves. We will get into
25 detail on that later on. I will simply say that right now

1 they go down through the floor and eventually tie into the
2 clean rad waste system.

3 Under normal operating conditions these valves are
4 open. Upon receipt of the scram signal, these valves go to
5 the closed position to contain and limit the amount of water
6 that is displaced by the control rod drive discharge system.

7 Page 3 of your handout is a closeup look at the
8 instrument volume tank that we saw on the previous
9 schematic. Shown here are the two-inch line connections
10 running from the individual east and west headers. The tank
11 is equipped with valving and piping that connects these six-
12 inch liquid level sensors. The six are rated on a
13 configuration which gives us three different tank level
14 readouts, the lowest being the 3 gallon level, the second at
15 a 25 gallon level, and a remainder of the switches at the 50
16 gallon level.

17 Also shown on here is the drain line, the drain
18 valves, which goes to the closed configuration during scram,
19 and a relief valve which is provided on there and set to
20 relieve at 1250 psi.

21 I would like next to look at the detailed drawing
22 on the Scram Discharge System, which is page 4 of your
23 handout. It is laid out in isometric form similar to what
24 the previous simpler schematic was that you looked at,
25 except that it contains all the detail and is actually made

1 by site personnel of an as-built configuration.

2 This is one of the drawings we have the full size
3 on. It contains all of the dimensions and is a little
4 difficult to read on the reduced size. Again in red I have
5 shown the six-inch piping, which consists of or makes up the
6 headers, the two-inch piping which routes from both of them
7 to the instrument volume tank. The instrument volume tank
8 is in yellow and is in a large scale here so you will see
9 all of the detail.

10 You can see that on the drain side of the
11 instrument volume tank, we had the relief valve and the
12 drain valve which both tie into the same loop vent and tie
13 down through the clean rad waste system. In addition here
14 we have shown the flush connection which has been added to
15 both units 1 and 3 but which are not yet on unit 2 at this
16 time.

17 This particular sheet drawing shows the
18 configuration for unit 3 at Browns Ferry. The next Vu-graph
19 shows some variations in the configuration. They are
20 functionally the same but there are dimensional differences
21 in some of the routing of the pipe. This is the
22 configuration that was in effect at the time of the
23 incident.

24 You notice I have two red marks here where the
25 vent lines go through the floor. That is the point at which

1 the cut has been made at NRC's request in the vent line to
2 provide a positive atmospheric vent to the header system
3 itself rather than tying into the clean rad waste. This has
4 been complete on all three units.

5 I mentioned that when we made this cut, the stepup
6 from the clean rad waste system was capped off and the vent
7 line was rerouted over to discharge above a floor drain for
8 the dirty rad waste system. It is regarded by us as a
9 temporary configuration at this time, and we will talk about
10 some of the long-range plans later on.

11 MR. ZUDANS: Could I ask? You said that the vent
12 valve is pneumatically controlled, designed to close when
13 you lose the air pressure.

14 MR. RATHJEN: The vent valve will fail to the
15 closed position. It has to be held open pneumatically for
16 normal configuration. So if it failed to the closed
17 position, which is the position it would go to during a
18 scram --

19 MR. ZUDANS: That means during normal operations
20 you monitor the position of that valve by what means?

21 MR. RATHJEN: We have a mode indication on the
22 valve position in the control room.

23 MR. ZUDANS: Just on the basis of the current in
24 the solenoid, or actual position of the valve?

25 MR. EDMONSON: The head switches on the valve stem.

1 MR. ZUDANS: Thank you.

2 MR. RATHJEN: There are light indications in the
3 control room.

4 MR. CATTON: Do you have alarm on the air pressure
5 loss?

6 MR. EDMONSON: Yes. If the control rod pressure
7 sags, you get an abnormal --

8 MR. CATTON: Yesterday we heard about the drain
9 time into these various systems, and it looked like the SDIV
10 drains much faster than the Scram Discharge Volume. Do you
11 plan to do anything about that?

12 MR. RATHJEN: Will you repeat that? The SDIV?

13 MR. CATTON: Yes. Your instrument volume drains
14 much faster than your Scram Discharge Volume on the bottom
15 side of that figure up there, which would mean that your
16 instrument volume is not going to tell you a great deal
17 about the amount of water that is in the discharge volume.
18 What do you plan to do about that?

19 MR. RATHJEN: Well, if you will bear with me,
20 perhaps if you can save that question, because we have
21 personnel coming up to talk about it, a few of those, and I
22 am just trying to get through the configurations that I have.

23 MR. CATTON: You mentioned one change, but I can
24 wait.

25 MR. RATHJEN: It was just an opportune time.

1 because the graph just shows physically where that is
2 located.

3 As I mentioned, there are variations between the
4 three units. Basically we are addressing unit 3. However,
5 we did complete a drawing which shows the variation on the
6 piping arrangement, especially on the vent side of the
7 header, for units 1 and 2. Functionally they are the same,
8 and as shown, on this side is the east portion of the vent
9 system on the scram header, and the west side, both for unit
10 1. On this side is shown the configurations for unit 2.

11 Again, vent lines are shown in yellow, and the
12 header itself in red. This illustration is equivalent to
13 the inserted drawing in your handout, where you can see on
14 here there is quite a bit of information contained on this
15 one drawing, so we gave you a larger version. We color
16 coded them.

17 This is not intended to be an absolute drawing. It
18 is simply a flow diagram which will give us a good
19 perspective on the overall clean rad waste system which the
20 scram header vent lines and drain lines for each unit tie
21 into. It is an extensive system, and the portion shown in
22 yellow represents that portion with the clean rad waste
23 system that is manifold defense, to the secondary paths
24 into the same header line drain line that the scram
25 discharge system has.

1 It is basically laid out on four elevations, with
2 the reactor building equipment drain sump located in the
3 lower part of the reactor building, the bottom of that being
4 at elevation 509. If we worked backwards, it is a little
5 easier to follow. Starting down at the sump we have the
6 eight-inch drain line which exits approximately nine inches
7 under the minimum water level of the sump, so that is always
8 isolated from any other drains that exit to the sump by the
9 water that is contained in here.

10 This sump is vented through a heap of filter up
11 into the reactor building ventilation system. And if we
12 follow back up through this individual eight-inch line, the
13 first elevation at which it Christmas trees out is 565 floor
14 elevation, which you will recall is the elevation at which
15 the hydraulic control units and the scram discharge headers
16 are located.

17 On this floor there are 30-odd different stub-ups
18 going to various drains, and it is at this elevation where
19 we have the two vent lines or had two vent lines, and the
20 single drain line for each unit that ties into the system,
21 located here in red.

22 The system that is marked in yellow in its
23 entirety takes in approximately 65 to 70 total of different
24 drains. The majority of them are normally closed during
25 system operation. Maintenance valves are open to drain on a

1 particular line or a valve in a panel. A large number of
2 them are blanked off.

3 So for approximately 65 to 70 total different
4 stub-ups that go into the system, a large portion of them
5 should be no flow to this particular drain line. The line
6 continues running up through the 593, to the 621, and
7 through the 639 floor elevations, eventually at its high
8 point going up to drain the reactor building equipment and
9 fuel pool ventilation ducts. They are checked at that point
10 with a check valve located in the line that is set to
11 relieve equivalent pressure of five feet of water.

12 There are too many individual stub-ups in the
13 system to go over individually; however, on pages 7-A, 7-B
14 and 7-C of the handout are a tabulated accounting of each
15 stub-up. There are variations between the three units, so
16 they will be described as to which is effective for each
17 unit.

18 Does your handout include these red numbers on it?

19 MR. ZUDANS: Yes.

20 MR. RATHJEN: These numbers corresponded to the
21 left-hand margin of that tabulation, which will aid you in
22 the following of the handout. You can trace it out and
23 compare that tabulation to the schematics here.

24 In addition we have actual as-built drawings
25 showing floor-by-floor elevations in the planned view that

1 are included in your handout, and we will take a look at
2 those.

3 MR. ZUDANS: In this line, are there any valves on
4 this line at any location?

5 MR. RATHJEN: There are no valves in the drain
6 system. It is simply a piping system that will drain, in
7 some cases, a seal or an area here, a valve, or, for
8 example, if you have maintenance work to do on a header
9 panel and you want to isolate the drain at panel, then we
10 open that valve and let it drain into the drain system.
11 That would be under a downtime, not an operating
12 configuration.

13 MR. ZUDANS: And it drains by gravity completely.

14 MR. RATHJEN: Yes. Most system gravity feed
15 atmospheric pressure, which is the same for the control rod
16 drive scram discharge system. Under normal conditions it is
17 open to atmosphere. Only during scram conditions does it
18 close off and build up the discharge pressure.

19 This is a planned view of the 565 floor elevation,
20 which is showing unit 1 on this side, unit 2 and 3 on this
21 side. Since unit 2 and 3 are very close to the same, that
22 will suffice to show both configurations. Now we have one
23 for all four floor elevations, but typically we have a riser
24 coming up at this point from the reactor building sump. It
25 rises up to the 565 floor. These are on bedded piping runs.

1 They spread out in this configuration in this
2 particular case, for unit 3. This stub-up would be located
3 underneath the instrument volume tank that we looked at. It
4 would be the line that receives the drain portion of the
5 cycle. This would be the vent line connection for the west
6 side, the vent line connection for the east side.

7 I neglected to mention the graphic drain. The
8 total system from high point on the six-inch header system
9 to its connection on the instrument volume tank has a slope
10 of about 2-1/2 feet that would be six inches for the east
11 side. It decreases for the west side, and was verified right
12 after incident 2-B. Negative slope all of the way. No traps.
13 So it should properly drain.

14 MR. ETHERINGTON: That slope is on the drain
15 line. Does the six-inch header have any pitch?

16 MR. RATHJEN: That slope I addressed was on the
17 six-inch header, the high point of the six-inch headers,
18 through that two-inch line connecting it to the instrument
19 volume.

20 MR. ETHERINGTON: All right.

21 MR. EBERSOLE: Mr. Rathjen, this is a lot of
22 detail that you are going through here. Is it fair to say
23 that you have enhanced the venting by putting new vents in?
24 Although it is still not a safety degree function, you have
25 improved the venting system as an interim measure.

1 MR. RATHJEN: It is NRC's idea and it has been
2 approved.

3 MR. EBERSOLE: Anyway, you have done something to
4 it.

5 MR. RATHJEN: Yes.

6 MR. EBERSOLE: But it is still not a safety
7 function per se.

8 MR. RATHJEN: After this event it has no possible
9 component between it, nothing to fail, and that is going
10 directly to the atmosphere. It is a positive vent in that
11 sense. In that sense it is an improvement.

12 MR. EBERSOLE: It is unimpeded. Now, on the
13 drain, have you done anything to enhance the drain? You
14 know, you were going through a lot of things, but in the
15 long run, there really is not safety function per se. Is
16 that correct? You are counting on the instruments and the
17 dump volume to do whatever has to be done.

18 MR. RATHJEN: We have not modified the drain.

19 MR. EBERSOLE: So you really haven't improved the
20 drain, have you?

21 MR. RATHJEN: It has been tested extensively on
22 the run.

23 MR. EBERSOLE: In the long run you can fool with
24 the drains and the vents until something freezes over, but
25 you will still be dependent on the instrument and the

1 instrument dump tank to tell you and do the proper things in
2 time, whether you have 10,000 ways of doing what you are
3 doing.

4 MR. RATHJEN: Yes.

5 MR. EBERSOLE: Now, the crux of it is the
6 instrument dump volume doesn't tell you what is going on in
7 the main dump tank. It doesn't tell you that the water is
8 still in there. So I understand you have interim measures
9 to verify whether these are empty or full.

10 MR. RATHJEN: You are referring to the sump?

11 MR. EBERSOLE: No, I am talking about the main
12 dump, the two big headers.

13 MR. RATHJEN: The scram discharge.

14 MR. EBERSOLE: So the crux of it is you are
15 supposed to be at this time continuously monitoring -- is it
16 continuous or intermittently monitoring?

17 MR. RATHJEN: Continuously. It is a recorder.

18 MR. EBERSOLE: It is a recorder monitoring of some
19 state of the dump volumes.

20 MR. RATHJEN: Yes.

21 MR. EBERSOLE: What is it, ultrasonic?

22 MR. RATHJEN: It is ultrasonic.

23 MR. EBERSOLE: So you know on a continuous basis
24 whether there is water in it or not water in it.

25 MR. RATHJEN: Yes.

1 MR. EBERSOLE: No matter how you do all of these
2 things.

3 MR. RATHJEN: That is right.

4 MR. EBERSOLE: Is that right?

5 MR. RATHJEN: That is true.

6 MR. EBERSOLE: So that is your main current thrust
7 of safety.

8 MR. RATHJEN: That is what is in existence right
9 now, and we will address what we will do.

10 MR. EBERSOLE: Does that monitoring give you a
11 modified identification of how much water is in there or any
12 water at all or what?

13 MR. RATHJEN: Yes, it is accurate down to within
14 about a half-inch.

15 MR. EBERSOLE: So it is a good visual.

16 MR. RATHJEN: Past a half-inch we would get an
17 actual readout of what levels are in there.

18 MR. EBERSOLE: That is great.

19 MR. RATHJEN: We use that on several other forms
20 of testing.

21 MR. EBERSOLE: And someone is eyeballing that on a
22 chair or something all of the time? You don't have any
23 automatic function.

24 MR. RATHJEN: All these units are set up and there
25 is a recorder set up on each one. This man is making

1 continuous rounds taking readings.

2 MR. EBERSOLE: There is nothing enunciating any
3 change of volume at the moment. You are depending on the
4 personnel observation.

5 MR. RATHJEN: There is a local alarm, I believe.

6 MR. ABERCROMBIE: There is a local alarm.

7 MR. EBERSOLE: Where there is water in it?

8 MR. ABERCROMBIE: Yes, plus the recorder.

9 MR. EBERSOLE: Is anybody in there to listen to
10 the local sound?

11 MR. ABERCROMBIE: He usually makes his rounds
12 within 30 minutes.

13 MR. EBERSOLE: In a 30-minute interval, what is
14 the opportunity of filling that. Do you know?

15 MR. ABERCROMBIE: I think to actually fill that
16 volume in 30 minutes, I don't know what catastrophic failure
17 would have to occur. We have not identified any.

18 MR. EBERSOLE: Have you looked for the possible
19 ways to fill it within the 30-minute interval, like a broken
20 valve that you could not see on the drift?

21 MR. ABERCROMBIE: I think what we have learned
22 from General Electric about the flow rates on the failures
23 of, say, any seals or any scram valves, but that would not
24 by itself fill the lines.

25 MR. EBERSOLE: You pick the 30 minutes, then,

1 intentionally, to say that there is no mechanism that could
2 fill it in that interval, is that right?

3 MR. ABERCROMBIE: We thought that was a
4 conservative approach.

5 MR. EBERSOLE: You could have picked two hours or
6 ten minutes or one second, I don't know what. But there was
7 a conscientious examination of the modes of possible fill.
8 Ultimately they are going to be continuous.

9 MR. ABERCROMBIE: Yes.

10 MR. EBERSOLE: Right now we are riding on a --
11 thank you.

12 MR. ABERCROMBIE: But I would like to say that you
13 certainly identified what we consider the bottom line, and
14 that is that you have to know about water in the volume.
15 Everything else doesn't really matter.

16 MR. EBERSOLE: Everything else is really
17 gingerbread.

18 MR. ABERCROMBIE: Convenience.

19 MR. RATHJEN: I think I have about covered the
20 ground. I don't think there is much point in looking at the
21 other drawings in here. In your handout is simply the
22 floor-by-floor breakdown of the floor plan of the rest of
23 the drain system. I believe that is it.

24 Are there any further questions?

25 MR. ZUDANS: Would it be feasible to run a larger

1 than two-inch line from -- is it technically or practically
2 feasible to increase the size of two-inch drain line from
3 east and west side for the SDIV?

4 MR. RATHJEN: I believe so, and I believe that is
5 one of the considerations of doing that. There are a number
6 of different concepts.

7 MR. ZUDANS: We will wait.

8 MR. PLESSET: Why don't we go on, then.

9 MR. DOMER: Bert Morris is going to cover several
10 agenda items here in the event sequence itself, our
11 evaluations of why the event occurred, investigation items,
12 including the investigation, and he is going to cover
13 corrections that have been made today.

14 MR. MORRIS: My name is Bert Morris. I work out
15 of the Reactor Engineering Section of the system in
16 Chattanooga. I am basically going through the same general
17 program that G.E. has presented which concerns the sequence
18 of events. I understand some of you may already have seen
19 this presentation, so I may be repetitive to you.

20 I have some nice visual aids which are available
21 to you, and also their conclusions are basically the same as
22 our own.

23 On the early morning of June 28th, we were
24 shutting Browns Ferry 3 down for some maintenance. This is
25 normally -- on a manual shutdown like this, we ordinarily

1 run the recirculation valves back to a fairly low power
2 level and then insert some rods so that we manually scram.
3 We were preparing to manually scram the reactor. It is
4 pretty much a full power rod pattern.

5 We had inserted ten power rods to further reduce
6 the power level from the point that it was scrambling.

7 This next slide here shows the actual rod pattern
8 prior to that first scram. You can see there was a
9 substantial number of rods that were out. We had 185 rods
10 out at Browns Ferry. Of these, 157 rods were pulled out the
11 full way and we had 18 rods in intermediate positions.

12 Now, on this picture we also show the rod position
13 after that first scram, and we see that there was a
14 substantial number of rods on the east side which failed to
15 go full in. You will notice that every rod actually did
16 move some distance, but we went in and looked at the
17 individual rods and the distance that they went in, and we
18 tried to correlate it in certain ways so that we could
19 install the flow and unique piping configuration on the
20 header itself.

21 We were unable to really draw any kind of
22 conclusions on individual rods, with the exception of the
23 fact that the faster rods as measured from our own scram
24 timings --

25 MR. EBERSOLE: I think at this point in time I

1 would like to divert a little bit anyway. The operator on
2 the desk watching this must have had some kind of mental and
3 physical reactions which were extraordinary to see that the
4 rods were not in when he loaded the building.

5 MR. MORRIS: It is really not very difficult to
6 tell that. Ed was talking about the blue lights before.
7 Also with the rods when you have a scram you really don't
8 have a rod position indication as such. You have what is a
9 green background.

10 MR. EBERSOLE: But anyhow, he saw that he did not
11 get a scram. Do you have any kind of a record of his
12 physical reaction to this? Did he say to himself
13 consciously, should I trip the turbine, should I engage
14 bypass, should I execute pump trip? Does he, in fact, have
15 an ordered, deliberate procedure for this case?

16 MR. ABERCROMBIE: Does he now, or did he then?

17 MR. EBERSOLE: Did he then? I mean here is a case
18 where --

19 MR. ABERCROMBIE: No, there was nothing explicit
20 such as the procedures that we have in place now for any
21 event such as this.

22 MR. EBERSOLE: He did not get the signal for
23 automatic pump trip because he did not get a pressure
24 supply, so he surely did the right thing in not tripping the
25 turbine or asking anything to close steam flow. Otherwise,

1 it would have been quite different if he had stopped steam
2 flow, especially if the bypass stuck. But do you think he
3 consciously let steam flow continue, knowing that it was the
4 best thing to do?

5 MR. ABERCROMBIE: That is difficult for me to
6 really say.

7 MR. EBERSOLE: Okay. Was the turbine tripped
8 before the rods had all gone in?

9 MR. ABERCROMBIE: Yes, he tripped the turbine
10 shortly after that. The power levels that existed, he
11 cannot have maintained the turbine on. The bypass system
12 was functioning properly, and he knew he was --

13 MR. EBERSOLE: So he had bypass, so he tripped.

14 MR. ABERCROMBIE: Yes.

15 MR. MORRIS: In the part of the handout I have
16 given you, there was a test breakdown of the actual sequence
17 of things in a little bit more detail than what I have gone
18 through, so you might look through that in a little while.
19 Actually, following this initial scram there were several
20 operator actions and observations and whatever.

21 The operator actions here were routine things that
22 we normally do after a scram at Browns Ferry. Normally you
23 clear the Scram Discharge Volume, high level and bypass to
24 allow to reset that scram at your first opportunity. This
25 will override your high level scram on your discharge volume

1 instrument volume.

2 We took the reactor load switch which shut down,
3 which also initiates the scram itself if one had not already
4 occurred through your manual actions. Your low lying, low
5 level neutrons were on in. The operator observed up in the
6 blue lights on the control panel there all the scram valves
7 did indeed open. The accumulators discharged and the APRM
8 instruments or the gross power was all the way downscale.

9 Other than that other thing as far as pipe
10 configuration, everything seemed pretty normal.

11 MR. ZUDANS: You say that all accumulators
12 discharged?

13 MR. MORRIS: Yes, sir.

14 MR. ZUDANS: Without actually moving the rods in?

15 MR. MORRIS: All accumulators discharged.

16 There are a couple more significant points to
17 note. The scram level switches. This was determined in
18 subsequent determinations. High level picked up in 18
19 seconds compared to normal 40 to 50 seconds to load to pick
20 up those high level switches on the instrument volume, 40 to
21 50. That was a real consistent number, and it was
22 significant that we got that much water in the instrument
23 volume in such a hurry.

24 This display here is what the neutron
25 instrumentation, the LPRM readings and our power monitors

1 read following the first scram. Again, this would be your
2 east side of your core. You see comparison with CRDs, and
3 you can see that we had several low readings on the east
4 side and more of what would be the top in the reactor core.

5 Earlier we referred to the fact that the amount of
6 insertion on the individual rods was correlated against the
7 scram speed. As a visual representation of that, this is
8 the chart of how far, on the average, particular rods got
9 from the rods that were at full out to begin with, position
10 48 versus the scram insertion time that had been noted
11 previously as far as testing goes.

12 I see generally the rods with a faster scram
13 insertion time than they probably were before.

14 On scram number 2, the operator had reset the
15 scram on this time. Resetting the scram will allow the
16 drain valves and the vent valves on that scram discharge
17 system to come back open and you will commence draining the
18 instrument volume. There was about 100 seconds of drain
19 time between the first and the second scram. That is
20 between the time the operator reset the scram and initiated
21 the manual second scram.

22 Again, the observations were similar to the first
23 scram. All scram valves were indicated open by the blue
24 light. All accumulators discharged. All rods again moved
25 somewhat. There are still 59 rods partially out.

1 And here is the actual rod positions. You can see
2 they moved about five notches, on the average. Again,
3 particular rods moved farther than some others, and some
4 moved very little. The same scram speed correlation
5 approximately holds for the second and subsequent scrams as
6 well.

7 The operator basically repeated his actions
8 again. He was convinced that the scram was well under
9 control and was taking positive efforts to get the rest of
10 the rods in and reset the scram again between the second and
11 third scram, about 53 seconds of drain time, and initiated
12 another manual scram. Again the rods moved in in a small
13 way, about three or four notches this time, and we still got
14 46 total rods out.

15 MR. ETHERINGTON: Are those times consistent with
16 the estimated drain time? I mean does it assume the boiler
17 has drained away sufficiently to permit a second scram?

18 MR. MORRIS: We haven't calculated that
19 specifically. We did some approximations, and it seemed
20 like the total number of rods and notches that went in was
21 about proportional to the drain times between the successive
22 scrams.

23 MR. ETHERINGTON: About proportional, you said?

24 MR. MORRIS: Yes.

25 MR. EBERSOLE: In the meantime, the bypass system

1 was --

2 MR. MORRIS: The bypass and normal feedwater
3 system was maintained in normal conditions. It wasn't what
4 we would have seen that we had in the past.

5 On scram number four the operator allowed a little
6 more drain time this time between the third and fourth
7 scram, I think about 160 seconds. This time he did not
8 manually scram the reactor. He took his instrument volume
9 bypass switch out of bypass. There was apparently high
10 water still in the instrument volumes as we would expect,
11 and he got an autoscam after he took that bypass switch out
12 of bypass on his instrument volume.

13 This is roughly 14 minutes after the beginning of
14 the event. All rods went in, and what the operator
15 described as a normal scram.

16 MR. THEOFANUS: What is his part at this point?
17 He took the bypass off. Was he trying consciously to go in
18 it in some way and do something?

19 MR. MORRIS: I'm not sure that he was.

20 MR. ABERCROMBIE: I'm sorry. I did not get all of
21 the question.

22 MR. MORRIS: He is asking if the operator intended
23 to scram by moving this bypass switch. I don't believe it
24 probably was.

25 MR. THEOFANUS: Do you know what path he was on at

1 this point? Is it known now what he was trying to do at
2 this point? Presumably your down time -

3 MR. MORRIS: He pretty much knew what he was
4 trying to do. It would not have made any difference whether
5 he manually scrambled or tripped that bypass. The end result
6 would have been the same.

7 MR. ABERCROMBIE: It really was a deliberate
8 action. They knew that they had problems with water. That
9 was what they had assumed was stopping the rod movements.
10 In this case his enunciators told him that the scram
11 discharge volume had completely drained. Therefore, he went
12 to the normal position.

13 It was a deliberate act based on the indications
14 that he had at the time. And then, as we learned later,
15 there are a lot of things that are happening in that Scram
16 Discharge Volume as far as those level switches are
17 concerned, and he still had a high water level in there as
18 soon as he shut the valves, and he scrambled them right out.

19 MR. THEOFANUS: Let me ask the question another
20 way. I think you can help me with what you said, but one
21 more step. Had the scram not occurred at this point, the
22 automatic scram, what would be his next action?

23 MR. ABERCROMBIE: He was getting set up to do a
24 manual scram.

25 MR. THEOFANUS: That is all I wanted. Thank you.

1 MR. MORRIS: I guess he did manually scram it.

2 MR. ABERCROMBIE: Yes.

3 MR. MORRIS: All rods went in shortly thereafter.

4 MR. ZUDANS: You said that they knew the Scram
5 Discharge Volume was empty by instrument. There are no
6 instruments in the Scram Discharge Volume.

7 MR. ABERCROMBIE: Yes, on the instrument volume is
8 what he was looking at. All his indications told him the
9 instrument volume was drained, and he went normal.

10 MR. EBERSOLE: Let me ask a question. Mr.
11 Abercrombie, is there instilled in the operator a feeling, a
12 gut feeling or whatever you want to call it, that the worst
13 thing to do under the circumstances of any kind of stuck rod
14 incident is to turn off free flow of steam; that he is to do
15 everything in his power to keep free flow of steam moving to
16 avoid water collapse when he arrives up to the safety degree
17 pressure?

18 Is he trained to at all costs keep the turbine
19 rolling, keep the bypass open, keep the MSIVs open, keep the
20 steam moving, because if I don't move it, if I close it I am
21 going to have one collapse and a reactivity spike, which
22 would be hard to cope with?

23 MR. ABERCROMBIE: I think it is fair to say that
24 maintaining the heat safe under those conditions is
25 instilled.

1 MR. EBERSOLE: He is going to try to keep the
2 steam flow, and if he could, he would dearly love to bypass
3 MSIV, and he did flip to the -- let's say he was in the run
4 mode and he did the mode switch. He put it in what? He
5 went to -- what is the other?

6 MR. ABERCROMBIE: Shutdown.

7 MR. EBERSOLE: Now, that bypassed the whole steam
8 bypass of the MSIV, didn't it?

9 MR. ABERCROMBIE: Yes.

10 MR. EBERSOLE: That was good. As a matter of
11 fact, he dearly would love to prop open those MSIVs so they
12 would not close all of them.

13 MR. MORRIS: That is part of the reason we do move
14 that switch.

15 MR. EBERSOLE: I often thought that we ought to
16 have a hard iron bypass on that MSIV.

17 MR. ABERCROMBIE: There is many a time I wish we
18 had had it.

19 MR. EBERSOLE: Right.

20 MR. MORRIS: This is the scram that we liked real
21 well. This is self-evident what it will show. This is just
22 a quick summary of the drain times between scrams. I have
23 already given you these numbers. Again, I would like to say
24 that we did do a real simplistic correlation between drain
25 times and the total number of rods that were inserted on

1 such a scram, and they are proportional.

2 In your handout now you do have a little more
3 detailed sequence of events. I am not sure we really have
4 time to go through it. I just included it in there for your
5 inspection. You may scan it and pick out questions.

6 These are some of the inspections and checkouts
7 that we did immediately following the incident or shortly
8 thereafter. The hydraulic control units were moved out and
9 perhaps someone went down there and changed some valve lines
10 on each side. It takes you about three or four hours to do
11 something like that.

12 We sent operators and Ed Edmonson and his men down
13 there immediately, and he blocked the whole system on the
14 east side, verified all of the manual valves on individual
15 hydraulic control units, and indeed, they were in the
16 description. We had two or three people who were just to
17 make sure that those valves were indeed lined up right.

18 We went in and operated the drain vent valves.
19 From all indications, our operator observations -- or prior
20 to this event they had been trained, and all valves were
21 indeed open, and they were identified in the control room
22 with the lights up there. We went in and calibrated all of
23 the instrument volume switches. All 50-gallon scram
24 switches were successfully calibrated.

25 We had a little bit of trouble on 3 and 25-gallon

1 switches on the first time that they tried to calibrate
2 them. Calibration procedure was a little different than
3 what you normally expect in a scram. With the slow fill
4 time they can kind of look at some of the flow switches that
5 kept them from picking up on the first attempt to calibrate
6 them.

7 Operator did verify that the 3-gallon switch
8 picked up during the incident and the 25-gallon switch as a
9 computer point was verified to operate and picked up there,
10 and then during the first scram, and subsequently cleared at
11 the end of the whole event in the correct sequential order,
12 and apparently they are at the 50-gallon switches. So we
13 knew that those switches were working as well during the
14 entire time.

15 We went back through all of our control rod
16 maintenance malfunctions and modification activities for
17 either the past several months and the past couple of years
18 as far as modifications went. We did not see anything at
19 all that could affect what happened down there. We walked
20 down all of the air lines to the hydraulic control units and
21 the vent-in valves to see if maybe some unauthorized work
22 had gone on inadvertently or something like that that wasn't
23 controlled. Everything was certainly normal.

24 We pulled all of the CRD temperature logs, and
25 temperature logs will tell you sometimes if you have a

1 successive seal leakage on your CRDs. I think there were a
2 couple of them on the west side that were a little hotter
3 than normal. There were no hot lines at all found on the
4 east side.

5 We went in and made cuts on all of the vent lines,
6 the two-inch drain line, the scram headers themselves and
7 the instrument volume. We ran a boroscope in there to make
8 sure we had no obstruction in those lines. That is the
9 two-inch long line on the east side. It was cut and rodded
10 out, and then we looked through and nothing was found.

11 Possibly some big blockage in the sump lines,
12 drain lines was there. So we went down there and looked
13 around the sump for some large object, and nothing was found
14 down there.

15 Prior to starting back up on the unit 3, we went
16 through the exhaustive CRD test program. We did our
17 friction testing, which is essentially measuring the
18 differential pressure it takes to drive that rod in and out
19 of the core. You notice we measured the stall flow there.
20 The stall flow tells you the shape your seals are in, and
21 also the rod scram time. All these rods and everything were
22 just perfectly normal.

23 This indicates mechanical integrity of the rods
24 was not impaired in any way. We did some flow and drainage
25 tests on the unit 3 Scram Discharge System. We pumped a

1 bunch of water in there in variations of the drain times,
2 how they open and flow on east and west sides, and we had a
3 lot of things taken there, and we will talk about that a
4 little later.

5 Ed Edmonson there went in and did a series of
6 testing on the electrical portion of the reactor protection
7 system, and there was nothing wrong there either. The same
8 parallel path he took there. Their CRD hydraulic test
9 unit. They were proceeding on some confirmatory test. By
10 this time it was pretty much decided that there was water in
11 that header which gave us the problem, and we wanted him to
12 go in and put some water in there and have a test modeled
13 out there and demonstrate. A test setup will act the same
14 way as what our rods did.

15

16

17

18

19

20

21

22

23

24

25

1 MR. MORRIS: We were sure there was water in that
2 volume which gave us the problem.

3 The second point here is, I guess you would say,
4 whether, if you had money or something you could bet on, but
5 there was a restriction -- and that six-inch header comes
6 into the two-inch drain line -- in that scum line there was
7 a restriction of some sort in that two-inch wraparound line
8 on the east side of the CRD models.

9 However, our subsequent testing indicated that the
10 vent system sort of impedes your drainage from those
11 headers, so we cannot -- we can say that the vent did
12 contribute to the incident.

13 MR. EBERSOLE: I can't help but look at that slide
14 again and notice that our problem is a common one to the
15 sewage plumbing industry. So I suggest you invoke the
16 plumbers in the future investigations. That is all it is.

17 MR. MORRIS: We considered a number of causes, and
18 I think we have already addressed some of these that I just
19 went through there. We went down and sat down and think of
20 all of the things possible that could cause the problem and
21 just either eliminate them in a methodical manner or
22 suggestions maybe that are plausible. And these are some of
23 the basic causes that one might hypothesize to give you
24 problem.

25 One is certainly electrical reactor protection

1 system logic, valve line on the hydraulic flow unit or some
2 total malfunction in the hydraulic control unit that would
3 give a problem. And the mechanical problem on drive system
4 itself would postulate it perhaps. The instrument volume is
5 plugged up and none of the drain switches were a problem
6 with the scram discharge problem proper.

7 I said that during the same period of time GE was
8 supporting us in San Jose, both analytically and with some
9 test work that they were doing.

10 Let us look through some of the causes that we
11 considered. First is electrical, and ended with that with a
12 bunch of the reactor protection system logic. I think Ed
13 Edmundson went through a pretty good discussion of why we
14 don't think that is a problem. In fact, the operators
15 always had blue lights which were indicative of the scram
16 valves actually moving to the scram position. Also, all of
17 the rods moved every time, which would be the logical if the
18 scram signal wasn't going. The post-test that they ran
19 showed that the logic wasn't working like it was supposed.

20 The hydraulic control unit. Checked all of the
21 valves. The accumulators all worked like they were supposed
22 to. A good indication of scram valve positions in the
23 control room. The air system looked like it was working
24 fine. The testing on the modules that we did, scram
25 testing, all such vents looked all fine. Maintenance looked

1 good. I think it would have been a problem in the hydraulic
2 inspection, but it was inspected, and probably on the west
3 bank drives as well. They all responded.

4 Control rod drive -- I guess the best thing you
5 can say there is that we went back in and mechanically
6 tested all of the east side drives after the event and
7 nothing looked wrong at all.

8 There seemed to be a lot of interest in the
9 possibility of the instrument volume somehow plugged up and
10 all of this for some reason. The level switches did not
11 work. I think the path problems of the various plants with
12 those level switches at one time or another -- we don't
13 think this is the case because we would not preferentially
14 bother the east side rods which affect both banks. And if
15 that were the case, from all the data that we have all of
16 the switches worked in the proper sequence during the entire
17 event.

18 This sort of leads you down to the problem out in
19 that discharge volume, particularly the east side. I say
20 again it is sort of significant that the scram level
21 switches tripped in 18 seconds. As I said before, the 40 to
22 50 seconds was a real number. We went back for many
23 scrams. Unit 3 hadn't scrambled within the last three
24 weeks. We went back to auto scram in the system, and
25 somehow we got that volume in 18 seconds. We just believe

1 there was a lot of water out there to begin with.

2 MR. PLESSET: Do you have any speculation as to
3 why there was such differences between the degree of
4 insertion and the various rods? Some of them went in much
5 further than others?

6 MR. MORRIS: The only thing that we have been able
7 to show there is at the scram speed. That is what we
8 expectd, faster rods to go in further.

9 MR. ABERCROMBIE: We went back, and Unit 3 had
10 usually come out of a refueling out. We went back and got
11 the scram times, and I think he pretty closely correlated
12 that the rods that were the fastest on scrambling in were the
13 ones that went in the furtherest.

14 MR. PLESSET: So it did correlate?

15 MR. ABERCROMBIE: Yes.

16 MR. MORRIS: We showed the figure earlier in the
17 handout which shows this.

18 MR. WU: Why is there such a drastic difference
19 between the east and the west banks if they are
20 differentially one side -- why the two sides are so
21 drastically different?

22 MR. MORRIS: I am not sure I know what you are
23 asking.

24 MR. WU: I understand that there is some
25 difference there.

1 MR. ABERCROMBIE: In the drain time?

2 MR. WU: Well, I was referring to the east bank
3 and the west bank. If the west bank scrams were normal and
4 the east bank, the distribution of them in the insertion
5 time.

6 MR. MORRIS: Are you looking at the figures? Is
7 that why you are asking the question? The west bank problem
8 is not the same distribution scram times. That distribution
9 is pretty much -- that is distributed on both sides.

10 MR. ABERCROMBIE: We do not believe there was any
11 water in the west header at all. We believe only that the
12 east header had water in it.

13 MR. EBERSOLE: At this time you think that it may
14 be either due to the improper venting or the flow
15 restriction in the long pipe, is that right?

16 MR. ABERCROMBIE: Yes. I wish I knew really what
17 caused it.

18 MR. EBERSOLE: One other parameter that can cause
19 it, if you can dream it up, it is pressure, even though it
20 is drive pressure in that header. Is there any possible way
21 that you can get drive pressure from some unexplained source
22 in that?

23 MR. ABERCROMBIE: I sure don't know of any.

24 MR. ZUDANS: I have another question. You
25 mentioned that scram switches drift in 18 seconds instead of

1 the normal 40 to 50. That kind of contradicts or indicates
2 that you had some water sitting in the SDIV already.

3 MR. MORRIS: Not necessarily. It was in the
4 volume force, not volume pressurizes. You can force a lot
5 of water through that two-inch line in a hurry.

6 MR. ZUDANS: Was it meant to force the water out
7 of the SDV on the west side because it was a short piece of
8 pipe, but did manage to force out the east side?

9 MR. MORRIS: What you are saying is true, that
10 water was in the east side. That would have to come from
11 the east side. I imagine though you have a significant
12 volume of water sitting already. Essentially you are trying
13 to shove a whole bunch of more water up there at
14 considerable pressure.

15 It certainly pressurizes that east side in a hurry
16 and forces a lot of water over there to push on that.
17 Rather in this case, it was just a predrain system like a
18 normal pressurized or pumping that water over into the east
19 bank.

20 Essentially the drain valves would go slower than
21 the vent valves.

22 MR. PLESSET: Let me see if I understand. You
23 have tested the insertion rate on individual rods
24 separately. Do they vary all that much, and if they did why
25 would that be?

1 MR. ABERCROMBIE: There are variations in the
2 scram timing. I don't recall the data and we have, I guess,
3 sort of an onload on the tech specs that the rods have to
4 insert at a certain time. There are rods that because of
5 seal conditions go in faster than others.

6 MR. PLESSET: So it is just variations in the way
7 that the seals have --

8 MR. ABERCROMBIE: Yes.

9 MR. MORRIS: They may vary two seconds or three
10 seconds from --

11 MR. PLESSET: There's not that much seals.

12 MR. MORRIS: Like I said, it was seals, there is a
13 certain amount of friction that your rod receives when it
14 goes into the core unit due to the particular channels and
15 things like that.

16 MR. EBERSOLE: When the nitrogen and accumulators
17 individually bottom out how much pressure is left in them,
18 500 pounds?

19 MR. EDMUNSON: 560.

20 MR. EBERSOLE: Do they have diaphragms to keep
21 them in?

22 MR. EDMUNSON: Yes. It is a piston.

23 MR. EBERSOLE: There is no diaphragm seal between
24 the water and the nitrogen?

25 MR. EDMUNSON: You are asking if there are seals?

1 MR. EBERSOLE: Is there a nitrogen bladder in the
2 bottom of that?

3 MR. EDMUNSON: Not a bladder, no. There is a
4 double over-ring seal piston.

5 MR. EBERSOLE: And when it bottoms out it is at
6 500 pounds, right?

7 MR. ABERCROMBIE: In that, yes.

8 MR. EBERSOLE: If you had boiled over, would that
9 nitrogen have proceeded into the dump tank because the dump
10 tank pressure is a lot less than that?

11 MR. ABERCROMBIE: Yes. We looked at that a
12 possible mechanism too, but when you look at it, you have
13 nitrogen in the volume, it is going to evacuate just like
14 air.

15 MR. EBERSOLE: Yes, except that it will take a
16 while.

17 MR. ABERCROMBIE: Also, preferentially, water will
18 leak into the accumulator because the choice of water
19 pressure is higher.

20 MR. EBERSOLE: That is before you scram?

21 MR. ABERCROMBIE: Yes, before we scram. I am
22 saying that that system basically tells us that the seal is
23 intact before the scram and there should not be a mechanism
24 that would cause the seal to just catastrophically fail.

25 MR. EBERSOLE: You mean as it discharges nitrogen

1 you say you don't allow for seals failing at that time and
2 allowing the nitrogen in the accumulator to go into the dump
3 volume?

4 MR. ABERCROMBIE: Let me see. Monty, you are
5 still -- the accumulator pressure, the nitrogen pressure
6 will still be lower than the reactor pressure.

7 MR. EBERSOLE: I know, but it is higher than dump
8 volume prior by a long sum.

9 MR. ROSS: We can show that during the subsequent
10 scram actuation the control room panel lights show that the
11 accumulators all recharged. It shows that --

12 MR. EBERSOLE: They all recharge?

13 MR. ROSS: Yes. It wasn't a seal failure.

14 MR. EBERSOLE: I see.

15 MR. CATTON: If you had your option, after looking
16 at all of this, what kind of a diagnostic system would have
17 been helpful?

18 MR. MORRIS: I did not hear the question.

19 MR. CATTON: What diagnostics would have been
20 helpful?

21 MR. PLESSET: That he did not have?

22 MR. CATTON: That the operator did not have. What
23 would be helpful for him to look at?

24 MR. MORRIS: Dump volume pressure would not have
25 told you anything because it was draining into the

1 atmosphere.

2 MR. EBERSOLE: I am talking about after dumping.

3 MR. CATTON: Let me broaden it then. Before,
4 during and after.

5 MR. MORRIS: The dump volume pressure will tell
6 you that your volume pressurized a lot sooner, and the
7 operator might see that. I don't know.

8 MR. ZUDANS: I still am puzzled a little bit with
9 this 18 seconds versus the 40 to 50 seconds. I wonder if
10 that is clear in your own mind why that happened. Where did
11 that water come from? Was it being held in the SDIV, or was
12 it pushed out of SDV, and if so where would that water come
13 from? Because obviously if it tripped in 18 seconds, if it
14 tripped the scram signal, that means that means that it
15 filled something like 50 gallons.

16 MR. MORRIS: We have some data here that may
17 explain the question for you.

18 MR. ABERCRCMBIE: Well, one thing, GE, I think
19 they have the data that they received from, I believe,
20 Brunswick, where they did install some transducers on a
21 scram discharge volume to see what the pressure transient
22 looked like from the volume. But if you assume you start
23 with an empty volume it takes a definite period of time for
24 that volume to fill and come up to reactor pressure. If you
25 assume that the volume is 90 percent full when you start the

1 scram, then it comes to the reactor pressure much, much
2 faster, which gives you the delta-P to force the water on
3 through the two-inch line into the volume, into the scram
4 discharge instrument volume.

5 MR. EBERSOLE: Well, at this nitrogen seal I am
6 going to hypothesize when it went on the upstroke and you
7 release the residual 500 pounds into the dump volume, it
8 would assist in pressurizing that, wouldn't it?a

9 MR. MORRIS: It would come down to the bottom of
10 the piston.

11 MR. EBERSOLE: It would assist in pressurizing the
12 dump tank.

13 MR. ABERCROMBIE: Yes.

14 MR. EBERSOLE: And that can be compounding the
15 problem of the pressure. Is your new canning system for the
16 water inventory, has it been tested against several scrams
17 so you can see -- do you have a signature, I guess you would
18 call it?

19 MR. ABERCROMBIE: Yes. We have looked at some
20 scrams with that installed, and it is evident what is
21 happening. You can see the west volume drain, then you can
22 see the east volume drain.

23 MR. EBERSOLE: You were getting a real picture?

24 MR. ABERCROMBIE: Yes.

25 MR. PLESSET: You wanted to make a comment? The

1 man from GE. Did you want to make a comment?

2 MR. ROSS: Yes. As to if the seals did leak again
3 and you are delivering even at that nitrogen to the bottom
4 side of the dry piston, and as I described yesterday, the
5 flow path of the bottom side of the piston isn't up past the
6 drive piston seal, it is up to like the normal cooling water
7 flow path which is on the outside of the drive. So it
8 preferentially enters the vessel, not deliver itself back to
9 the scram discharge volume. And even if it did it is just
10 adding volume in that flow, whether it is compressable air
11 or whether it is the water that normally flows that way. It
12 is not going to add significant amounts of some matter that
13 is going to cause a different signature and pressure.

14 MR. EBERSOLE: It is typical past the low pressure.

15 MR. ROSS: Excuse me.

16 MR. EBERSOLE: Will it tend to go past the outside
17 then?

18 MR. ROSS: Right.

19 MR. CATTON: What maintenance are there for the
20 nitrogen volume? Do you check the pressure? Do you check
21 for water leakage periodically so that you can drain water
22 from the nitrogen space?

23 MR. ABERCROMBIE: Yes. It has an alarm device.
24 It would tell us if we had any water leakage into the
25 nitrogen side.

1 MR. CATTON: Your comment about the nitrogen is
2 really not true. When you push water through the system,
3 the water is constant volume pretty much, both high pressure
4 and low pressure. When you push that nitrogen from 500 psi
5 into the SDV it is at roughly atmospheric pressure, and you
6 have got a heck of a lot more volume to push out of the
7 system. So it would not act the same. As a matter of fact,
8 it would be significantly different.

9 MR. ROSS: I guess I am not understanding you.

10 MR. CATTON: You are decreasing the pressure on
11 the nitrogen by maybe ten atmospheres. All other things
12 being the same, that means the volume is ten times greater
13 that you have got to push out through that two-inch line;
14 whereas, the water, the volume expansion would be small.

15 MR. PLESSET: Let us let him think a minute. Do
16 you want to respond to that?

17 MR. ROSS: Yes, I would like to respond if I
18 understand it.

19 MR. PLESSET: What he is pointing out is that the
20 nitrogen in that chamber is at very high pressure, and it
21 goes into a low pressure region and expands. The pressure
22 is down by tens, and it expands by ten times the volume.
23 That is his point.

24 So it might have a bigger vent in that low
25 pressure region, isn't that right?

1 MR. CATTON: His response to Jesse is that the
2 nitrogen doesn't matter.

3 MR. PLESSET: While they are conferring on that
4 point, can somebody tell us whether there is any evidence of
5 deterioration in the seals?

6 MR. MORRIS: I am happy to. I have had a
7 substantial number of seal failures, and your enunciation
8 there will tell you if you have a seal failure, if you are
9 leaking with the water.

10 MR. PLESSET: That would tell you the state of the
11 seal.

12 MR. EBERSOLE: You mean after you pressurize you
13 would see water.

14 MR. MORRIS: If in fact we did pressurize and
15 there was water.

16 MR. EBERSOLE: You now have a record that they did
17 not fail, these seals?

18 MR. MORRIS: Well, they were recharged, and there
19 was no indication of water.

20 MR. EBERSOLE: Anyway if that did occur, would one
21 accumulator bled down through your atmospheric 500 psi
22 represent a substantial fill problem in the -- I mean
23 since --

24 MR. PLESSET: They are working on that.

25 MR. CATTON: I still don't think I understood your

1 answer about diagnostics. Did you indicate that you felt
2 that there were no further diagnostics that would be needed?

3 MR. ABERCROMBIE: As far as diagnostics are
4 concerned, the best thing that we could have was an
5 indication that the volume was empty before we ever
6 started. That was the best thing that we could have.

7 MR. EBERSOLE: And unpressurize?

8 MR. ABERCROMBIE: Yes.

9 MR. CATTON: So maybe pressure and your ultrasonic
10 device would be a complete set of instrumentation?

11 MR. ABERCROMBIE: I think a level indication -- I
12 don't know about the pressure. I really haven't thought
13 that much about it. I am sure that will be discussed when
14 we talk about modifications.

15 MR. PLESSET: Why don't let him finish his
16 presentation? Are you almost finished? Is that right?

17 We will let them interrupt them when they come
18 back with their answer.

19 MR. MORRIS: We are just discussing some of the
20 inspections that we did on the east volume proper Ed
21 Edmunson has already discussed. We inspected the six-inch
22 headers, the two-inch headers. We inspected the six-inch
23 and two-inch headers and looked at the instrument volume,
24 looked in through the drains and verified that the vent
25 lines were not obstructed.

1 We went out and transited the whole system,
2 benchmarked the reactor building and transited in all of the
3 slope and elevations on the drainage lines and found that it
4 was a positive -- or actually a negative slope, I guess you
5 would say, all the way from the headers to the instrument
6 volumes.

7 Here is some of the data that GE provided for us
8 that they got on their testing down in San Jose, and this
9 figure has the scram volume pressurization, essentially the
10 rate there, plotted against what one would assume for a seal
11 leakage versus a turbine shear or the volume in their test
12 rates that were available for the scram discharge into.

13 In other words, I think 3.3 gallons is the nominal
14 volume allowed for a particular drive in the scram discharge
15 volume and have it available to it to discharge into. So on
16 185, roughly three times 185 on Browns Ferry, this shows
17 that as you start limiting the volume available to you in
18 that scram discharge volume pressurization it works very
19 fast.

20 MR. CATTON: Is this time to pressurize the
21 reactor pressure?

22 MR. MORRIS: I think so. It is very close, but
23 not exactly that.

24 MR. EBERSOLE: 1530?

25 MR. MORRIS: Here is a couple of points that is

1 not quite clear on the graph there. With the available
2 volume even less, you see the pressurization rate is very,
3 very fast there. They get those on the chart there on those
4 points.

5 MR. ABERCROMBIE: That particular chart I think GE
6 was using to indicate that we were about 90 percent full on
7 that volume.

8 MR. MORRIS: I think this shows, this slide here
9 shows that same thing. It says time after the strike --

10 MR. PLESSET: Will you explain that statement? I
11 did not quite follow you. You say they used this data to
12 indicate that the SDV was 90 percent full about?

13 MR. ABERCROMBIE: In trying to reconstruct the
14 event, you said, well, I have water in there. Well, how
15 much did I have? And maybe somehow that will lead you to
16 the source. And when GE ran through the testing that they
17 did in San Jose and came up with these curves, I think
18 everything that we saw kept coming back to that volume, of
19 which was about 90 percent on the east side, before the
20 scram.

21 MR. MORRIS: Also, this graph shows the normally
22 expected scram time to be roughly three seconds on the scram
23 time. So even a substantial volume, at least in that
24 volume, immediately available for the scram, was finally
25 pressurized.

1 MR. EBERSOLE: It comes to my mind here that just
2 that curve doesn't throw it away. It has some important
3 implications. Will you put it back up again?

4 Notice the variation in the three curves on the
5 volume. About how fast it can possibly scram. And then the
6 next curve was a -- well, let me ask you this: if I scram
7 and I have a gross seal failure on one rod and in the course
8 of scrambling, I will now have extraordinary backfill out of
9 the reactor system, right? On the halfstroke, after the
10 accumulators have done their thing, and you are really
11 scrambling. Is that going to prefill the dump volume?

12 MR. ABERCROMBIE: Monty?

13 MR. EBERSOLE: I have a gross seal failure on the
14 rods between the piston and the reactor vessels to
15 contribute to abnormally fast dump volume fill. Is that a
16 mechanism by which you can prematurely fill the volume?

17 MR. ROSS: No. Remember again that the sizing of
18 the scram discharge volume is based on worst case seal
19 leakage rate.

20 MR. EBERSOLE: But that is a design seal related
21 to leakage. I am going to take a catastrophic seal failure.

22 MR. ROSS: The design base is the number 10 GPM,
23 is determined where we move the seals from the stop piston
24 to pilot piston.

25 MR. EBERSOLE: So it is a catastrophic failure?

1 MR. ROSS: The seals will crack, the seals will
2 degrade and the seals will not be removed.

3 MR. EBERSOLE: Can I devise any mechanical way,
4 such as coupling reactor pressure to the dump volume on a
5 mechanical failure before I have rod insertion?

6 MR. ROSS: The coupling is through the drives, and
7 we limit the flow by the inherent restriction on the drive.

8 MR. EBERSOLE: If I break a drive or a piston.

9 MR. ROSS: If you break a drive or piston?

10 MR. EBERSOLE: Yes. Or piston rod, I should say.

11 MR. ROSS: Again, the seals are going to remain
12 there, although you might separate a portion of the shaft
13 itself. And the flow path is from the vessel to pass all of
14 the seals.

15 MR. EBERSOLE: All right. I am just trying to
16 visualize inadvertent coupling of a reactor pressure system
17 to the dump volume prematurely.

18 MR. ROSS: We will address that in a moment.

19 MR. MORRIS: As I understand also, Monty, the
20 volume at Browns Ferry is set for 10 GPM times 185 rods.

21 MR. RATHJEN: 10 GPM for 10 seconds.

22 MR. MORRIS: I thought times the total number of
23 rods.

24 MR. ZUDANS: That is what I was going to ask. The
25 GPM indicated here are per rod, but the times, assuming the

1 same condition for all rods.

2 MR. MORRIS: This is for an individual rod. The
3 design basis is carried over for the 185 rods.

4 MR. ZUDANS: In other words, you have 1,850
5 gallons per minute total flow when you indicate the intent?

6 MR. MORRIS: Of allowed volume for the rod
7 construction.

8 MR. EBERSOLE: I am going to just mention
9 something. You haven't had a scram for some time. Where
10 would that water come from that you think was in the dump?

11 MR. ABERCROMBIE: I wish I knew. We just did not
12 come to any conclusions of any source.

13 MR. EBERSOLE: You don't know where that water
14 came from? But it had to come from someplace.

15 MR. ABERCROMBIE: If it did remain there from the
16 last scram, then that lends some credibility for some
17 blockage in that two-inch line. And then we developed, or
18 directed pressure in that volume, very quickly on that scram
19 on the 28th, it dislodged what ever was in there.

20 MR. EBERSOLE: Where does GE think that water came
21 from that was there?

22 MR. ROSS: You can postulate that many ways the
23 water gets there. On a probabilistic basis, I think that
24 the probability that the water enters the scram discharge
25 volume 1 was leakage.

1 MR. EBERSOLE: It is supposed to get out of there
2 at a reasonable rate. But this time it didn't get out?

3 MR. ROSS: Yes.

4 MR. CATTON: Could the drain valve be closing and
5 you don't know it, or the vent valve had been closed?

6 MR. ROSS: Even if the water at the bottom.

7 MR. CATTON: How long before was the previous
8 scram? There was a number of days, wasn't it?

9 MR. ABERCROMBIE: Three weeks.

10 MR. CATTON: Three weeks. Even if the vent valve
11 was closed it probably would have drained?

12 MR. EBERSOLE: Well, I hope so.

13 MR. ABERCROMBIE: The test data of the drain time
14 showed that the east volume had restabilized at about a half
15 a GPM drain rate. So if you assume that with the vent
16 completely closed and you stabilized, then if you had
17 something that is slightly over a half a GPM coming in
18 there, you would have never drained completely.

19 MR. CATTON: Is half a GPM an unreasonable leak
20 rate into that SDV on the east side?

21 MR. ABERCROMBIE: I don't think so. That is not
22 an unreasonable number.

23 MR. PLESSET: Let us go on.

24 MR. MORRIS: This figure shows essentially the
25 same thing. It is a level in here. This shows for the

1 various fill volumes in the scram discharge header what your
2 pressurization rate would be. It is significant here to
3 note that your pressurization rate could occur within the
4 timeframe of your scram stroke.

5 I think it was about 90 percent flow.

6 MR. EBERSOLE: If you thought you had vented, but
7 you had not vented because the vent valve had stuck, would
8 that by negative pressure affect -- hold that water up in
9 there for an indefinite period?

10 MR. MORRIS: You said before it will drain but
11 very slowly.

12 MR. ABERCROMBIE: We did in that test we ran. The
13 east header stabilized at about a half a GPM drain.

14 MR. EBERSOLE: I am talking about with the vent
15 closed.

16 MR. ABERCROMBIE: That is what I am talking about.

17 MR. EBERSOLE: And trying to drain?

18 MR. ABERCROMBIE: Yes. We closed the vent to
19 determine whether or not we would drain eventually.

20 MR. EBERSOLE: At a half a GPM. Thank you.

21 MR. MORRIS: GE also did some calculations for us
22 showing the fill times on the instrument volume. On this
23 particular curve, what you would normally see, it shows that
24 it normally would be about typical of what we see on
25 records, about 50 seconds to pick up those 50-gallon

1 switches. And they contrasted this particular figure.
2 Maybe you will be able to read this better.

3 GE did some similar calculations, assuming that
4 that east header was full of water and tried to calculate
5 the hydraulic -- how long it would take to put that
6 instrument up. I think this will answer your question.

7 MR. CATTON: Yes, but I just want to finish up the
8 previous line of questioning. You measure the leak rate
9 into the SDV, don't you, as a standard maintenance type
10 procedure?

11 MR. ABERCROMBIE: No, that is not a standard
12 thing, although we did do it as a part of the Unit 3
13 startup. We actually had different plateaus of pressure.
14 Close the drain valves and then determine whether or not we
15 had enough inflow to eventually bring in the three-gallon
16 alarm. We measured the level after an hour at that plateau
17 with ultrasonics and established the leak rate.

18 MR. CATTON: What was it?

19 MR. ABERCROMBIE: .03 GPM. It was very, very
20 low. We never did get the three-gallon alarm after one hour
21 even at full reactor pressure.

22 MR. CATTON: So you have no idea what the leak
23 rate is now, or whether or not it could explain that water
24 being there?

25 MR. MORRIS: There was no water.

1 MR. ABERCROMBIE: No, there was no water in the
2 volume then.

3 MR. CATTON: But you don't know what your leak
4 rate is either?

5 MR. ABERCROMBIE: That is true.

6 MR. MORRIS: Here are some of the various sources
7 of water that we might postulate would get into the system.
8 I am going to talk about the outlet scram valve. Already,
9 normally, if your valve is leaking to any extent at all -- I
10 am saying leakage normally. If the outlet scram valves are
11 leaking to any extent at all, you are going to end up with a
12 hot rod. We did check the CRD temperature logs prior to
13 venting and there were none.

14 As Herb was just saying, after we restarted at
15 Browns Ferry 3, we indeed checked the leakage into the
16 system by closing the drain valve and roughly, in intervals
17 of 200 psi, and then pressurization after, on restart, after
18 they have vented. I think it was something there like two
19 gallons per hour, was the leakage into the system.

20 MR. CATTON: That is at present?

21 MR. MORRIS: That was after the restart. I don't
22 know what it is right now.

23 MR. ABERCROMBIE: The only way we have to
24 determine if there is any substantial leakage into the
25 volume would be by indications on the control rod, the hot

1 rod. But we have no established method of determining at
2 any period what that end leakage is to all of the rods.

3 MR. CATTON: In other words, you just can't close
4 that drain and measure --

5 MR. ABERCROMBIE: We could.

6 MR. CATTON: You have two levels?

7 MR. ABERCROMBIE: Yes. We could. But I am saying
8 that right now we do not have --

9 MR. CATTON: Do you think it would be worthwhile
10 to do that?

11 MR. ABERCROMBIE: I really don't, you know to me
12 you still go back to the bottom line is ensuring that the
13 volume is empty when you need it.

14 MR. CATTON: I would agree with that.

15 MR. ABERCROMBIE: Knowing what the total leakage
16 is into the system really doesn't do you any good. The only
17 thing that will do you any good is if you have a rod that is
18 giving you trouble. You need to know that so you can
19 replace the rod.

20 MR. CATTON: I would agree with that. I also
21 would have thought that people would calculate things like
22 time to drain too and find that they didn't. That is why I
23 ask the question.

24 MR. MORRIS: One could postulate that upon
25 previous scrams we had those levels never came out. We had

1 blockage in the drain line, created the activity, and you
2 would not know about it. And then the vent was closed off
3 and you had substantial leakage, a half gallon a minute.
4 Essentially, you would say that you had volume in that
5 header. I believe a half gallon of that would be a pretty
6 substantial leakage into that.

7 It would be pretty unusual, I think, to have that
8 much scram valves that is going to get you that kind of
9 number.

10 The introduction of water from the vent drain
11 systems, we discuss those together basically, since they
12 both tie into the same system.

13 As I said, that is a free drainage system that
14 doesn't really look like much of a path for water to come
15 down that or to get back up into the scram system itself.

16 The flow rates in the system are not very large.
17 We did check the sump activity prior to the period,
18 initially, through the Browns Ferry 3 event, and the sump
19 level, which would indicate how much safe flow you have
20 going into the system. It was not any greater than usual.

21 Just graphically, or elevation-wise, it was very
22 difficult to postulate getting water back into that system
23 from that drainage bed. Then getting your instrument
24 volume, picking it up, the instrument switches are somehow
25 running it uphill into the vent system.

1 We don't think we picked up water from that
2 drainage system. Someone else will talk about some
3 modifications and try to improve that system to make sure
4 that we sort of discharge the scram discharge system to some
5 extent, flushing connections. They are all used during
6 outages, and we put hoses on them and then run water through
7 them to the discharge headers to wash out some of the
8 contamination. And they are normally not connected nor were
9 they at the time.

10 MR. CATTON: What is your best guess?

11 MR. MORRIS: To that vent I bet on blockage. I
12 can't tell you.

13 MR. ZUDANS: Even if you are blocked you would
14 have to get water from someplace.

15 MR. MORRIS: Blockage, like I say, you can
16 postulate. I am sure there is some leakage past the scram
17 discharge valve, even though it is a small amount. And over
18 a long period of time, say three weeks, you could probably
19 fill that volume.

20 MR. ZUDANS: But with a half a gallon discharge
21 from the SDIV --

22 MR. CATTON: That is gravity, not blockage,
23 gravity without a vent.

24 MR. ZUDANS: I understand.

25 MR. EBERSOLE: I have a picture here in my hand,

1 and following up GE's observation about no leakage paths, I
2 can easily with this picture envision a trap as a sleeve
3 that will give me prodigious flows to fill the dump volume
4 at the precise time I need to scram.

5 MR. WIESENBURG: What we are going to do here is
6 Mr. Ross has a slide, a picture that you have in your hand --

7 MR. EBERSOLE: I am just thinking of it
8 mechanically.

9 MR. WIESENBURG: Mr. Morris is done that. Mr.
10 Ross will cover that.

11 MR. MORRIS: Here is a summary of some of the flow
12 testing at Unit 3.

13 MR. ABERCROMBIE: Can I go back just a moment?
14 One thing that, one possible source of water on those flush
15 connections, and I don't know if you really notice those,
16 but when we put those flush connections on, they were
17 intended to be used during shutdown and they did require an
18 external source of water to them and some valves if you like
19 to open them up. But as best we can determine there were no
20 hoses or were no -- there was no flushing at all going on at
21 that time. But that was a potential source of water.

22 MR. MORRIS: This is a summary of some of the
23 drain testing we did on the Browns Ferry 3. We actually
24 brought water into the flushing mechanism, and we actually
25 filled the whole system solid, and there is some variations

1 of drain times of the vents, open and closed. The data
2 presented here is the drain times of the system, with both
3 the drains open. It shows you west side, the short side,
4 drained considerably faster than the east side.

5 Again, what you mentioned, after the west sides
6 drains down, I believe this instrument, the level switch
7 indication, the east side still has another 15 minutes of
8 drain time associated with it.

9 MR. CATTON: Yesterday we discussed a little bit
10 the interface between the NSSS vendor and the A&E. And you
11 are on the A&E. Maybe I can ask you the question. Who is
12 responsible for making those kinds of calculations for a
13 system when it is to be installed, or does anybody make
14 those kinds of calculations?

15 MR. ABERCROMBIE: Monty might be able to address
16 that because GE did make a change in the volume required in
17 the early 1970's.

18 MR. CATTON: But I am referring to these -- he
19 built the hydraulic instrument, and yet it seems to me that
20 the calculations to check out the instrument were much less
21 -- pre-op testing was never done.

22

23

24

25

1 MR. ABERCROMBIE: There was a test, obtained
2 during the pre-op testing, based on scram and when the
3 high-level alarm cleared, when it came in.

4 MR. CATTON: Then the pre-op testing was
5 incomplete. If you look at this diagram and you consider
6 the drain time of the instrument volume, the drain time of
7 the the east header, your instrument is not telling you at
8 all what is going on in the east header.

9 Now, those are very simple calculations to make.
10 And I am wondering where it fell down the crack, the fact
11 that they were never made.

12 MR. MORRIS: I think the instrument volume, the
13 original design will tell you that that valve was closed.
14 And we had blockage of the drain line on the basis that it
15 was done normally. It doesn't in theory make any
16 difference, the fact that it takes only five minutes to
17 drain. I know it doesn't look very good, but normally you
18 never care about that, because after a scram you have
19 usually several hours where you don't expect to have to use
20 that scram system again.

21 MR. EBERSOLE: Isn't there a third party besides
22 GE and TVA called Control Associates?

23 MR. ABERCROMBIE: Reactor Controls.

24 MR. EBERSOLE: Now, does GE subcontract to that
25 subcontractor to take care of this problem?

1 MR. ABERCROMBIE: The contract with Reactor Controls was
2 with TVA.

3 MR. EBERSOLE: Oh, it was with TVA.

4 MR. ABERCROMBIE: Right.

5 MR. EBERSOLE: That was a subcontracting job from
6 TVA. GE doesn't do it?

7 MR. METCALF: The Reactor Controls contract was
8 actually with TVA.

9 MR. EBERSOLE: So they did that.

10 MR. METCALF: Right.

11 MR. EBERSOLE: Interfacing with GE.

12 MR. METCALF: Their design and their supply was
13 based on the design criteria and guidelines supplied by GE
14 for the basic design.

15 MR. EBERSOLE: TVA deliberately stayed away from
16 that part of the design and installation.

17 MR. MORRIS: I might add a couple of points here
18 that are not on the chart. With the vent closed, the east
19 side, as we already said, would take the drains at roughly a
20 half gpm. With the vent closed on the west side, it is a
21 little bit harder to measure that. I think we set the test
22 up it has to be three or four gpm on the west side when the
23 vent closed. It was a shorter path and there was no way for
24 the air to sneak back up in there.

25 Let me go over real quickly some of the stuff that

1 we have done since that time. We discussed the pre-flow
2 test. And we brought all of our people and we brought the
3 design down to GE in Chattanooga and we were trying to fix
4 it down there. As I said, we have to take a lot better
5 appreciation of how that system operates. We really know
6 how about to fix it so we make sure it won't happen again.
7 I think the system is basically a reliable system, when it
8 has worked three hundred times or four, several times at
9 other facilities.

10 And what we are saying, we have gone down and
11 looked at it, I believe we can further improve it
12 considerably. We have done all of the 8017 tests and we
13 have scrambled each unit and just testing all the -- we
14 monitored the discharge header itself. All of them seem to
15 be working fine. Some interim changes were made to the
16 system, and so far we have had UT monitors on both the east
17 and west side headers and continuously coordinating them, we
18 beam ultrasonic -- we have used this UT quite a bit during
19 the Unit 3 testing. We did it also the 8017 scram test and
20 had a lot of confidence in that testing. We have positive
21 vents on both the east and west headers, as Mr. Rathjen
22 explained earlier.

23 Of course, procedures and training goes, there are
24 several operating instructions have been changed to be a
25 little more explicit and telling the operator what to do if

1 by chance we should detect water within these instrument
2 volumes. And also, as part of the information and
3 dissemination program that we have, we inform all of our
4 operators about the TVA, about what is going on and this
5 incident, where we are at right now.

6 We are starting to converge on what we think our
7 final modifications would be to the system. We believe we
8 can eliminate possible reoccurrence of this event and
9 overall increase the general reliability of the system.

10 MR. CATTON: Do you have any requirements on time
11 to drain for SDV?

12 MR. MORRIS: In theory it doesn't make any
13 difference.

14 MR. CATTON: Well, in theory it does, but it is --
15 if it isn't, you will be in trouble.

16 MR. MORRIS: Our modifications certainly improved
17 the drain time of that system.

18 MR. CATTON: There is also do you have any
19 requirements on the amount of flow capacity it would have to
20 have, getting back to some of the questions that have been
21 raised by Mr. Ebersole.

22 MR. MORRIS: I don't think that there is really
23 not a specific requirement, as long as it will drain any
24 kind of a reasonable time period, say, an hour, something of
25 that nature. I don't see that you can really say that that

1 is a real hard criteria.

2 MR. CATTON: I wasn't trying to; I was asking.

3 MR. MORRIS: It would fall out of our modification
4 procedures.

5 And that is all I have.

6 MR. PLESSET: I think that Mr. Ebersole would like
7 to get his point discussed. Right?

8 MR. EBERSOLE: I thought they were going to do it
9 later.

10 MR. WIESENBURG: I would like to have Mr. Ross
11 address both of these questions -- on what happens to
12 nitrogen given leak by an accumulator, and address Mr.
13 Ebersole's question.

14 MR. PLESSET: Fine.

15 MR. WIESENBURG: The catastrophic failures of the
16 control rod itself.

17 MR. ROSS: First, to the nitrogen question: as I
18 understand it, the concern is what happens if we get
19 nitrogen across the piston of the accumulator and it is
20 trained in the flow going to the underside of the drive.

21 We have a schematic of the drive. It would make
22 it easier to understand the flow path through the drive.

23 The water from the accumulator is going to enter
24 into the drive water insert path, here, the underside of the
25 drive piston. The flow path, the normal cooling water flow

1 path, is the path not shown here, but it comes through the
2 flange of the drive and it goes up this permashield region
3 of the drive to the vessel, that way. The communication
4 path that potential nitrogen train of flow would have, then,
5 is one up through the drive piston, past these shields, and
6 as I said, there is on the order of like a dozen shields and
7 bushings, through that flow path, up past the outside of the
8 drive piston, through a like number of shields here, which
9 then communicates again with the vessel pressure; and from
10 that flow path, from this flow path on the outside of the
11 drive piston, it then has to go past more shields on the
12 collet piston shields to get again to the exhaust flow path
13 to the scram discharge volume.

14 I guess the bottom line on this discussion is that
15 if you were to get nitrogen train, it has a tough time
16 getting to the scram discharge volumes, to preferentially
17 discharge through the vessel instead.

18 I guess another point, going back to the earlier
19 diagram, is that it is tough to imagine that the nitrogen
20 does make it across the piston itself. Again, when you get
21 the scram injection and discharge valves open up and the
22 accumulator pushes the pressurized water to the accumulators
23 to the underside of the drive piston, at the point where the
24 accumulator pressure equals the vessel pressure, the -- we
25 have a ball check of the drive piston moves up and plugs

1 that flow path, and therefore you are not going to have any
2 communication from that point on with the accumulator.

3 MR. EBERSOLE: Because that goes to the reactor
4 pressure then, doesn't it?

5 MR. ROSS: Right. It equals out at reactor
6 pressure.

7 Now, the potential effect that would have is, once
8 -- well, let us assume that we did get nitrogen to the scram
9 discharge volume. Its consequence would be one of it would
10 modify the pressurization form of the trace, the
11 pressurizing of the scram discharge volume. However, the
12 rods would insert and in time, when the nitrogen would take
13 the volume of nitrogen assumed to be training at tank zero,
14 the water that it displaced at scram discharge volume is
15 that which is initially on the top of the drive piston, so
16 that the volume of nitrogen would have to traverse the full
17 length of the insert line and at the time that the rod is
18 fully inserted it has probably just made it to the underside
19 of the drive, let alone communicated clear back to the scram
20 discharge volume.

21 The next question was that of the consequences of
22 potential breaks or for reaching inside the drive itself. I
23 don't know, I look at it and I can hardly see a mechanism
24 which would give you a full communication path between the
25 vessel and the scram discharge volume through the type of

1 structure that we have. But even if it did occur on a
2 drive, the flow would still be limited by the discharge area
3 of the withdrawal line, and a critical mass flux rate would
4 be somewhere around 8000 pounds mass per square foot per
5 second. On an individual rod, where you have a withdrawal
6 line, it is a three-quarter-inch line; that would give you a
7 discharge of somewhere around 40 to 50 pounds per second.
8 Appreciating that the rods are fully inserted on the order
9 of three seconds, the contribution of this one rod would
10 only give you a gallon or two more of discharge to the
11 discharge volume which is shared by all of the rods. So its
12 potential consequence is, again, small.

13 MR. EBERSOLE: There is no structural failure that
14 you can envision in the piston rod or the cylindrical shell
15 within which it works that can cross-couple reactor fluid
16 pressure to the dump volume at a rapid rate prior to actual
17 calling for a scram signal and have it prefilled and
18 subsequently, in a matter of a few seconds, demand a scram
19 and not get it?

20 MR. ROSS: Certainly not prior to a scram. If you
21 have the breach of the piston occur prior to scram, the
22 scram valve is shut; there is no communication between the
23 vessel and the scram discharge volume.

24 MR. EBERSOLE: Well, out in the withdrawal lines
25 it is closed, the withdrawal valve is closed?

1 MR. ROSS: Yes.

2 MR. EBERSOLE: So that would preclude the
3 insertion of water from the dump volume from the cracked
4 piston or whatever?

5 MR. ROSS: Right. So prior to the time of the
6 scram there is no communication; this valve is shut. You
7 could have the cracked piston jumping in communication so
8 its only contribution is that which occurs during the time
9 the rod is broken.

10 MR. EBERSOLE: Now comes the question of whether
11 the fact that the mechanical failure could prefill the dump
12 volume during execution of the scram stroke. And you're
13 saying there is not time enough, right, because of
14 constrictions in the flow path?

15 MR. ROSS: Yes.

16 MR. EBERSOLE: It sounds like a good argument to
17 me.

18 MR. ZUDANS: Except that the closing time volume,
19 the discharge, because of the scram, also goes to the same
20 vent, through the same path. You can't scram; there is
21 competition for the outlet.

22 MR. ROSS: It may affect that one drive.

23 MR. EBERSOLE: That one drive is adequately taken
24 care of.

25 MR. ROSS: Maybe we might have a short break, a

1 ten-minute recess.

2 (A brief recess was taken.)

3 MR. PLESSET: Let us go on.

4 MR. WIESENBERG: We are ready. We have to address
5 some corrections and modifications, et cetera, that are
6 under consideration in the future. And Mr. Metcalf will
7 discuss that.

8 MR. METCALF: My name is Pelar Metcalf. And I am
9 with the engineering design. And I would like to discuss
10 some of the things that we have looked at in regard to
11 making modifications to the CRD system and make it more
12 reliable and more effective. And some of these
13 modifications I think you probably heard before, because
14 there are some somewhat similar to some of the
15 recommendations that GE is looking at.

16 And one of the things, our primary objective, I
17 think, in looking at these is like Jesse hit it earlier,
18 that the safety aspects of the system is to ensure that you
19 have a scram volume such that when you want to scram you
20 have an effective volume space to scram. The drain system
21 per se is not a safety system. You want to have a drain
22 system and you want it to be reliable such as you can drain
23 the water out. But what you really are looking for is to
24 making sure that the scram discharge volume along with the
25 scram discharge headers are empty of water when you want to

1 scram.

2 So one of the things that we have looked at from
3 the standpoint of the scram discharge instrument volume are
4 putting separate instrument volumes on both of the east and
5 west scram discharge headers. Each one of these headers
6 would be directly tied to the east scram discharge header in
7 the west with a six-inch line. There would be no pipe size
8 reduction from the header to the instrument volume.

9 And this is very similar to what is being done now
10 in the BRW sixes, because each one of the headers now have
11 separate instrument volume on BWRC sixes. The drain lines
12 from the scram discharge instrument volume would be an
13 individual line from each volume to the CRW system. They
14 would not cross-tie together; there would be a separate line
15 to the CRW system, the current CRW system at Browns Ferry.

16 Also, each scram discharge instrument volume would
17 basically have the same controls that are now on the
18 individual header, the instrument volume. So it would have
19 alarms for three-gallon alarm. There would be an inhibiting
20 control rod withdrawal, which is the 25-gallon. And there
21 would be a scram signal based on the 50-gallon alarm.

22 This suggests a kind of a pictorial view of what
23 the next system we'll look at looked like, and these lines
24 are not direct routings, it is just an idea of what would be
25 done. But you have a six-inch line coming into each one of

1 the instrument volumes. There would be a separate drain
2 line into the CRW system, so that any leakage into here
3 would go directly into here, because it would not be a
4 two-inch line, would be eliminated. Both the long line now
5 and also the two-inch line, which this line here is probably
6 a two-inch line, that would be changed to a six-inch line.

7 MR. ZUDANS: Why do you maintain still that that
8 will maintain --

9 MR. METCALF: Let me go into that a little later.
10 It is a little further on.

11 One of the things that is being considered, it is
12 a cross, I guess, of two things that you would like to see,
13 is you would like to make sure that the instrument volume
14 drains quickly, if after a scram, even though it is not a
15 safety requirement, and also you would like to have some
16 fairly close indication of what kind of leakage you may be
17 getting into the system. So one thing that has been
18 considered is maybe having a small line coming out of the
19 bottom such as you can detect leakage which would be
20 somewhere in the three-gallon alarm, would be the low, the
21 larger drain line going into the CRW system. This is the
22 drain valve such that larger volumes of water would drain
23 out quickly, and you would not rely on a small line coming
24 out of the bottom, it would be your primary drain if the
25 volume was full of water. So that is being considered.

1 Or there is also a possibility that the drain line
2 to the CRW could be increased to three inches or four
3 inches. Of course, when you do that you are effectively
4 draining water out quicker, but you also maybe lose a closer
5 indication of what kind of leakage you may be having in the
6 volume.

7 Is there any questions? I am now going into the
8 scram discharge header vent. Now, is there any questions
9 maybe on just the instrument volume itself?

10 MR. EBERSOLE. I guess this is as good a time as
11 any to make an observation here. I think this is a
12 classical case of a philosophy that permeates the whole
13 business to the detriment of safety. And that is, such
14 tight control is maintained over very minor radioactive
15 movements, that here the philosophy has been that it is more
16 important to close the dump volume and not let any of that
17 back leakage get someplace where it shouldn't than it is to
18 be sure that it is open so you can dump water into the dump
19 volume. And an inversion of that principle would be to say,
20 "I will have large open valves on the dump volume leading to
21 an appropriate fluid sink, and I will never close it until I
22 have guaranteed my rods have seated and then I will close
23 it." Right now the philosophy is: close them and then -- in
24 that -- and then work hard to make sure that you have plenty
25 of room having closed them.

1 It is an inversion principle here which is a
2 detriment to safety, and I think you ought to look at the
3 real root logic as to why it would not have been far better
4 to have had a volume clearly open, I don't care to where,
5 the dry well or the torus or whatever, and never close it
6 until I have got the rods home, and then close it to erase
7 the minor problem which is a little bit of leakage back
8 by-passing to the shields. It is a philosophical problem,
9 but I think it is right here and all we are doing is
10 patching it up.

11 MR. METCALF: I don't disagree with that. I think
12 the problem is actually that looking at closing such as you
13 don't have radiation and your possibility as long as you've
14 got an open space, keep it open until you get everything in.

15 MR. WIESENBERG: There is one other design
16 consideration that enters into this. And that is: given a
17 scram, the scram discharge system itself becomes an
18 extension of the reactor pressure vessel pressure boundary,
19 and it is not just a strict guard against radioactive
20 leakage; it is a strict guard against --

21 MR. EBERSOLE: It is new boundary; however, it is
22 rather tightly sealed by those strictures, and if it were
23 introduced into a safe area it would not matter. I mean, it
24 is a fundamental philosophy that contradicts safety.

25 MR. PLESSET: I disagree slightly with Mr.

1 Ebersole about their being a little bit looser with the
2 radioactivity. However, if you regard this scram discharge
3 volume, the instrument volume, as an extension of the
4 reactor vessel, why isn't it all safety grade? Why isn't it
5 all safety grade? I mean, it doesn't seem to follow. I
6 will accept your logic that it is an extension of the
7 primary vessel, which it is. But why isn't it, then, safety
8 grade all throughout? Why hasn't it been? And why will it
9 not be?

10 MR. METCALF: The system is safety grade up
11 through the vent valves and the drain valves. The
12 instrument volume, it is safety grade up through the vent
13 valves and the drain valves.

14 MR. CATTON: Is the air system safety grade? And
15 that is part of your square system.

16 MR. ABERCROMBIE: It is fail-safe.

17 MR. METCALF: I really could not answer that
18 question. The aspect of the valves, once the air is taken
19 off, then that part is now back, the other part, if you lose
20 your air, then you are going to scram.

21 MR. PLESSET: You are telling me that it has the
22 same seismic qualification as any other safety grade and it
23 is throughout?

24 MR. WIESENBERG: The discharge volume system
25 itself. Yes.

1 MR. PLESSET: And the instrument volume?

2 MR. METCALF: That is correct.

3 MR. PLESSET: It has always been that way?

4 MR. EBERSOLE: Well, the pipe back to the torus
5 could also be safety grade. If you wanted to open the
6 system, on the open there would be no degradation of the
7 reactivity, it would be the same, if you adopted the open
8 logic rather than the closed logic.

9 MR. WIESENBURG: Your point is well taken. All we
10 were trying to insert in the discussion was that there is
11 more consideration to this aspect.

12 MR. EBERSOLE: Time and again you will see safety
13 degraded by the apparent need, which is a political one, to
14 forbid the escape of the slightest amount of radioactivity.
15 It impacts on the safety function everywhere you turn.

16 MR. CATTON: How do you rationalize the relief
17 valves emptying into the torus? Is that different? Is it a
18 different philosophy in your relief valve than for your
19 scram system?

20 MR. METCALF: I think that from the aspect of what
21 --

22 MR. PLESSET: If this is all safety grade, why
23 does it stop at that valve? Because, as I understand it, at
24 Hatch they pulled out all of the hangers and the whole thing
25 got all torn up. Is that right?

1 MR. METCALF: I didn't understand your question.

2 MR. PLESSET: It is safety grade all the way down
3 to the clean rad waste.

4 MR. WIESENBURG: Safety grade until the drain
5 valve.

6 MR. PLESSET: But it has beyond that valve, is
7 where this pipe tore out of the wall and affected the rest
8 of the system, presumably set a water hammer back into it,
9 is that right?

10 MS. ZUKOR: I don't know at Hatch. I don't have
11 all that information.

12 MR. PLESSET: Well, it was Brunswick that set a
13 water hammer back through the system and crushed the level
14 indicators in the instrument volume. I still don't think
15 that it is safety grade in the sense that I am thinking of
16 it. Is yours safety grade, then, in that same sense? I
17 don't think it is. You say it stopped at the valves.

18 MR. WIESENBURG: It stops at the valves because
19 the valve would be the pressure boundary.

20 MR. PLESSET: So if you had a water hammer just
21 beyond the valve or back into the system and it crushed the
22 floats, you would be in trouble -- just as they were at
23 Brunswick. I mean, I don't follow the argument.

24 MR. EBERSOLE: It is safety grade, you say, up to
25 and including the valve, the vent and drain valves of the

1 dump volume.

2 MR. WIESENBURG: Yes, sir.

3 MR. PLESSET: Beyond that they are not, I believe.

4 MR. WIESENBURG: Yes, sir.

5 MR. PANCIERA: I am from the NRC staff.

6 Clarification on the point of safety grade. At our regional
7 meetings, indicated that in all cases there is a benign
8 seismic load; in most cases this was a static type analysis.

9 Point number two: we found at least one case where
10 it was -- in one case we felt that it was ASME Section 3,
11 Class 2. In many cases it was ASME B 31-1. In this I am
12 talking about the piping within the boundaries of the vent
13 and drain valve. So I am really at this point not sure just
14 what we have overall generically.

15 MR. PLESSET: Okay. That helps. Thank you.

16 Well, I think we have tried to make a point.

17 Maybe yours is all --

18 MR. METCALF: Well, going back to ours, I'm not
19 sure exactly. I think ours was to be 31-1. Of course, when
20 this was designed it wasn't basically a Section 3
21 requirement. And I think what we really are saying is that
22 within the confines of the isolation valve, of the -- not
23 the isolation, the drain valve and the vent valve, that
24 there was a seismic analysis done at some time, and from
25 that standpoint on the requirements were less because of the

1 fact that you were going into the CRW system and really your
2 requirement, like I said earlier, is the fact that you want
3 to ensure that you have got volume to scram, it is within
4 those confines of those two valves that back into the scram
5 valves back to the vessel.

6 MR. EBERSOLE: Are those stainless?

7 MR. METCALF: I believe everything is stainless
8 except for the scram discharge headers and maybe the drain
9 lines themselves. The withdrawal lines and things are
10 stainless. The small-diameter lines coming in from the
11 control units.

12 MR. EBERSOLE: But the big headers are?

13 MR. METCALF: Are not. They are carbon steel.

14 A little discussion now with regard to the scram
15 discharge header vents. And like I said earlier, the
16 primary interest is to make sure that you don't have water
17 in the scram headers or in the instrument volume. The
18 header vents and ensuring the vent and drain as quick as
19 possible are two things to do, but they are not the safety
20 aspects of the system.

21 Some of the things that we have looked and are
22 considering in regard to improving the vent and drain system
23 is cross-tying the vents from each of the scram headers.
24 This cross-tie would be before the vent valves there would
25 be a cross-tie with an isolation valve between such closing

1 and can put it back into the configuration that it is in
2 now. This is just to ensure that one of the vent valves
3 failed to open, that you would have a path that you could
4 vent back through the other vent valve, and just an
5 additional means for it.

6 We are also evaluating the vent valve design and
7 configuration. Currently it is a float valve. Maybe it
8 should be another type of valve. Maybe it should in a
9 vertical run as opposed to a horizontal run of pipe. These
10 are things that are being considered currently.

11 Also we are looking into where this scram
12 discharge header vent should be run: should it be
13 continually run to the CRW system, or possibly look at other
14 ways to have a more positive vent arrangement, such as going
15 to the DRW system or tying somehow into the APAC system.
16 And all of this is really to make sure that you have a vent
17 and for some reason that vent is available such that you can
18 ensure that you can drain from the instrument volume.

19 This sketch shows how the vent cross-tie would be
20 before each one of the vent valves. This is one
21 configuration which is being considered. And this is
22 currently each one of the vent lines come back in to a CRW
23 line, which is right above the floor elevation. One thing
24 that is being considered is to come up with a four-inch line
25 and tie in at a high elevation and then take a

1 small-diameter line being straight to the HVAC system. This
2 is to help ensure that you have a positive vent. That is
3 one thing that is being looked at currently.

4 Another item and with regard to the vent that we
5 are considering is taking the vent now to the DRW system,
6 rather than to the clean rad waste system. And we are also
7 looking at the possibility of putting two vent valves, as
8 opposed to one; and these would basically just be to ensure
9 that these valves close on scram. You basically would have
10 -- they would be the same type of valves, but it would just
11 be two valves.

12 But really, from our standpoint, we really haven't
13 made -- I guess we are a lot closer to making a decision as
14 to actually what we are going to do with the instrument
15 volume, as opposed to what we are going to do with the vent
16 system. And I think part of this is getting back to the
17 aspect of trying to make the vent more positive.

18 MR. EPERSOLE: Mr. Metcalf, I guess this is a good
19 time to observe we have been rightly accused of putting
20 Band-Aids on bad problems all over the place, and that is
21 exactly what we are doing here: we are Band-Aiding the
22 daylights out of what is a closed system to make it open and
23 close on schedule and to make it an instrument totally
24 acceptable for all operations. So shortly we are operating
25 all sorts of Band-Aids to close the system when it is

1 needed, as against the idea of having an open system which
2 doesn't need any instruments, it is just open and it will
3 dump, and then, having executed the prime function, you will
4 close it to prevent follow-on of a somewhat modest problem,
5 the leakage of seals.

6 All we are doing here is stacking all sorts of
7 garbage on top of garbage to make it work, rather than going
8 back to the root concept of evaluating that. And I would
9 suggest that you do that: you go back to the roots, not just
10 patch.

11 MR. METCALF: I don't disagree. And I think that
12 we have looked at other things. And I guess, from the
13 aspect of the vent itself, we are not completely satisfied
14 with what we want to do with it. And I think this part we
15 are more, because that gives you a positive indication that
16 you have got water and you don't have water, and if you
17 don't have water, you can scam. So this is a lot more
18 straightforward than from the aspect of the vent, because
19 that, I agree, is an area where it is really no clear
20 thought way to do it and solve all of your problems or maybe
21 create other problems by doing it different.

22 MR. EBERSOLE: You have to build on the
23 fundamental stake that it is beginning to make it work.

24 MR. ZUDANS: Would you consider that this is an
25 interim solution to make sure that you don't have any

1 further problems and you will continue thinking along the
2 lines that Jesse is talking about?

3 MR. METCALF: This that we are talking about here
4 is our plans in looking at a long-term solution. The
5 interim solution and detection of water, making sure that
6 you don't have water in the system, is being done by our UT
7 network. But this would be the long-term modification. It
8 would be an interim fix.

9 MR. ZUDANS: Do you feel, do you need any vents in
10 this modification at all?

11 MR. METCALF: Yes. You have to have some type of
12 vent if you are going to drain water out. And that goes
13 back to, I think, to what Herb said earlier: with the valves
14 closed you only get a certain amount of drainage. So you
15 would have to have some type of vent. Exactly how that vent
16 was configured is debatable.

17 MR. ETHERINGTON: That arrangement of the vent
18 that you have over there looks more like an overflow
19 arrangement than a vent.

20 MR. METCALF: An overflow?

21 MR. ETHERINGTON: Yes. You have it going down
22 into a funnel. I agree this is fine for when it does
23 overflow, but don't you want a connection to the vent system
24 as well? You've got an open pipe there.

25 MR. METCALF: The basis of this discussion, I

1 guess, in regard to -- you see, DRW system is an open
2 system; it is not a closed system like the DRW systems. The
3 arrangement is to make sure that -- I'm not sure there'd be
4 a funnel arrangement, but the intent is to make sure that
5 you have a positive vent to the atmosphere, but also some
6 type of configuration such that if you had any water or
7 steam condensation that it would go down into your drain.

8 MR. ETHERINGTON: Yes. But I would have thought
9 that you would have wanted to make another connection to the
10 vent system rather than just let it get out into the
11 building.

12 MR. METCALF: Well, this design would be made such
13 that that would be the intent, because you would make sure
14 you have a positive vent, plus any steam condensation would
15 go into the drain system rather than going out into the room.

16 MR. ETHERINGTON: Yes. But your previous slide
17 showed both a vent and a drain from the top of the --

18 MR. METCALF: You are talking with regard to the
19 vent back into the HVAC system?

20 MR. ETHERINGTON: The previous made more sense to
21 me than this one did. There you have an off-take for gas
22 and an off-take for condensation of water.

23 MR. METCALF: Well, there is drawbacks on both
24 ways. I guess this one you are venting into the HVA system
25 and if there's a possibility of steam you don't want

1 particularly steam going into the HVAC system. So, like I
2 say, it is being evaluated which would be the preferred way
3 to go, and I think there is drawbacks both ways.

4 MR. EPERSOLE: Mr. Metcalf, having endorsed an
5 open system, I'm going to get to the other part of the
6 problem. If I invoked a single failure on your venting
7 system and say that it stays open prior to a scram, and I
8 have somewhat messed up the reactive order by fuel failure
9 or whatever, then I've got an open path through that funnel
10 that we just saw all out into everywhere and I've got a big
11 mess on my hands -- right into the machinery rooms which
12 must mitigate the accident which I started with.

13 So how are you going to ensure as a prescram
14 function that, in fact, I did stop it up? Although I'd much
15 rather you did not do it at all. Do you understand?

16 MR. METCALF: I don't disagree with you. I think
17 that is one of the problems that we are having coming up
18 with a definite recommendation on regard to the vent
19 system. But that is one of the reasons why we were looking
20 at the possibility of having two valves if we go to an open
21 system like the DRW, such that you would, hopefully, ensure
22 that, number one, the valves would close if you needed them
23 closed and you were open.

24 Are there any other questions?

25 MR. PLESSET: That one there looks like you can

1 get some radioactivity into the ventilating system. Is that
2 right?

3 MR. METCALF: That is a possibility.

4 MR. PLESSET: That doesn't sound very appealing to
5 me.

6 MR. METCALF: Of course, there is monitors on the
7 ventilation system such that if there is radiation they
8 isolate. You can also on the stand-by.

9 MR. ZUDANS: But it doesn't do much good. They
10 only tell you, not a number, but you can't fix it.

11 MR. EBERSOLE: They tell you it already happened,
12 but you can't go in and fix it.

13 MR. CATTON: The suppression pool is looking
14 better and better.

15 MR. METCALF: I would say that we have looked
16 into, we have looked, considered the fact of putting the
17 vent into the torus. The problem is, I guess, there was
18 questions then when you might need to isolate that line.
19 But that has been --

20 MR. ZUDANS: Why not drain in the torus?

21 MR. METCALF: You are saying looking at the
22 possibility of running the drain itself into the torus?

23 MR. ZUDANS: Right. You started out with six-inch
24 line and you will cut it off at that point and run it
25 straight through the suppression pool, just put one valve in

1 there, get all your instrument; you don't need any
2 complementary vent lines; it is a perfect system, that is
3 what Jesse is talking about.

4 MR. EBERSOLE: Leave it open.

5 MR. ZUDANS: Leave it open and shut the valve when
6 you want to, to prevent it from leaking. All your level
7 sensors are your two-inch lines.

8 MR. EBERSOLE: It just disappears.

9 MR. ZUDANS: There's no reason to change the
10 headers and banks. They can stay there all right. The
11 question is can you find a place to run such a line. It
12 doesn't have to be six inches.

13 MR. METCALF: I agree. It is worth consideration.

14 MR. CATTON: Have you considered the use of the
15 suppression pool seriously?

16 MR. METCALF: Not seriously. We have looked at
17 the aspect of taking the vent back to the torus area. We
18 haven't really looked at bringing the drain line itself into
19 the suppression area.

20 MR. CATTON: When one of the relief valves is
21 actuated, how much mass are you putting into the suppression
22 pool? How does it compare with the amount of water
23 associated with the scram?

24 MR. METCALF: I don't know the exact amount, but
25 there'd be no comparison.

1 MR. EBERSOLE: It is infinitely greater.

2 MR. METCALF: There's just no comparison.

3 MR. PLESSET: I would like to shut off all of this
4 discussion up here. But let us do it. Are you finished?

5 MR. METCALF: Yes.

6 MR. PLESSET: Let us go on.

7 MR. DOMER: That takes us down to the last of the
8 agenda items. And that will be handled by Hank Pfefferlen
9 of GE.

10 MR. PLESSET: I should say that we would have to
11 stop in five minutes to twelve. Some people have to catch
12 the airport bus.

13 MR. PFEFFERLEN: I have a short presentation. I
14 will present what I have, then we will open it to questions.

15 MR. PLESSET: That will be fine.

16 MR. PFEFFERLEN: My name is Hank Pfferferlen. I
17 am manager of the BWR licensing programs for GE. And my
18 purpose here today is to discuss with you the results of the
19 GE evaluation into possible implications of the Browns Ferry
20 partial scram.

21 GE has performed some analysis in an attempt to
22 shed some light on the questions that were asked by the NRC
23 and by the ACRS, questions that are of the "what if"
24 character, what if we had this event concurrent with a
25 transient of some sort for full power. I will say that GE

1 has done this evaluation and we have concluded that given
2 the existing BWR configuration, that had the Browns Ferry
3 initial scram attempt occurred under these conditions, that
4 the operator had the capability to safely shut the plant
5 down.

6 Given that we have come to that conclusion, we
7 still treat this event in a very serious -- we feel it is
8 very important. To that end, GE has devoted significant
9 resources to investigating and evaluating the occurrence. I
10 think some of the activities were alluded to earlier. And
11 before I go into the results of our evaluation, I would like
12 to just very briefly put it into perspective of what the
13 total effort that we have done in understanding the problem.

14 Right after the Browns Ferry event, right after
15 the Browns Ferry event, we established communications with
16 the site; we set up a task force to interface Browns Ferry
17 with other units; we did send a team of individuals
18 knowledgeable on the scram system to the site, to try to
19 understand what was happening; and we activated a 24-hour
20 communication center. Those first four bullets really
21 represent the data accumulation and dissemination activity.
22 This was then used in a structured problem analysis effort
23 to try and understand just what went wrong, and I think the
24 results of this effort was presented already.

25 We also performed some analytical work to look at

1 the scram system performance. This was coupled with some
2 tests that were run in San Jose. And again this was
3 discussed previously.

4 What I would like to get into now are some of the
5 analytical efforts that we did in support of the answer to
6 one of the questions. These were: to answer our own
7 questions, to respond to I&E bulletins, and to respond to
8 NRC staff questions.

9 Given this input, I would like to summarize for
10 you just what we found.

11 Our evaluation was, first of all, based on the
12 generic plant that was assessed in the ATWS report that was
13 submitted to the staff in December of last year. We took
14 that plan and we considered in terms of an isolation event.
15 We did a, first of all, a core power calculation and
16 determined that given the rod motion that occurred after the
17 first scram attempt at Browns Ferry and taking that from an
18 end-of-cycle all-rods-out configuration, that we would drop,
19 probably power drop to less than 10 percent. This is
20 considerably evaluated, given that the initial power was at
21 100 percent, as I indicated, at the Browns Ferry rod motion,
22 we had recirculation pumps tripped in our case and we
23 assumed it happened someplace in the first 30 seconds. And
24 as I indicated, rods would be inserted from all-out,
25 end-of-cycle all-rods-out configuration.

1 MR. EBERSOLE: Is that a manual recirculation pump
2 trip that you envision in 30 seconds?

3 MR. PFEFFERLEN: Our assessment in the 30 seconds
4 in the eventuality if we had this event we would get an
5 automatically pump trip. The important thing that is in the
6 time scale, we had up to 30 seconds. So for a plant that
7 perhaps did not have ATWS RPT there would be time to take
8 some action. We believe that in reality the ATWS pump trip
9 would cause us to occur in a much shorter time.

10 MR. EBERSOLE: What would trip the pumps? Where
11 is the signal that would trip it?

12 MR. PFEFFERLEN: We are starting isolation from
13 100 percent power. No, we are not talking about what
14 happened at Browns Ferry.

15 MR. EBERSOLE: You propose --

16 MR. PFEFFERLEN: It is 100 percent and then the
17 rods scram in the same manner that was observed after the
18 first attempt at Browns Ferry.

19 In attaining this we had iterate between our REDY
20 code and a 3-D BWR core simulator, in order to establish
21 power. Once establishing this power, we used the REDY,
22 again the same code that we used in our ATWS assessment, to
23 look at the plant response. And I have broken that down
24 into two categories: first of all, the short-term response,
25 and then the suppression pool, which would be the long-term.

1 MR. CATTON: There's a REDY code that replaced the
2 old code?

3 MR. PFEFFERLEN: No. ODYN has replaced REDY. In
4 our ATWS assessment we have done a comparison between the
5 REDY and ODYN codes to assure ourselves that the two are
6 predicting the similar results and it is termed that REDY is
7 conservative for these ATWS tests.

8 At any rate, this is, then, an extension of our
9 ATWS extension.

10 MR. CATTON: I thought that the comparison between
11 that code did not quite predict the pressure peaks that it
12 should and that the new code did a good job and that a
13 lapped --

14 MR. PFEFFERLEN: As I understand it, it is
15 primarily related to the scram. It is more the timing.

16 MR. CATTON: The REDY code underpredicted the
17 pressures.

18 MR. PFEFFERLEN: With scram there is a problem
19 with timing, where the scram occurs relative to the
20 pressurization. It is not a problem in ATWS, since we are
21 not scrambling.

22 So what we would do is, we are cutting off the
23 peak, and depending on where you cut it off, the slope of
24 that peak makes quite a bit of difference. But then, I say,
25 we did compare CDYN and REDY in the ATWS context and we

1 found that, indeed, REDY was predicting conservatively.
2 They were very, very close, but REDY was somewhat
3 conservative.

4 MR. CATTON: All right. I will just accept that
5 for the moment.

6 MR. PFEFFERLEN: What we found, that in the
7 short-term, because of the drop to the lower power, the
8 rapid vessel pressure stayed within the off-set limits.

9 MR. EBERSOLE: What pressure was that, please?

10 MR. PFEFFERLEN: It was on the order of 1250, I
11 believe.

12 MR. EBERSOLE: And all valves were relieved? Or
13 did you take one stuck?

14 MR. PFEFFERLEN: No, we had all valves available.

15 MR. EBERSOLE: So you did not take a stuck safety
16 relief, you used them all?

17 MR. PFEFFERLEN: I'm not sure that all were called
18 upon at the power level. I could not answer that. We did
19 not assume a stuck valve. I'm not sure that all of them
20 were relieved. They all were available to relieve. I'm not
21 just quite sure what the actual response was.

22 MR. EBERSOLE: The pressure was 1250?

23 MR. PFEFFERLEN: Yes.

24

25

1 MR. PFEFFERSON: We both maintain an acceptable
2 level, and the fluid control and the level were well above
3 that calculated in the full ATWS.

4 MR. EBERSOLE: The fluid is just boiling flow, so
5 that wouldn't matter. But the level is something else. You
6 have lost main feedwater?

7 MR. PFEFFERSON: Yes.

8 MR. EBERSOLE: And you were operating at what
9 percent power?

10 MR. PFEFFERSON: 10 percent.

11 MR. EBERSOLE: And you have had water compression?

12 MR. PFEFFERSON: Yes.

13 MR. EBERSOLE: At what point in time did you have
14 to call upon the turbine driven aux feedwater, so-called --
15 what do you call it?

16 MR. PFEFFERSON: HPCI. I believe that is on the
17 order of one to two minutes into the event.

18 MR. EBERSOLE: And you call upon it at the time --

19 MR. PFEFFERSON: -- of level 2.

20 MR. EBERSOLE: You were sitting then at 1250
21 pounds?

22 MR. PFEFFERSON: No, no, the pressure --

23 MR. EBERSOLE: It would be --

24 MR. PFEFFERSON: With recirculation pumps, the
25 pressure would come back down.

1 MR. EBERSOLE: Oh, it would come down. What is
2 the power level after you have tripped the pumps then?

3 MR. PFEFFERSON: Well, that is when you get down
4 to the 10 percent.

5 MR. EBERSOLE: Okay. Now having got down to 10
6 percent and tripped the pumps, what is going to make the --

7 MR. PFEFFERSON: The level is moving down.

8 MR. EBERSOLE: The level is moving down, the
9 pressure is holding at 1250?

10 MR. PFEFFERSON: The pressure is back down to
11 below the low set point.

12 MR. EBERSOLE: Is it?

13 MR. PFEFFERSON: It comes back down, yes, and --

14 MR. EBERSOLE: But anyway, you are at the relief
15 set point --

16 MR. PFEFFERSON: Yes.

17 MR. EBERSOLE: -- of the first valve?

18 MR. PFEFFERSON: Yes.

19 MR. EBERSOLE: Now you are going to ask HPCI to
20 turn on under that condition?

21 MR. PFEFFERSON: That is correct.

22 MR. EBERSOLE: And of course they are notoriously
23 allergic to turning on the high pressure because they have
24 all these big trips which pumps it even at normal pressure.
25 So I guess I am going to get around to the fact

1 that you didn't get the HPCI pump eventually.

2 MR. PFEFFERSON: Well, we get down and at level 2
3 we would call for HPCI pump, which is what we have done in a
4 full ATWS and, you know, the same area.

5 MR. EBERSOLE: Yes, I know.

6 MR. PFEFFERSON: My point here is that in a full
7 ATWS, if the level continues down, the flow will reduce
8 further. But in this case, because of the lower power, the
9 HPCI is not able to correct the situation and maintain our
10 level within the range of the normal operation.

11 Now you are right, it is going to presume failure
12 in the HPCI. We have a --

13 MR. EBERSOLE: A problem?

14 MR. PFEFFERSON: We then have RCIC, which at the
15 lower power levels could provide some flow, and in fact we
16 believe that even a full ATWS, that while the level will go
17 very, very low, that eventually the RCIC would not -- and we
18 have not run this analysis. I am concluding -- --

19 MR. EBERSOLE: I know, but I know RCIC wouldn't
20 even cope with that for quite a while.

21 I guess now I would like to point a question to
22 TVA. I want you to notice your writing on HPCI. You have
23 got a lot of practical experience with HPCI and its
24 reliability or unreliability at normal pressures and
25 conditions. Here you are asking it to start on an

1 absolutely guaranteed requirement that it work at abnormal
2 high pressures. How do you feel about it? It had better
3 work quick too, no delay, no fiddling around.

4 MR. PFEFFERSON: I don't really know how to answer
5 you, other than that I think we have all looked at the
6 reliability of the data on HPCI's and we have made an awful
7 lot of improvements on the units at Browns Ferry. I think
8 we have improved reliability and, you know, if you think
9 that HPCI is not going to go you may as well as hang it up.

10 MR. EBERSOLE: You may as well hang up Browns
11 Ferry if HPCI doesn't work.

12 MR. PFEFFERSON: Or anywhere else.

13 MR. EBERSOLE: HPCI is a critical matter here.

14 MR. PFEFFERSON: Again, the point I am trying to
15 make, and I must qualify that it is not the result of
16 rigorous analysis, but it is our technical people's opinion
17 that if we were to go through a HPCI loss, that other
18 sources of water would eventually maintain the cooling
19 through that core. It's a difficult thing to analyze,
20 though.

21 MR. EBERSOLE: I guess I object to the word
22 "eventually," because it doesn't connote anything to me.
23 When you say eventually you will get cool, I don't know
24 whether that is after --

25 MR. PFEFFERSON: Well, no, I am sorry. Let me

1 clarify that.

2 What will happen is the level in the reactor will
3 continue to drop. At some point HPCI stabilizes and brings
4 the level back up, and the flow is then proportional to the
5 levels and natural circulation flow. If we were to lose
6 HPCI our level would continue to drop to a much lower
7 level. The core flow would reduce to a much lower level.
8 It would continue to maintain core flow at some very low
9 level. The power will then also -- and I think it is an
10 important point -- the power will continue down, and we
11 would reach a point where the RCIC closed would be
12 equivalent to the power system, which would maintain cooling.

13 MR. EBERSOLE: I would like at this point to ask a
14 question to you, GE, that has been asked internally but we
15 have made no progress on it.

16 It seems that the boiler has perhaps an attractive
17 features which is not exploited if you get to these dire
18 straits. Suppose I tell the operator at this time to
19 execute SAR and boil the reactor down to 100 pounds or
20 whatever to enable foam or froth cooling and get a void
21 fraction which is extremely high.

22 Would I get then a power reduction rate which I
23 could deal with with RCIC for example?

24 MR. PFEFFERSON: If you depressurize.

25 MR. EBERSOLE: Without burning the core?

1 MR. PFEFFERSON: If you depressurize, I think that
2 would be the case, but then you would bring on the low
3 pressure systems on cold water, which you would have to --

4 MR. EBERSOLE: Then I would get back in trouble
5 again?

6 MR. PFEFFERSON: You would get back in trouble
7 again.

8 MR. EBERSOLE: So I would have to intercede?

9 MR. PFEFFERSON: That is correct. Now we are back
10 to --

11 MR. EBERSOLE: Now we are cut two. We don't want
12 to pull that far down, to 400 pounds. But it does seem that
13 there is some possibility that you can void the core and
14 control the reactivity problem which has not been exploited.

15 MR. PFEFFERSON: Well, in essence I think that is
16 what I was saying here, that as the level goes down we in
17 essence accomplish --

18 MR. EBERSOLE: Some of that, yes.

19 MR. PFEFFERSON: And it is not as strong as what
20 you have suggested, but the mechanism is certainly there.

21 MR. EBERSOLE: Well, what I am arguing is that I
22 will increase the void volume, that I will reduce the void
23 -- in other words, I will reduce the void so that they
24 individually carry away fewer BTU's, so I have got to have
25 more of them, and that means I am going to reduce reactivity.

1 MR. PFEFFERSON: You are absolutely right, and we
2 have been thinking about this, and I think our problem is
3 that we are not able today with our analytical models to
4 handle a critical core during a blowdown. Now we are
5 looking at this. You are absolutely right. I think it is
6 an area that deserves exploration.

7 MR. EBERSOLE: Great.

8 MR. ABERCROMBIE: But you have got to know what
9 you are doing now.

10 MR. PFEFFERSON: Maybe we can't answer it. We
11 have to make some --

12 MR. ABERCROMBIE: They would have to know what
13 they doing.

14 MR. EBERSOLE: Oh, yes, but when your back is to
15 the wall you do whatever you can.

16 MR. ABERCROMBIE: Yes, that is really what you
17 have to go to.

18 MR. PFEFFERSON: Okay, the point I am trying to
19 make here is that in the short term the response would
20 perhaps vary so that the scram pattern is rounded
21 conservatively.

22 If we turn our attention now to the longer term
23 suppression pool temperature, we look at the timing
24 necessary to just keep the temperature within the acceptable
25 limits. It turns out that if the SLC were initiated in 30

1 minutes, that our peak pool temperature, will stay within
2 186 or below 186 degrees, which we feel is acceptable.

3 This is using the existing SLC system, the single
4 pump rather than the two pumps that are being discussed in
5 terms of ATWS. And the RHR was initiated at 10 minutes.

6 So I think though that the point I am trying to
7 make here is that while we expect the operator could take
8 actions well before this, that if he waited for 30 minutes
9 to initiate the SLC, the existing system, single pump, that
10 the pool temperature would be acceptable.

11 I think there was a question from the ACRS on loss
12 of offsite power, and we believe that, in looking through
13 the consequences of the loss of offsite power, that what I
14 have said here would apply also to loss of offsite power,
15 since one of the very early things that would happen would
16 be the closure of the SLC.

17 We would trickle off the heat water, the recirc
18 pumps named earlier, and in some cases we would be in an
19 even better situation.

20 The point, I guess that I am making here, this is
21 my conclusion, and this is all that I had planned to
22 present, is that given the low power that we attained
23 following the Browns Ferry scram, the effectiveness of that
24 portion of the scram, it is highly necessary for the
25 operator to initiate the boron system coupled with the

1 capability of the existing system. We believe that a plant
2 could survive a safety shutdown given the Browns Ferry today.

3 MR. EBERSOLE: Right, that is assuming that a lots
4 of things work like you think they are going to work.

5 MR. PFEFFERSON: That is correct.

6 MR. EBERSOLE: Let me compound the problem a
7 little bit. When you upset the safety reliefs -- by the
8 way, the whole plants have tail pipes on the reliefs now or
9 do some of them dump it --

10 MR. PFEFFERSON: Still on pipe.

11 MR. EBERSOLE: So you would get a high level
12 pressure for those?

13 MR. PFEFFERSON: Yes.

14 MR. EBERSOLE: Okay. Now I am going to make
15 things a little more messy by picking up another problem
16 that we have, which is sticky safety reliefs. And now you
17 have continued discharge at low pressure, or rather at low
18 power, such that eventually your pressure will fall to a
19 point at which the ECCS systems will do their great thing,
20 which is dump water by the tons into the system.

21 How is your boron injection system going to cope
22 with the flooding process that occurs?

23 MR. PFEFFERSON: We have to keep the low pressure
24 system from flooding the vessel.

25 MR. EBERSOLE: How are you going to do that?

1 MR. PFEFFERSON: The operator will have to prevent
2 the low pressure systems from --

3 MR. EBERSOLE: I am afraid he is locked out, he
4 can't. Can you?

5 I have gone to low pressure in the primary loop
6 below 400 pounds. I have got high level pressure and all my
7 big props are going to, against all efforts I think that you
8 make, are going to flush out all the boron you put in.

9 MR. PFEFFERSON: Well, I think you have to tie two
10 or three things together here. First, on the safety relief
11 valves that I have mentioned, since we have changed to state
12 valves we have not had a blowdown.

13 MR. EBERSOLE: So they are more reliable.

14 MR. PFEFFERSON: The reliability of the valves is
15 tremendous.

16 MR. EBERSOLE: Okay.

17 MR. PFEFFERSON: Secondly, in flooding the core,
18 where you have normal levels, for example, the work that we
19 have done, the order through the Emergency Procedures
20 Subgroup, we do instruct the operator to hold out the low
21 pressure systems if he has a normal level.

22 MR. EBERSOLE: And he can --

23 MR. PFEFFERSON: We would not let them start.

24 MR. EBERSOLE: He can stop those motors in the
25 presence of any signal?

1 MR. PFEFFERSON: He can override.

2 MR. EBERSOLE: He has overrides.

3 MR. PFEFFERSON: Yes.

4 MR. EBERSOLE: I remember, yes, he has got
5 forcible overrides.

6 MR. PFEFFERSON: But to keep pouring in, if he has
7 his reactor water level normal, within normal limits, he
8 would not allow those pumps to flood.

9 MR. EBERSOLE: He would turn them off. They are
10 on automatic power?

11 MR. PFEFFERSON: Yes.

12 MR. EBERSOLE: But would he go off and turn them
13 off?

14 MR. PFEFFERSON: That is what we have in our
15 procedures now. The thing you can in on, under all
16 circumstances, is you got a normal level.

17 MR. EBERSOLE: Yes. And didn't you have that
18 procedure prior to this?

19 MR. PFEFFERSON: Yes. We did that work in the
20 aftermath of TMI, the boards -- General Electric and all the
21 utilities working together.

22 MR. EBERSOLE: So you are already aware of the
23 boron washout potential?

24 MR. PFEFFERSON: I don't think, we do not directly
25 couple the operator actions with any problem on SLC.

1 MR. EBERSOLE: Oh, it just came about as a back --

2 MR. PFEFFERSON: Yes. I understand at that point
3 you have to put two or three things together to kind of
4 figure out what might be happening to the operator.

5 MR. EBERSOLE: Do you regard it as advantageous
6 that he has to manually put boron in because he will
7 remember he better keep it in rather than automate its
8 insertion?

9 Suppose I automated its insertion. Would he
10 remember that he has got to keep it in?

11 MR. PFEFFERSON: Yes, I think so.

12 MR. EBERSOLE: In other words, you would favor
13 manual insertion?

14 MR. PFEFFERSON: I favor manual insertion for the
15 boron.

16 MR. EBERSOLE: At least it would make him remember
17 he had better keep it.

18 Thank you.

19 MR. PLESSET: Well, thank you. I think we had
20 better kind of draw things to a close. We have a five
21 minute to 12:00 deadline for some people. Do you want to
22 make some closing remarks? We will give you just a couple
23 of minutes.

24 MR. DORMER: The only thing I was going to say is
25 that I hope we covered everything you wanted us to cover.

1 MR. ZUDANS: Mr. Chairman, could I ask a very
2 quick question?

3 MR. PLESSET: Very. Just one short one.

4 MR. ZUDANS: Yes, one short question. Why are all
5 the drives on one side, and why don't they crisscross from
6 one to the other? Wouldn't that then be a better end result
7 if it did?

8 MR. ROSS: In retrospect, yes, I would consider it
9 would. I guess the design basis of that system was that it
10 wasn't required because we provided instrumentations to
11 monitor the potential accumulation of water in that volume
12 that designs itself.

13 MR. PLESSET: A plumber's nightmare. Let's leave
14 it at that. I am sorry. Let's make it simple and say it is
15 a plumber's nightmare.

16 The only other comment I was going to make, you
17 have got an impression that some of the people up here like
18 the idea of draining down into the suppression pool. I want
19 to tell you it is not unanimous up here. But I like your
20 viewing this whole SDV and the instrument volume, drain and
21 vent lines as part of the primary vessel. But I would like
22 you to include that drain valve, because this Brunswick
23 thing, there is a possibility that that drain valve is what
24 caused the destruction of the instrumentation and the
25 instrument volume.

1 So if you go just a little bit farther, you would
2 make me happy. That may not be your objective, but it is a
3 thought.

4 I don't think there is any disagreement with
5 having this high class installation all the way to the
6 bitter end, downstream of the valve.

7 Well, I thank you all, and I think there will be
8 some further discussion on September 3rd on some aspects of
9 this in Washington. There is this Safety Philosophies
10 Subcommittee meeting in Washington September 3rd, and some
11 of you might wish to be in touch with that subcommittee
12 agenda in case there are things of interest to you.

13 With that I thank you again. You responded very
14 well, I think, on short notice, and we appreciate it. So
15 the meeting is adjourned.

16 (Whereupon, at 12:00 p.m., the meeting was
17 adjourned.)

18
19
20
21
22
23
24
25

- - -

NUCLEAR REGULATORY COMMISSION

This is to certify that the attached proceedings before the
ACRS SUBCOMMITTEE MEETING ON FLUID DYNAMICS

in the matter of:

Date of Proceeding: 20 AUG 80

Docket Number: _____

Place of Proceeding: INGLEWOOD, CA


were held as herein appears, and that this is the original transcript thereof for the file of the Commission.

JAMES J. HIGGINS

Official Reporter (Typed)

James Higgins

Official Reporter (Signature)



Subject: INCOMPLETE CONTROL ROD INSERTION FOLLOWING UNIT THREE SCRAM -
REVIEW TO SUPPORT PROPER ELECTRICAL OPERATION OF THE REACTOR
PROTECTION SYSTEM

During a planned shutdown of unit 3, hydraulic control units on the east side of the reactor failed to fully insert control rods until after several attempts. The following analysis supports proper electrical operation of the reactor protection system.


Operators verified blue scram lights illuminated on the main control panel while partially inserted control rods held steady at recognizable intermediate positions. Closure of limit switches mounted on each scram valve are required for blue scram light illumination and this is positive indication that both scram valves were open.

Response times required for the scram actuators to fully de-energize were verified to be acceptable and each rod scram group was verified to be electrically independent.


Hydraulic control units from each of the four rod scram groups were verified to be randomly positioned on both sides of the reactor. It is then reasonable to observe typical electrical response from only two sets of four if each of the hydraulic control units are directly adjacent and one is from each rod scram group. Hydraulic control units 18-03, 22-03, 26-03, 30-03, 30-07, 34-07, 38-07, and 42-07 were selected because their control rod drives are also directly adjacent and located in the same core proximity.

The second set of four hydraulic control units which share the west side scram discharge volume all inserted rods properly. Since west side hydraulic control units inserted rods properly the manual scram actuators which are common to each side of the reactor must have operated properly and the pilot scram valve solenoids on both the east and west sides of the reactor must have de-energized. Rod movement to position 02 following scram is a relatively common occurrence and the failure of rod 30-23 to fully insert on the first attempt is not considered relevant.


Based on this analysis, the failure of rods to fully insert was not caused by any electrical malfunction in the reactor protection system trip logic.




Back-up Scram Valve Circuit
TYPICAL OF 2




RESET CIRCUIT
TYPICAL



GROUP SCRAM VALVE SOLENOIDS
TYPICAL OF 4 GROUPS



GROUP SCRAM VALVE SOLENOIDS
TYPICAL OF 4 GROUPS



MANUAL SCRAM CIRCUIT
TYPICAL FOR A & B CHANNELS

PROPOSED SCHEDULE FOR ACRS
FLUID DYNAMICS SUBCOMMITTEE MEETING
AUGUST 19-20, 1980

TUESDAY, AUGUST 19, 1980

- | | |
|---|----------|
| I. EXECUTIVE SESSION - Opening Comments - M. Plesset | 8:30 am |
| (A) Discussion with ACRS Fellows on Their Report | |
| BREAK | 11:00 am |
| II. INTRODUCTORY COMMENTS - NRC Staff | 11:15 am |
| III. DESCRIPTION OF BWR CONTROL ROD DRIVE MECHANISM AND
SCRAM SYSTEM GE SCOPE OF DESIGN AND INTERFACE RE-
QUIREMENT FOR A.E. - GE | 11:30 am |
| LUNCH | 1:00 pm |
| IV. BRUNSWICK AND HATCH EVENTS RESULTING IN DAMAGE TO
LEVEL SWITCHES | 2:00 pm |
| (A) System Design | |
| (B) Normal System Operation | |
| (C) Event Sequence | |
| (D) Course of the Event | |
| (1) Actions Taken to Investigate | |
| (2) Conclusions Reached | |
| (E) Possible Consequences if all Instruments had
Failed | |
| (i) How Long Would it Take to Accumulate Enough
Water to Prevent Scram | |
| V. QUESTIONS RAISED BY COMMITTEE MEMBERS (List provided to
Staff) | 3:30 pm |
| RECESS | 5:00 pm |

WEDNESDAY, AUGUST 20, 1980

VI. BROWNS FERRY 3 EVENT OF JUNE 28, 1980

8:30 am

- (A) As Built Design of the Scram System Scram Discharge, Piping, Valves, Instrumentation, Drain Tanks, etc.
- (B) Description of the Normal Operation of the System
- (C) Event Sequence of June 28, 1980
- (D) Why did Event Occur
 - (1) Actions Taken to Investigate Event
 - (2) Conclusions Reached
- (E) Corrections Taken or Planned
- (F) Possible Outcome of Event Under Slightly Different Conditions, i.e., Scram from 100% Power, Scram from Loss of Offsite Power

VII. NRC RESPONSE TO EVENTS

10:30 am

- (A) Immediate NRC Actions Through I&E Bulletin 80-14 and 8-17
- (B) Results of Testing at Other BWRs
- (C) Immediate Modifications Required to Vent the Scram Discharge Volume
- (D) NRC Regional Meetings with Licensee's to discuss as Built Conditions
- (E) Long Term NRC Actions Underway
- (F) Implications with Regard to ATWS

VIII. GENERAL DISCUSSION

12:30 pm

ADJOURN

1:00 pm

SCRAM DISCHARGE HEADER VENT

Crosstie vents from each scram header

Evaluate vent valve design and configuration

Each scram header vented to CRW system

Positive vent arrangement


SCRAM DISCHARGE INSTRUMENT VOLUME

Separate SDIV's for the east and west scram discharge headers.

Six inch diameter pipe from scram header to SDIV


Drain line to CRW system


Either SDIV will alarm, inhibit control rod withdrawal, and scram




25 GALLONS

3 GALLONS







17

GENERAL ELECTRIC
PRESENTATION TO THE
ACRS ON
BROWNS FERRY 3 EVENT

AUGUST 20, 1980

HCP
8/18/80 (MM/1539)

PURPOSE

PRESENT RESPONSE TO QUESTIONS ON BROWNS FERRY
PARTIAL SCRAM WITH ESCALATED ASSUMPTIONS

HCP (1)
8/15/80 (MM/1793)

15

GE ACTIONS

- o ESTABLISH DIRECT PHONE CONVERSATION WITH BROWNS FERRY SITE
- o ESTABLISHED SAN JOSE TASK FORCE TO COORDINATE SUPPORT FOR BROWNS FERRY 3 AND DIRECT EFFORTS FOR OTHER UNITS
- o DISPATCHED TEAM OF SIX SENIOR PERSONNEL TO BROWNS FERRY SITE
- o ACTIVATED A 24-HOUR COMMUNICATION CENTER FOR DIRECT COMMUNICATIONS WITH OPERATING UNITS
- o PERFORMED STRUCTURED PROBLEM ANALYSIS AND IDENTIFIED POTENTIAL IMPROVEMENTS
- o PERFORMED ANALYTICAL ASSESSMENTS
 - SUPPORT INTERNAL EVALUATIONS
 - RESPOND TO I&E BULLETIN
 - RESPOND TO NRC STAFF QUESTIONS

HCP (2)
8/15/80 (MM/1794)

PARTIAL SCRAM EVALUATION

- o EVALUATION BASED ON RESPONSE OF GENERIC BWR/4 PLANT USED IN ATWS REPORT TO ISOLATION EVENT
- o CORE POWER CALCULATED TO DROP BELOW 10%
 - INITIAL POWER AT 100%
 - BROWNS FERRY PARTIAL SCRAM ROD MOTION
 - RECIRCULATION PUMPS TRIP WITHIN 30 SEC.
 - RODS INSERTED FROM EOC ALL RODS OUT CONDITION
- o PLANT RESPONSE TO ISOLATION (SHORT TERM)
 - REACTOR VESSEL PRESSURE WITHIN "UPSET" LIMITS
 - CORE COOLANT LEVEL/FLOW MAINTAINED AT ACCEPTABLE LEVELS
 - CORE RESPONSE CONSERVATIVELY BOUNDED BY ATWS EVALUATIONS
- o SUPPRESSION POOL TEMPERATURE MAINTAINED WITHIN ACCEPTABLE LIMITS
 - PEAK POOL TEMPERATURE IS 186°F
 - EXISTING (SINGLE PUMP) SLC UTILIZED
 - SLC INITIATED AT 30 MINUTES (MANUALLY)
 - RHR INITIATED AT 10 MINUTES
- o ISOLATION EVENT EVALUATED CONSISTENT WITH LOSS OF OFFSITE POWER EVENT

HCP

8/18/80 (MM/1540)

CONCLUSIONS

EXISTING PLANT DESIGN CAPABLE OF
ACCOMMODATING BROWNS FERRY PARTIAL
SCRAM SHOULD IT HAVE RESULTED FROM
A TRANSIENT AT FULL POWER

OUTLINE

- I. DESCRIPTION OF HANDOUTS AND FULL-SIZE DRAWINGS AVAILABLE

- II. SIMPLIFIED CRD HYDRAULIC CONTROL SYSTEM FIG. 1

- BASIC ISOMETRIC OF SCRAM DISCHARGE SYSTEM (SIMILAR TO DISPLAY MODEL) FIG. 2

- DETAILS OF SCRAM INSTRUMENT VOLUME TANK AND LEVEL SWITCH FIG. 3

- AS-BUILT ISOMETRIC OF SCRAM DISCHARGE SYSTEM FIG. 4


- AS-BUILT ISOMETRIC OF UNITS 1 AND 2 VARIATIONS FIG. 5

- III. FLOW DIAGRAM OF CLEAN RADWASTE DRAINAGE SYSTEM FIG. 6


- TABULATION OF CRW INTERFACES WITH SCRAM DISCHARGE SYSTEM FIG. 7A THRU 7C


- AS-BUILT PLAN VIEWS OF CRW PIPING BY ELEVATIONS:
 - EL. 565-0 FIG. 8
 - EL. 593-0 FIG. 9
 - EL. 621-3 FIG. 10
 - EL. 639-0 FIG. 11

SIMPLIFIED SCHEMATIC
TYPICAL CRD HYDRAULIC CONTROL SYSTEM




LEGEND






CRD SCRAM DISCHARGE HEADER ISOMETRIC
BROWNS FERRY NUCLEAR PLANT


SCRAM DISCHARGE INSTRUMENT TANK





DETAIL 'A'


NOTES: UNIT #3 SHOWN
 FOR NON-TYP. RETINA SEE SHEET #2
 CAD HEADER ELEV FOR UNIT #3 UNIT #2 ADD 1'0"



NO.	REV. NO.	DATE	DESCRIPTION	BY	CHKD.	APPD.
SCALE			EXCEPT AS NOTED			
CONTROL ROD DRIVE HYD. SYS. SCRAM DISCHARGE HDR. ISOMETRIC UNIT 1-2-3 SHEET #1						
TENNESSEE VALLEY AUTHORITY DIVISION OF ENGINEERING DESIGN						
DESIGNED		RECOMMENDED		APPROVED		
INSPECTED AND APPROVED FOR ISSUE _____ KNOXVILLE						

AS CONSTRUCTED



4




WEST CRD. SCRAM HEADER VENT
UNIT #2

EAST CRD. SCRAM HEADER VENT
UNIT #2


NOTES: UNIT #2 HAS NO PLUMBING LINES



DETAIL - A UNITS 1 & 2




WEST CRD SCRAM HEADER VENT & FLUSHING SYSTEM UNIT #1



EAST CRD SCRAM HEADER VENT & FLUSHING SYSTEM UNIT #1

NO.	REV. NO.	DATE	DESCRIPTION	BY	APP. (LICENSE NO.)
SCALE			EXCEPT AS NOTED		
CONTROL ROD DRIVE HYD. SYS. SCRAM DISCHARGE HGR ISOMETRIC UNIT 1-2-3 SHEET # 2					
TENNESSEE VALLEY AUTHORITY DIVISION OF ENGINEERING DESIGN					
SUBMITTED		RECOMMENDED		APPROVED	
INSPECTED AND APPROVED FOR ISSUE					
KNOXVILLE					



NO.	REV. NO.	DATE	DESCRIPTION	BY	APP. (LICENSE NO.)

AS CONSTRUCTED

5

TABULATION OF CRW INTERFACES WITH SCRAM DISCHARGE SYSTEM



FLOW DIAGRAM


REF. NO.	LINE DESCRIPTION	LOCATION
1	Lower end of 8" unlimited access equipment Drain Hdr. (in R.B. equipment Dr. sump)	El. 509'-0"
2	Vertical run of 8" header from sump.	To El. 547'-6"
3	Vertical run of 8" header from sump (continued).	To El. 560'-4"
4	<u>90° El. for horiz. run of 8" header to Stub-ups thru the 565'-0 floor slab:</u>	El. 561'-4" El. 565'-0"
5	<u>Train 1 (For all units unless indicated)</u> 1 ea panel 25-52 dr * 1 ea U2 capped and U3 atmospheric filter vent (CAPPED) 2 ea CRW dr. capped * 1 ea atmospheric vent (CAPPED) * 1 ea CRD header vent (CAPPED) 1 ea RHR heat exchanger dr. (shell side) (unit 1 only) 1 ea panel 27-217 dr. U2 capped U3 D.W. control air surge Tk. dr. 2 ea RHR shutdown cooling dr. U3 capped 1 ea RHR supply dr. U3 capped 1 ea panel 25-196 dr. U2 and U3 capped	El. 565'-0"
	<u>Train 1A (U2 and U3 only)</u> 2 ea CRW dr. capped 1 ea CRW dr. capped (U2) 1 ea RHR heat exchanger dr. (U3)	El. 565'-0"
6	<u>Train 2</u> 1 ea panel 25-18 dr. 2 ea CRW dr. capped 1 ea Recvrc Pmp seal dr. U3 CRD relief vlv. disch. dr. 4 ea CRW dr. (inaccessible)	El. 565'-0"
8	<u>Train 3</u> * 1 ea scram instr. vol. dr. 1 ea Dp comp. separator dr. U2 line trap dr. 1 ea CRW dr. capped off-U1 1 ea RHR heat exchanger dr. shell side -U1	El. 565'-0"

FLOW DIAGRAM

REF. NO.	LINE DESCRIPTION	LOCATION
7	<u>Train 4</u> 1 ea CRW dr (inaccessible) 1 ea panel 25-51 dr. and dr. from steam tunnel 2 ea CRW dr. capped * 1 ea atmospheric vent (CAPPED) * 1 ea scram hdr. vent (CAPPED) 1 ea panel 25-57 dr. U2 and U3 only 1 ea RHR heat exchanger dr. 1 ea CRW dr. capped	El. 565'-0"
9	<u>6" header from 8" header to</u>	El. 565'-0"
10	<u>stub -ups in the 593' floor:</u> 2 ea CRW dr. capped (U1) 1 ea RBCCW panel 25-8 dr. A/C dr RBCCW receiver dr. "B" isolation tank dr. Vertical line to RBCCW dr. Receiving Tr. dr. RBCCW dryer dr. (U3 blanked) 1 ea panel 25-5 A and B and 25-5-00 dr. 1 ea RWCU panel 25-2 dr. 1 ea panel 25-6-001 dr. (U2 and U3) 1 ea panel 25-6 A and B dr. (U2 and U3) 1 ea CRW dr. blanked (U2 and U3)	El. 593'-0"
11	<u>6" header to stub-ups</u> <u>in 621'-3" floor:</u> <u>Unit 1 only</u> 1 ea A/C unit bd. rm dr. 1 ea D.W. pool Htx. dr. 1 ea T's to D.W. and FPC pipe dr. 2 ea T's to vent sys and fuel pool Ht Exch. dr. 2 ea fuel pool cool PMP dr to vent sys to FPC pipe dr. 2 ea to 14" pipe dr. 1 ea RWCU precoat PMP dr. RWCU precoat Tk dr. to tank overflow dr. (VENTED TO ATMOSPHERE) to backwash inlet dr. precoat outlet dr. 1 ea to precoat inlet A dr. to precoat outlet B dr. to RWCU holding PMP 1B dr. to backwash line dr. to precoat PMP disch. dr. to precoat outlet dr.	El. 593'-0" El. 621'-3"

11 (cont'd)	<p>1 ea spare blank</p> <p>1 ea to RWCU holding PMP 1A dr to precoat inlet A dr. to precoat inlet B dr.</p> <p style="text-align: center;"><u>Unit 2 and Unit 3</u></p> <p>1 ea panel 25-36 A and B and 25-187 dr. El. 621'-3"</p> <p>1 ea holding PMP dr.</p> <p>1 ea RWCU station dr. U2 precoat backwash intake dr.</p> <p>1 ea pump 2A dr. U3 PMP disch dr. U3 PMP 3B dr. U3 backwash air pipe dr.</p> <p>1 ea PMP 2A dr. to backwash air line dr. U3 blank</p> <p>1 ea U2 blank U3 precoat overflow dr.</p> <p>1 ea to conds. s and s pipe dr. to 6" RHP pipe dr.</p> <p>1 ea FPC pipe dr.</p> <p>1 ea PMP A and B dr. FPC pipe dr. U3 FPC PMP dr. A and B</p> <p>1 ea FPC pipe dr. for U2 add PMP A and B dr.</p> <p>2 ea FPC Ht. Exch. dr. U3 FPC Ht. Exch. dr.</p> <p>1 ea panel 43-674 and 673 dr. U3 sample station dr.</p> <p>1 ea eq. dr.</p>	
12	<p><u>6" header to stub-ups in the 639'-0" floor:</u></p> <p>4 ea air duct dr. 4 ea blank (5 ea for U2 and U3)</p>	El. 639'-0"
13	<p><u>4" line from 8" header to</u></p>	El. 561'-4" to
14	<p><u>Stub-ups in the 593'-0" floor:</u></p> <p>2 ea CRW dr. 1 ea instru. panel dr.</p>	El. 593'-0"
15	<p><u>2" line from 4" line to stub-ups in 621'-3" floor:</u></p> <p>1 ea fuel pool vent duct dr.</p>	El. 593'-0" to El. 621'-3"





PLAN 509.0

UNIT 2 F 2


UNLIMITED ACCESS @ EC 509.0
 UNLIMITED ACCESS @ EC 509.0
 UNLIMITED ACCESS @ EC 509.0

AS CONSTRUCTED


NO.	REV.	DATE	DESCRIPTION	BY	CHKD.
SCALE			EXCEPT AS NOTED		
POWERHOUSE					
REACTOR BUILDING UNITS 1-3					
CRW					
UNLIMITED ACCESS @ EC 509.0					
TENNESSEE VALLEY AUTHORITY					
DIVISION OF ENGINEERING DESIGN					
SUBMITTED		RECOMMENDED		APPROVED	
KNOXVILLE					
DESIGNED BY					
CHECKED BY					
DATE					

NO.	REV.	DATE	DESCRIPTION	BY	CHKD.

8



PLAN-EL 5




930'


UNIT NO. 1 Paul Smith, John E. Hill
 UNIT NO. 2 J. W. Smith, John E. Hill
 UNIT NO. 3 J. W. Smith, John E. Hill
AS CONSTRUCTED

SCALE		EXCEPT AS NOTED
CRW UNLIMITED ACCESS ELEV 5930'		
TENNESSEE VALLEY AUTHORITY		
DIVISION OF ENGINEERING DESIGN		
DESIGNED	RECOMMENDED	APPROVED
KNOXVILLE		

INSPECTED AND APPROVED FOR ISSUE										
NO.	DATE	BY	FOR	NO.	DATE	BY	FOR	NO.	DATE	BY

9





UNIT 2 & 3


ELEVATION 621.25'


UNIT 1 *[Handwritten Signature]*
 UNIT 2 *[Handwritten Signature]*
 UNIT 3 *[Handwritten Signature]*

AS CONSTRUCTED

NO.	REV.	DATE	DESCRIPTION	BY	CHECKED
SCALE				EXCEPT AS NOTED	
<p>UNLIMITED ACCESS @ ELEV 621.25'</p>					
<p>TENNESSEE VALLEY AUTHORITY DIVISION OF ENGINEERING DESIGN</p>					
SUBMITTED		RECOMMENDED		APPROVED	
KNOXVILLE					

10





PLAN EL 619.0

UNIT ONE
UNIT TWO
UNIT THREE

AS CONSTRUCTED

NO.	REV. NO.	DATE	DESCRIPTION OF CHANGE	BY	APPROVED
SCALE			EXCEPT AS NOTED		
<p>CRW 6" UNLIMITED ACCESS EL 619.0</p>					
<p>TENNESSEE VALLEY AUTHORITY DIVISION OF ENGINEERING DESIGN</p>					
SUBMITTED		RECOMMENDED		APPROVED	
KNOXVILLE					
<p>INSPECTED AND APPROVED FOR ISSUE</p>					
<p> </p>					

NO.	REV. NO.	DATE	DESCRIPTION OF CHANGE	BY	APPROVED

14

PRIOR TO INITIAL SCRAM

- POWER LEVEL REDUCED TO 36% BY:
 - REDUCED RECIRCULATION FLOW
 - SELECTED CRD INSERTION

- NORMAL SHUTDOWN COMPLETED BY MANUAL SCRAM

PRIOR TO SCRAM #1

59				48	48	48	48	48	48	48						
55				48	48	48	42	48	42	48	48	48				
51				48	48	48	48	48	48	48	48	48	48			
47				48	12	48	0	48	8	48	8	48	0	48	12	48
43	48	48	48	48	48	48	48	48	48	48	48	48	48	48	48	48
39	38	48	48	48	0	48	48	48	48	48	0	48	48	48	38	
35	48	48	48	48	48	48	48	48	48	48	48	48	48	48	48	
31	48	48	0	48	48	48	48	48	48	48	48	48	0	48	48	
27	48	48	48	48	48	48	48	48	48	48	48	48	48	48	48	
23	38	48	48	48	0	48	48	48	48	48	0	48	48	48	38	
19	48	48	48	48	48	48	48	48	48	48	48	48	48	48	48	
15				48	12	48	0	48	8	48	8	48	0	48	12	48
11				48	48	48	48	48	48	48	48	48	48	48		
07				48	48	48	42	48	42	48	48	48				
03				48	48	48	48	48	48	48						

16

02 06 10 14 18 22 26 30 34 38 42 46 50 54 58

AFTER SCRAM #1

59				40	4	36	42								
55				36	46	38	2								
51				36	34		36	42	10						
47				42		20		24							
43	12	40	44		30	28	40	38							
39	24		40			34	32								
35	30	4	38		18	8	34	30							
31	22	10		34	28	2									
27	42	36	30	14	26	28	36	24							
23	8		38	32		12	36	2							
19	34	42	34	20	10	28	22	26							
15			40		36		38								
11			26	6	14	40	40	24							
07					40	2									
03					28	42	42	30							

0131

Blank
Indicate
Rod Full
In

02 06 10 14 18 22 26 30 34 38 42 46 50 54 58

FOLLOWING INITIAL SCRAM

● OPERATOR ACTIONS

- SCRAM DISCHARGE VOLUME HIGH LEVEL SCRAM BYPASSED
- PLACED REACTOR MODE SWITCH IN SHUTDOWN
- IRM'S AND SRM'S INSERTED
- SCRAM RESET 4 MIN 27 SECS

● OPERATOR OBSERVES

- ALL SCRAM VALVES OPEN
- ALL ACCUMULATORS DISCHARGED
- MANY CRD'S ON EAST SIDE NOT FULLY INSERTED
- APRM READINGS DOWNSCALE
- OTHER PLANT PARAMETERS NORMAL

● OTHER SIGNIFICANT INFORMATION


- SCRAM LEVEL SWITCHES TRIPPED IN 18 SECONDS VS. NORMAL 40 TO 50 SECS
- SEVERAL LOW SCALE LPPM READINGS ON EAST SIDE
- 76 CRDs DID NOT FULLY INSERT

7/29/80

57		2	2	0	0		
		0	0	0	20*		
		0	0	0	0		
		0	0	0	0		*Failed
49	2	4	4	0	0	1	
	0	2	0	0	0	0	
	0	0	0	0	0	0	
	0	0	0	0	0	0	
41	3	3	6	0	0	0	0
	2	2	6	0	0	0	0
	0	0	0	0	0	0	0
	0	0	0	0	0	0	0
33	6	8	3	0	0	0	0
	3	4	2	0	0	0	0
	0	0	0	0	0	0	0
	0	0	0	0	0	0	0
25	9	10	9	2	0	0	0
	>0	0	4	0	0	0	0
	0	0	0	0	0	0	0
	0	0	0	0	0	0	0
17	>0	10	7	2	0	0	0
	6	6	4	0	0	0	0
	0	0	0	0	0	0	0
	0	0	0	0	0	0	0
09	D	4	4	0	0	0	
	C	0	2	0	0	0	
	B	0	0	0	0	0	
	A	0	0	0	0	0	
	08	16	24	32	40	48	56

LPRM READINGS FOLLOWING SCRAM #1

CONTROL ROD POSITION VS SCRAM INSERTION TIME



7/29/80
32

01818-1

SECOND SCRAM

• OPERATOR ACTIONS

- MANUAL SCRAM 6 MIN 04 SECS AFTER INITIAL SCRAM
- RESET SCRAM 7 MIN 03 SECS AFTER INITIAL SCRAM

• OPERATOR OBSERVES

- ALL SCRAM VALVES OPEN
- ALL ACCUMULATORS DISCHARGED
- SOME ROD MOVEMENT
- OTHER PLANT PARAMETERS NORMAL

• OTHER SIGNIFICANT INFORMATION

- RODS FULL OUT 0
- RODS PARTIALLY IN 59
- RODS FULL IN 126

PRIOR TO SCRAM #2

59				40	4	36	42			
55				36	46	38	2			
51				36	34		36	42	10	
47				47		20		24		
43	12	40	44		30	28	40	38		
39	24		40			34	32			
35	30	4	38		18	8	34	30		
31	22	10		34	28	2				
27	42	36	30	14	26	28	36	24		
23	8		38	32		12	36	2		
19	34	42	34	20	10	28	22	26		
15		40		36		38				
11			26	6	14	40	40	24		
07					40	2				
03					28	42	42	30		

0131

02 06 10 14 18 22 26 30 34 38 42 46 50 54 58

AFTER SCRAM #2

59				30		14	18				
55				26	42	28					
51				12	22	28	34				
47				30			12				
43				30	38		14	4	30	26	
39				8		30		26	14		
35				14		30		4	22	20	
31				8			14	12			
27				26	22	20	2	12	12	16	2
23						30	20			16	
19				10	26	24			8	6	4
15					18		18		28		
11					12			32	30	14	
07							30				
03								2	34	22	4

0136

02 06 10 14 18 22 26 30 34 38 42 46 50 54 58

14

THIRD SCRAM

● OPERATOR ACTIONS

- MANUAL SCRAM 7 MIN 56 SECS AFTER INITIAL SCRAM
- RESET SCRAM 11 MIN 21 SECS AFTER INITIAL SCRAM

● OPERATOR OBSERVES

- ALL SCRAM VALVES OPEN
- ALL ACCUMULATORS DISCHARGED
- SOME ROD MOVEMENT
- OTHER PLANT PARAMETERS NORMAL

● OTHER SIGNIFICANT INFORMATION

- RODS PARTIALLY IN 46
- RODS FULL IN 139

PRIOR TO SCRAM #3

59			30		14	18				
55			26	42	28					
51			12	22		28	34			
47			30			12				
43			30	38		14	4	30	26	
39			8		30		26	14		
35			14		30		4	12	20	
31			8			14	12			
27			26	22	20	2	12	16	2	
23					30	20		16		
19			10	26	24			8	6	4
15			18		18		28			
11				12			32	30	14	
07						30				
03						2	34	22	4	

0136

02 06 10 14 18 22 26 30 34 38 42 46 50 54 58

AFTER SCRAM #3

59			24							
55			20	40	22					
51			16		24	30				
47			26			6				
43			24	36		2		24	18	
39			2	24		20				
35			6	26				14	16	
31					2	4				
27			18	16	14	2	4	6	2	
23				26	12			2		
19			16	18				2	2	
15			4	10		>0				
11				6		28	26	8		
07					24					
03						30	10			

0137

02 06 10 14 18 22 26 30 34 38 42 46 50 54 58


FOURTH SCRAM

- OPERATOR ACTIONS
 - AUTO SCRAM WHEN SDV HIGH LEVEL BYPASS REMOVED 14 MINUTES 01 SECONDS AFTER INITIAL SCRAM
 - RESET SCRAM 16 MINUTES 27 SECONDS AFTER INITIAL SCRAM

- OPERATOR OBSERVES
 - ALL RODS IN -- SCRAM APPEARED NORMAL
 - ALL SCRAM VALVES OPEN
 - ALL ACCUMULATOR DISCHARGED
 - PLANT PARAMETERS NORMAL

- OTHER SIGNIFICANT INFORMATION
 - SDV HIGH SCRAM TRIP RESET 9 MINUTES 02 SECONDS AFTER SCRAM RESET
 - SDV NOT DRAINED ALARM RESET 9 MINUTES 51 SECONDS AFTER SCRAM RESET


PRIOR TO SCRAM #4



0137

02 06 10 14 18 22 26 30 34 38 42 46 50 54 58

AFTER SCRAM #4



02 06 10 14 18 22 26 30 34 38 42 46 50 54 58

SCRAM SUMMARY

<u>SCRAM/RESET</u>	<u>TIME AFTER INITIAL SCRAM</u>	<u>TIME SDV ALLOWED TO DRAIN</u>
INITIAL SCRAM RESET	0 4 MIN 27 SEC	
SECOND SCRAM RESET	6 MIN 04 SEC 7 MIN 03 SEC	1 MIN 37 SEC
THIRD SCRAM RESET	7 MIN 56 SEC 11 MIN 21 SEC	53 SECONDS
FOURTH SCRAM RESET	14 MIN 01 SEC 16 MIN 27 SEC	2 MIN 40 SEC
		9 MIN 51 SEC

7/29/80
18

BF3 INCOMPLETE CONTROL ROD INSERTION
SEQUENCE OF EVENTS

6/27/80
22 12 00

Browns Ferry Unit 3 commenced a routine shutdown to perform maintenance on a reactor feedwater pump discharge line. The initial power reduction from 1082 MWE to 542 MWE was performed by slowly reducing recirculation flow through the reactor core by recirculation pump speed reduction.

6/28/80
00 55 00

With the recirculation pump operating at minimum speed, additional power reduction to 400 MWE was accomplished by normal insertion of selected control rods.

The plant conditions following this power reduction were normal and as follows:

Power Level	36% of Rated
Core Flow	29×10^6 lbs. per hr.
Reactor Pressure	920 psi
Vessel Level	35 inches (203 inches above the top of the active fuel)
Generator Output	400 MWE
Steam Flow	4.9×10^6 lbs. per hr.
Feedwater Flow	4.9×10^6 lbs. per hr.
Control Rod Pattern	157 control rods were fully withdrawn 10 rods were fully inserted 18 rods were at intermediate position (see Attachment 1)

01 31 16 (T₀)

A manual scram was initiated to complete the power reduction. This was a normal part of the Browns Ferry shutdown procedure.

Within several seconds after the scram, in accordance with normal procedures, the scram discharge volume (SDV) bypass was placed in

"bypass" position, the reactor mode switch was placed in "shutdown" position, and insertion of the source range monitors (SRMs) and intermediate range monitors (IRMs) were initiated.

Within several seconds (approximately 5 to 10) after this scram, operating personnel noted that:

- o The blue source range and intermediate range accumulator lights were as expected.
- o A number of rods on the east side of the reactor were indicated to be not fully inserted.

During this entire sequence of events, operating personnel observed that key plant parameters (pressure, level, temperatures and flows) were well within safe limits even though a number of control rods were not fully inserted.

Subsequently, a review of plant recorders and process computer printout showed:

- o A total of seventy rods did not fully insert. Another six rods settled at either position 02 or 04. The extent of insertion varied from about 5 percent of fully inserted to 90 percent of fully inserted for these partially inserted rods. The rod pattern at this time is shown by Attachment 1.

- o During and after this scram, no other unusual or unexplained variations in plant parameters were observed.

Reactor pressure decreased from 920 to approximately 900 psi (this pressure remained approximately constant throughout the remainder of the event.)

Core flow decreased to 22×10^6 lbs. per hr. This decrease was due to the loss of natural circulation driving head when reactor power was reduced.

Based on steam flow, the heat generation within the reactor was very close to the heat generation expected from decay heat alone, verifying that the insertion of the rods had virtually stopped the fission process.

01 31 24 ($T_0 + 8$ sec.)

Low reactor water level trip occurred. (This corresponds to Level 3 which is 180.5 inches above the top of the active fuel.) The water level decrease was due to void collapse following the scram. From plant recorders it was later verified that the minimum water level reached during this event remained above the level required for emergency core cooling system initiation. (This corresponds to Level 2 which is 130 inches above the top of the active fuel.)

The level variation, including maximum and minimum values, was well within the expected range during a normal scram.

01 31 34 ($T_0 + 18$ sec.)

The scram discharge volume "high-high" level was reached. This occurred 18 seconds after the manual scram. This normally occurs approximately 40 seconds after a scram. Subsequent investigation confirmed that all "high-high" instrument volume level switches were properly calibrated and functioning.

01 31 40 ($T_0 + 24$ sec.)

The main turbine was tripped as part of normal procedure.

01 32 01 ($T_0 + 45$ sec.)

The low reactor water level trip was reset.

Upon achieving normal water level, one feedwater pump, two condensate booster pumps and one condensate pump were secured.

01 35 43 (T_0 + 4 min.
27 sec.)

The scram was reset again and the hydraulic control unit accumulators were recharged until the lights cleared.

01 37 20 (T_0 + 6 min.
4 sec.)

A second scram was manually initiated for the purpose of inserting the remaining seventy rods. Within several seconds after this scram, operating personnel observed that:

- o all blue scram lights and accumulator lights were lit and scram pilot lights were out as expected.
- o Rod movement was indicated, but motion appeared slower than normal.
- o Some rods were indicated to be not fully inserted.

Subsequent review of plant recorders and printouts indicated that:

- o a total of 59 rods were still not fully inserted. The rod pattern at this time is shown by Attachment 3. Major plant parameters (steam flow, core flow, water level and reactor pressure) remained essentially unchanged throughout the scram.
- o Fluctuations of IRM sensor readings prevent determination of actual effects due to the scram.

01 38 19 (T_0 + 7 min. 3
sec.)

The scram was reset and the hydraulic control unit accumulators recharged until the lights cleared.

01 39 12 (T_0 + 7 min. 56
sec.)

A third manual scram was initiated. Operating personnel observed that:

- o all blue scram lights and accumulator lights were lit and scram pilot lights were out.
- o Rod movement was indicated.
- o Some rods were indicated to be not fully inserted.

Information obtained later from plant recorders showed that:

- o a total of 47 rods were still not fully inserted. The rod pattern at this time is shown by Attachment 4.
- o LPRM readings all indicated "0" except 40-57C which was failed.
- o All major parameters discussed above, remained approximately constant throughout this scram.

01 42 37 ($T_o + 11$ min.
21 sec.)

The scram was reset for the third time and the hydraulic control unit accumulators were recharged until the lights cleared.

01 43 11 ($T_o + 14$ min.
01 sec.)

The operator placed the scram discharge volume (SDV) bypass switch in "normal" which resulted in a scram since the SDV was not actually fully drained. This was the fourth scram in this sequence of events.

Operating personnel observed that:

- o rod insertion rate appeared normal for a scram
- o all blue scram lights and accumulator lights were lit
- o all rods were indicated to be fully inserted
- o Plant parameters and conditions were as normally expected following a scram.

01 46 30 ($T_o + 15$ min.
14 sec.)

The operator initiated a manual scram (confirmatory).

01 47 43 ($T_o + 16$ min.
27 sec.)

The scram was reset.

01 57 04 ($T_o + 25$ min.
48 sec.)

The scram discharge volume "High-High" trip was reset.

01 57 34 ($T_o + 26$ min.
18 sec.)

The discharge volume high water level trips (50 gallon scram trips) cleared.

POST-INCIDENT INSPECTIONS

14

- HYDRAULIC CONTROL UNIT VALVE LINEUP VERIFIED CORRECT
- DRAIN AND VENT VALVES DEMONSTRATED OPERABLE
- INSTRUMENT VOLUME LEVEL SWITCHES CALIBRATED. ALL 50 GALLON (SCRAM) SWITCHES WERE TESTED. THREE (3) AND 25 GALLON SWITCHES DID NOT OPERATE ON FIRST CALIBRATION ATTEMPT (ALTHOUGH SWITCHES DID OPERATE DURING INCIDENT)
- REVIEWED SCRAM HISTORY FOR BF-1, 2, AND 3. OUT OF 320 SCRAMS, NO RELATED INCIDENTS. ALSO PERFORMED DETAILED ANALYSIS OF RECENT U-3 SCRAMS. NO MALFUNCTION FORECASTED
- REVIEWED HISTORY OF CONTROL ROD DRIVE OPERATIONS, MAINTENANCE, AND MODIFICATION ACTIVITIES. NO APPARENT RELATIONSHIP
- INSPECTED AIR LINE SUPPLIES TO HCU'S AND VALVES
- REVIEWED CRD TEMPERATURE LOGS FOR INDICATION OF EXCESSIVE SEAL LEAKAGE. NONE FOUND ON EAST SIDE
- PERFORMED PHYSICAL INSPECTION OF VENT LINES, 2" DRAIN LINE, SCRAM HEADER, AND INSTRUMENT VOLUME BY CUTTING PIPE AND USING BOROSCOPE. NO OBSTRUCTIONS FOUND. ALSO INSPECTED ROD-WASTE SUMP FOR LARGE OBJECTS. NONE FOUND
- PERFORMED COMPREHENSIVE TESTS ON EAST SIDE CRD'S, FRICTION TESTS, STILL FLOW, SCRAM TIMING. ALL RESULTS NORMAL
- PERFORMED FLOW AND DRAINAGE TESTS ON U-3 SCRAM DISCHARGE SYSTEM. INDICATED NORMAL OPERATION
- PERFORMED ADDITIONAL ELECTRICAL TESTING OF PPS LOGIC AND OPERATION. EVERYTHING FUNCTIONED AS EXPECTED
- REQUESTED GE PERFORM CONFIRMATORY TESTING TO DEMONSTRATE THAT WATER IN VOLUME WOULD PRODUCE OBSERVED RESULTS

15

CAUSE OF INCOMPLETE INSERTION

CONCLUSION

- THE BROWNS FERRY 3 EVENT WAS CAUSED BY UNDETECTED WATER IN THE EAST SCRAM DISCHARGE VOLUME

- WATER WAS PRESENT DUE TO A RESTRICTION IN THE EAST SDV DRAINAGE SYSTEM

- SINCE NO EVIDENCE OF A RESTRICTION COULD PHYSICALLY BE FOUND, THE CONTRIBUTION OF THE VENT SYSTEM TO THE EVENT CANNOT BE DISCOUNTED

15

CAUSE DETERMINATION

POTENTIAL CAUSES CONSIDERED

- ELECTRICAL
- HYDRAULIC CONTROL UNIT
- CONTROL ROD DRIVE
- SCRAM DISCHARGE VOLUME LEVEL INSTRUMENTATION
- SCRAM DISCHARGE VOLUME
- PHYSICAL INSPECTIONS

SUPPORTING EVALUATIONS

- SAN JOSE DRIVE TESTS
- INSERTION VARIATIONS
- ANALYTICAL PROGRAMS

POST EVENT TESTS

- DRAIN TESTS

NJB
7/29/80
23

15

CAUSE DETERMINATION

- ELECTRICAL

- EVALUATION:

- RESULTING CHECKERBOARD PATTERN NOT CONSISTENT WITH OBSERVED INCOMPLETE ROD INSERTION PATTERN
- ROD MOTION WOULD BE EITHER COMPLETE OR NO MOTION
- POST EVENT SCRAM TESTS SHOWED ACTUATION CIRCUITRY FUNCTIONAL
- ELECTRICAL INDEPENDENCE OF EACH ROD SCRAM GROUP VERIFIED

- CONCLUSION:

NOT CAUSE OF BROWNS FERRY 3 PARTIAL ROD INSERTION

CAUSE DETERMINATION

- HYDRAULIC CONTROL UNIT

- EVALUATIONS:

- HYDRAULIC CONTROL UNIT VALVE LINE-UP VERIFIED AS NORMAL
- ACCUMULATOR CONDITION VERIFIED IN CONTROL ROOM
- CONTROL ROOM INDICATION OF PROPER SCRAM INLET/OUTLET VALVES
- NO EVIDENCE OF MALFUNCTIONS IN THE PNEUMATIC SYSTEM
- POST-EVENT SCRAM TIME MEASUREMENTS CONSISTENT WITH PREVIOUSLY MEASURED VALUES
- NO APPARENT CONTRIBUTION BY MAINTENANCE ACTIVITIES
- WEST BANK DRIVES PERFORMED NORMALLY

- CONCLUSION:

NOT CAUSE OF BROWNS FERRY 3 PARTIAL ROD INSERTION

NJB
7/29/80
25

CAUSE DETERMINATION

- CONTROL ROD DRIVE

- EVALUATIONS:

- WEST BANK DRIVES PERFORMED NORMALLY
- POST EVENT SCRAM TIME MEASUREMENTS CONSISTENT WITH PREVIOUSLY MEASURED VALUES
- POST EVENT TESTS (FRICTION, STALL FLOW) RESULTS NORMAL
- DRIVE OPERATING TEMPERATURES NORMAL
- NO UNUSUAL MAINTENANCE HISTORY

- CONCLUSION:

NOT CAUSE OF BROWN'S FERRY 3 PARTIAL ROD INSERTION

NJB
7/29/80
26

CAUSE DETERMINATION

- SCRAM DISCHARGE INSTRUMENT VOLUME LEVEL INSTRUMENTATION

- EVALUATION:

- WOULD CAUSE BOTH EAST AND WEST BANK FAILURES
- SCRAM SENSOR OPERATION DURING EVENT VERIFIED BY PROCESS COMPUTER
- POST-EVENT CALIBRATION DEMONSTRATED THAT SCRAM SENSORS OPERATIONAL
- SDV VENT & DRAIN VALVES WERE VERIFIED TO BE OPERATING PROPERLY

- CONCLUSION:

NOT CAUSE OF BROWNS FERRY 3 PARTIAL ROD INSERTION

CAUSE DETERMINATION

● SCRAM DISCHARGE VOLUME

● EVALUATION:

- DRIVES NOT FULLY INSERTED ALL IN EAST BANK
- WEST BANK DRIVES SCRAMMED NORMALLY
- SCRAM LEVEL SWITCHES TRIPPED IN 18 SECONDS
(NORMAL 40/50 SECONDS)
- SDV VENT & DRAIN VALVES OPERATED PROPERLY


● CONCLUSION:

WATER IN EAST SCRAM DISCHARGE VOLUME MOST LIKELY
CAUSE OF BROWNS FERRY 3 PARTIAL ROD INSERTION

NJB
7/29/80
28

SAN JOSE TESTING

SCRAM VOLUME PRESSURIZATION TIME VS INDUCED CRD SEAL LEAKAGE VS AVAILABLE PRE-SCRAM VOLUME



CONCLUSION:
 PERFORMANCE OF DRIVE IN TEST FACILITY COMPARABLE
 TO PERFORMANCE OBSERVED AT BROWNS FERRY 3

G1917-1

7/29/80

30

15

CAUSE DETERMINATION

INITIAL VOLUME (GALLONS)	PERCENT VOLUME	TIME (SECONDS)* INDUCED LEAKAGE	
		"0" GPM	9.0 GPM
0.5	85	1.6	1.5
0.0	100	0.2	0.2


*TIME FOR SCRAM DISCHARGE VOLUME TO REACH 1000 PSIG.

7/29/80

31


SIMULATION OF 6/28 INCOMPLETE SCRAM - BF-3

HEADER PRESSURE vs TIME



01818-6
7/29/80
34


NORMAL SCRAM REDUCED POWER LEVEL



01818-5

7/29/80

35



BF-3 Incomplete CRD Scram
 Transient Model Simulation

Conditions: Partial Blockage of East Header Drain
 91% Filled East Header
 5.0 sec Vent and Drain Valve Closure

Figure 9 Instrument Tank level - Condition #1

GENERAL ELECTRIC COMPANY
 Schenectady, N.Y., U.S.A.
 100A140 7-5000
 Division

CAUSE DETERMINATION

SOURCES OF WATER

- OUTLET SCRAM VALVE LEAKAGE
- NORMAL WATER DISCHARGE DURING AND FOLLOWING SCRAM
- INTRODUCTION OF WATER FROM VENT SYSTEM
- INTRODUCTION OF WATER FROM DRAIN SYSTEM
- FLUSHING CONNECTIONS FOR DECONTAMINATION

INADEQUATE DRAINAGE

INVESTIGATION OF CAUSE OF WATER IN EAST
SDV HYDRAULIC SYSTEM

- INSPECTION FOR RESTRICTION -- NONE FOUND
 - 6" HEADERS
 - 2" DRAIN
 - INSTRUMENT VOLUME
 - DRAIN TO EQUIPMENT DRAIN TANK

- SCRAM VENT LINE NOT RESTRICTED

- VERIFIED SLOPE AND ELEVATION ON TWO-INCH DRAIN LINE TO INSTRUMENT VOLUME

- VERIFIED SLOPE AND ELEVATION OF SCRAM DISCHARGE VOLUME


NJB
7/29/80
29

CAUSE OF INCOMPLETE INSERTION

CONCLUSION

- THE BROWNS FERRY 3 EVENT WAS CAUSED BY UNDETECTED WATER IN THE EAST SCRAM DISCHARGE VOLUME
- WATER WAS PRESENT DUE TO A RESTRICTION IN THE EAST SDV DRAINAGE SYSTEM
- SINCE NO EVIDENCE OF A RESTRICTION COULD PHYSICALLY BE FOUND, THE CONTRIBUTION OF THE VENT SYSTEM TO THE EVENT CANNOT BE DISCOUNTED

BROWNS FERRY 3 DRAIN TESTS



REACTOR BUILDING EQUIPMENT
DRAIN TANK

TIME TO DRAIN 6" HEADER SYSTEM			
<u>EAST</u>		<u>WEST</u>	
MEASURED	25.5 MIN.	MEASURED	9.5 MIN.
CALCULATED	23 MIN.	CALCULATED	10 MIN.
TOTAL VOLUME DRAINED 750 GALLONS (APPROXIMATELY)			

SUBSEQUENT ACTIVITIES

UNIT 3 FLOW TESTS

- PLANT MAINTENANCE, CHATTANOOGA ENGINEERING, TVA DESIGN, AND GE ALL INVOLVED DIRECTLY IN TESTING
- PROVIDED DETAILED INFORMATION ON SYSTEM DRAINAGE AND OVERALL CHARACTERISTICS OF SYSTEM, CONTRIBUTION OF VENTS
- POINTED OUT LIMITATIONS OF LEVEL INSTRUMENTATION
- GOOD BASELINE DATA TO COMPARE SYSTEM OPERATION IN FUTURE
- INDICATED SYSTEM AREAS WHICH WARRANT IMPROVEMENT

IE BULLETIN 80-17 TESTS

- INVOLVED 2 SCRAMS ON EACH UNIT
- TESTING INVOLVED RPS ELECTRICAL SYSTEM, CRD MECHANICAL, DRAIN AND VENT VALVES, SCRAM DISCHARGE HEADER
- INDICATES BF 1, 2, AND 3 CRD SYSTEMS WORKING NORMALLY

SYSTEM CHANGES

- UT MONITORING - CONTINUOUS READOUT MONITORS INSTALLED ON SCRAM HEADER LOWPOINTS
- EXPERIENCE DURING U-3 AND 80-17 TESTING INDICATES UT MONITORING IS RELIABLE

VENTS

- POSITIVE VENT PROVIDED ON EAST AND WEST HEADERS

PROCEDURES AND TRAINING

- EMERGENCY INSTRUCTION WRITTEN DESCRIBING OPERATOR SECTIONS IF WATER DETECTED IN VOLUME
- ALL OPERATORS INFORMED THOROUGHLY ON BF-3 EVENT

DESIGN WORK

- TVA WORKING VIGOROUSLY TO FINALIZE MODIFICATIONS TO ELIMINATE POSSIBILITY OF REOCCURENCE OF THIS TYPE OF EVENT