

LICENSEE EVENT REPORT

CONTROL BLOCK: [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[0][1] N E C P R I [2] 0 0 0 - 0 0 0 0 - 0 0 0 0 [3] 4 1 1 1 1 [4] [ ] [5]
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T REPORT SOURCE [6] L [6] 0 5 0 0 0 2 9 8 [7] 0 7 0 1 8 0 [8] 0 7 3 0 8 0 [9]
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

[0][2] During routine measurement of identified reactor leakage, the drywell equipment
[0][3] drain sump flow instrument was found inoperable. This instrument is required to be
[0][4] operable by Tech. Spec. 3.6.C.2. There were no significant occurrences as a result
[0][5] of this event and there were no adverse affects on the public health and safety.
[0][6] This event is not repetitive.

[0][9] SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
I D E E I N S T R U R Z
EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
8 0 0 2 6 0 3 L 0
LER/RO REPORT NUMBER ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
A Z Z Z 0 0 0 0 N 24 N B 0 4 0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

[1][0] The flow instrument failed due to a broken slide wire in the recorder and a blown
[1][1] fuse in the power supply. The slide wire failure is attributed to natural end of
[1][2] life. The fuse failure was likely a result of the slide wire failure. The slide wire
[1][3] was manufactured by Bailey Instruments, Part No. 6170K62G700. The fuse and slide
[1][4] wire were replaced and the equipment returned to service.

[1][5] FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
E 0 9 2 NA A Operator Observation

[1][6] ACTIVITY CONTENT RELEASSED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
Z Z NA NA

[1][7] PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
0 0 0 Z NA

[1][8] PERSONNEL INJURIES NUMBER DESCRIPTION
0 0 0 NA

[1][9] LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
Z NA

[2][0] PUBLICITY ISSUED DESCRIPTION
N NA

8008260535

GPO 017-226