



Public Service Company of Colorado

16305 ROAD 19½
PLATTEVILLE, COLORADO 80651

July 25, 1980
Fort St. Vrain
Unit No. 1
P-80230

Mr. Karl V. Seyfrit, Director
Nuclear Regulatory Commission
Region IV
Office of Inspection and Enforcement
611 Ryan Plaza Drive
Suite 1000
Arlington, Texas 76012

Reference: Facility Operating License
No. DPR-34

Docket No. 50-267

Dear Mr. Seyfrit:

Enclosed please find a copy of Reportable Occurrence Report No. 50-267/
80-35, Final, submitted per the requirements of Technical Specification
AC 7.5.2(b)2.

Also, please find enclosed one copy of the Licensee Event Report for
Reportable Occurrence Report No. 50-267/80-35.

Very truly yours,

Don Warembourg

Don Warembourg
Manager, Nuclear Production

DW/clis

Enclosure

cc: Director, MIPC

A002
s
1/1

8008280 548

5

OCCURRENCE REPORT DISTRIBUTION

| | <u>Number of Copies</u> | |
|---|-------------------------|---|
| Department of Energy - - - - - San Francisco Operations Office Attn: California Patent Group 1333 Broadway Oakland, California 94612 | 1 | (P Letter) |
| Department of Energy - - - - - Office of Nuclear Engineering Programs Washington, D.C. 20545 | 1 | (P Letter) |
| Department of Energy - - - - - Mr. Glen A. Newby, Chief HTR Branch Division of Nuclear Power Development Mail Station B-107 Washington, D.C. 20545 | 1 | (P Letter) |
| Department of Energy - - - - - Attn: Senior Program Coordinator P. O. Box 81325 San Diego, California 92138 | 1 | (P Letter) |
| Mr. Karl V. Seyfrit, Director - - - - - Region IV Office of Inspection and Enforcement Nuclear Regulatory Commission 611 Ryan Plaza Drive Suite 1000 Arlington, Texas 76012 | 1 | (Original of P Letter and Copy of LER) |
| Director - - - - - Office of Management Information and Program Control U. S. Nuclear Regulatory Commission Washington, D.C. 20555 | 1 | (P Letter, LER) |
| W. Bushnell, Site Manager - - - - - General Atomic Company P. O. Box 426 Platteville, Colorado 80651 | 10 | (Original of FPLG Letter plus Two Copies, One Copy of P Letter, One Copy of LER) |
| NRC Resident Site Inspector - - - - - | 1 | (P Letter, LER) |

REPORT DATE: July 25, 1980

REPORTABLE OCCURRENCE 80-35

OCCURRENCE DATE: June 25, 1980

ISSUE 0

Page 1 of 3

FORT ST. VRAIN NUCLEAR GENERATING STATION
PUBLIC SERVICE COMPANY OF COLORADO
16805 WELD COUNTY ROAD 19 1/2
PLATTEVILLE, COLORADO 80651

REPORT NO. 50-267/80-35/03-L-0

Final

IDENTIFICATION OF
OCCURRENCE:

During the regeneration of a batch of condensate polisher resin, waste water was discharged to the plant liquid effluent system instead of the waste neutralizing tank. This resulted in a degraded mode of LCO NR 1.1, and is reportable per Fort St. Vrain Technical Specification AC 7.5.2(b)2.

EVENT
DESCRIPTION:

On June 25, 1980, at approximately 1100 hours, the valves which control the discharge path of waste water from the condensate polisher resin regeneration system did not automatically line up properly and discharged the waste acid and caustic used in resin regeneration to the Turbine Building sump instead of the waste neutralization tank. This resulted in the waste water being discharged to the yard drain and then to the Goosequill Ditch.

Fort St. Vrain Technical Specification LCO NR 1.1 requires that the regeneration effluent be stored in lined evaporation ponds, and establishes limits for various chemicals in the effluent. The discharge of the regeneration waste water to the Goosequill Ditch was not in accordance with the Technical Specification. Three of the chemical limits of LCO NR 1.1 were exceeded as noted below

| <u>Constituent</u> | <u>Maximum Concentration Or Value</u> | <u>Actual Value</u> |
|--------------------|---|-------------------------|
| Cu | 1 ppm | 1.3 ppm |
| Zn | 5 ppm | 9.2 ppm |
| pH | 6.0 - 9.0 | 1.9 - 9.8 |

EVENT

DESCRIPTION: (Cont'd)

The remaining requirements of the LCO were satisfied as the liquid effluent did follow the prescribed discharge paths.

When the abnormal Goosequill chemistry was observed, the possible sources were investigated and the problem with the condensate polisher resin regeneration system was discovered. Immediate action was taken to terminate the release of regeneration chemicals by manually overriding the discharge path selector and putting all the waste water to the neutralizing tank. Corrective action returned chemical constituents to acceptable concentrations within the 24 hours required.

CAUSE

DESCRIPTION:

The inadvertent discharge of the regeneration waste water was due to a failed conductivity cell in the waste water line which prevented proper automatic valve line up. This equipment failure could not have been avoided or the discharge prevented by more frequent process sampling or testing of the instrument.

CORRECTIVE


ACTION:


Immediate action consisted of manually directing regeneration waste water to the neutralizing tank.


Followup actions were to continue the sampling until chemical concentrations were within LCO NR 1.1 limits. The conductivity element was replaced, and discharge valve operability was verified.

No further corrective action is anticipated or required.

Prepared By: 
Asa B. Reed
Technical Services Technician

Reviewed By: 
J. W. Gahm
Technical Services Supervisor

Reviewed By: 
Frank M. Mathie
Operations Manager

Approved By: 
Don Warembourg
Manager, Nuclear Production