

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6 7 8 9 10										(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)																																							
0 1 MAY K R 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5										7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50																																							
CON'T 0 1 REPORT SOURCE L 0 5 0 0 0 0 2 9 7 0 7 2 1 8 0 8 0 8 2 0 8 0 9										7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50																																							
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10																																																	
0 2 During a maintenance outage while in Mode 5 yard hydrant number 11 and 1																																																	
0 3 8 were individually removed from service to repair leaking valves. The																																																	
0 4 hydrants are required to be operational per T.S. 3.7.10.4. Since the hyd																																																	
0 5 rants were operational prior to removal from service and hoses of equal																																																	
0 6 capacity were routed to protect the area normally covered by the hydrant																																																	
0 7 s there were no adverse effects to the public health or safety.																																																	
0 8																																																	
0 9																																																	
SYSTEM CODE AB 11 CAUSE CODE E 12 CAUSE SUBCODE F 13 COMPONENT CODE VALVEX 14 COMP. SUBCODE F 15 VALVE SUBCODE D 16																																																	
17 LER/RO REPORT NUMBER 18 8 0 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50																																																	
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB PRIME COMP. SUPPLIER COMPONENT MANUFACTURER																																																	
A 18 Z 19 Z 20 Z 21 0 0 0 0 22 N 23 N 24 A 25 K 0 7 5 26																																																	
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27																																																	
1 0 The root cause of this event was the wearing of the fiber disc and seat																																																	
1 1 due to valve cycling. The valves are Model 150 manufactured by the Kenne																																																	
1 2 dy Valve Co. The valves disc, seat, and drain were replaced in kind and																																																	
1 3 the valves were returned to service. No further action is required.																																																	
1 4																																																	
FACILITY STATUS 1 5 G 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50																																																	
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36																																																	
1 6 Z 33 Z 34 NA 35 NA 36																																																	
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39																																																	
1 7 0 0 0 37 Z 38 NA 39																																																	
PERSONNEL INJURIES NUMBER DESCRIPTION 41																																																	
1 8 0 0 0 40 NA 41																																																	
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43																																																	
1 9 Z 42 NA 43																																																	
PUBLICATION ISSUED DESCRIPTION 45 8008260 558 46 47 48 49 50																																																	
2 0 N 44 NA 45 46 47 48 49 50																																																	
NAME OF PREPARER L. D. French PHONE (413) 625-6140																																																	