## LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 N E C P R 1 2 0 0 - 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 6 7 CAT 58
CON'T  O 1  SOURCE L 6 0 5 0 0 0 2 9 8 7 0 7 0 9 8 0 8 0 7 1 7 8 0 9  TO 1 8 SOURCE SO
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  During normal operation, condenser cooling water outlet temperature limit of
0 3 103°F was exceeded. No effect on public health and safety. During the event a
need for emergency power existed and the limit was exceeded in accordance with
o so our Technical Specifications.
0 6
0 7
7 8 9
SYSTEM CAUSE SUBCODE COMPONENT CODE SUBCODE SU
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
Event caused by abnormally high river temperature and removal of several rows of
low pressure turbine blades. Event was terminated when power was reduced after
hours of peak demand.
13
14 2 8 9
FACILITY STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32  T 5 E 28 1 0 0 29 1
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA LOCATION OF SLEASE 36 NA NA NA NA NA NA NA NA NA
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) NA  PERSONNEL INJURIES  PERSONNEL INJURIES  13  80
NUMBER DESCRIPTION 41  I B O O O O NA  1 11 12  BO DUSS OF OR DAMAGE TO FACILITY (43)
TYPE DESCRIPTION  1 9 Z 4 NA  80
PUBLICITY 155UED DESCRIPTION 45 2 0 Z 44 NA
008260 NAME OF PREPARER PAUL J. Borer PHONE PHONE 90.