

# UNITED STATES NUCLEAR REGULATORY COMMISSION REGION IV

811 RYAN PLAZA DRIVE, SUITE 1000 ARLINGTON, TEXAS 76012

August 27, 1980

DCC to DAC:ADM: CENTRAL FILES PDR:HQ LPDR TIC NSIC

Docket No. 50-285

Omaha Public Power District
ATTN: W. C. Jones, Division Manager Production Operations
1623 Harmey Street
Omaha, Nebraska 68102

### Gentlemen:

This IE Information Notice is provided as a notification of a matter of possible safety significance. It is expected that recipients will review the information for possible applicability to their facility, and where applicable, consider the recommended action. If you have questions regarding this matter, please contact the director of this office.

Sincerely,

Karl V. Seyfrit

337 bacentto-

Director

#### Enclosures:

 IE Information Notice No. 80-31

List of recently issued IE Information Notices

cc: S. C. Stevens, Manager Fort Calhoun Station Post Office Box 98

Fort Calhoun, Nebraska 68132

SSINS No.: 6870 Accession No.: 8006190040

# UNITED STATES NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT WASHINGTON, D.C. 20555

IE Information Notice 80-31 Date: August 27, 1980 Page 1 of 2

MALOPERATION OF GOULD-BROWN BOVERI 480 VOLT-TYPE K-600S AND K-DON 600S CIRCUIT BREAKERS

### Description of Circumstances:

The Cincinnati Gas & Electric Company reported probles with the Gould-Brown Boveri Type K-600S and K-DON 600S circuit breakers used in 480 volt a.c. circuits at the William H. 2 mmer nuclear station. The problem involved inadvertent circuit breaker closure during operation of the breaker charging springs when the breaker was racked out to the test position.

The problem resulted from the use of undersized bushings in the circuit breaker secondary close latches. The undersized bushings caused the secondary close latch to hang-up on the shunt trip device resulting in an inadvertent circuit breaker closure when the spring charging motor was energized.

The vendor has stated that the problem does not exist during normal operations with the circuit breaker in the connected position.

## Recommended Action for Licensees and Holders of Construction Permits:

All licensees of operating nuclear power reactors and holders of construction permits should be aware of the potential problems described above. The vendor has stated that a small number of circuit breakers were assembled with undersized secondary latch bushings between 1969 and 1977. It is recommended that the following actions be taken:

- (1) Determine if the subject circuit breakers are installed in any safetyrelated application at your facility. The affected circuit breakers are manufactured by Gould-Brown Boveri and are types K-600S and K-DON 600S, 480-volt a.c electrically operated, drawout type with static trip device.
- (2) If it is determined that your facility has the circuit breakers described in Item (1) above, perform the K-600S, K-DON 600S Field Test Procedure attached to this information notice (Gould-Brown Boveri I.B.-9.1.7-6 Issue F, Addendum 2, dated March 4,
- (3) If maloperation of the circuit brea field test procedure described in I action described in the attached fi 0.050 inch shim to the secondary cl breaker).

DUPLICATE DOCUMENT

Entire document previously entered into system under:

ANO 8006/90040

No. of pages: