

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | T N S N P | 1 | 2 | 0 0 - | 0 0 | 0 0 0 - | 0 0 | 3 | 4 | 1 1 1 | 1 | 4 | 5

7 8 9 14 15 25 26 30 31 32 33 34 35 36

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 56

CONT

0 1 | REPORT SOURCE | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 2 | 7 | 7 | 1 | 1 | 0 | 1 | 8 | 0 | 8 | 1 | 2 | 0 | 1 | 8 | 0 | 9

2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33

REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | With unit 1 in mode 1 at 30% power, loop 1 UT delta T and OP delta T bistables,

0 3 | TS-68-2D/E and TS-68-2G/F respectively, were found out of tolerance and action

0 4 | statement 6 of LCO 3.3.1.1 was entered. There was no effect on public health and

0 5 | safety. Previous occurrences - none. The loop was returned to service after

0 6 | fifteen hours.

0 7 | _____

0 8 | _____

7 8 9

0 9 | SYSTEM CODE | I | A | 11 | CAUSE CODE | B | 12 | CAUSE SUBCODE | B | 13 | COMPONENT CODE | I | N | S | T | R | U | 14 | COMP. SUBCODE | Y | 15 | VALVE SUBCODE | Z | 16

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23

LER/RO REPORT NUMBER | 17 | 8 | 0 | 21 22 | SEQUENTIAL REPORT NO. | 1 | 8 | 1 | 24 25 26 | OCCURRENCE CODE | 0 | 3 | 27 28 29 | REPORT TYPE | L | 30 31 | REVISION NO. | 0 | 32

ACTION TAKEN | E | 18 | 33 | FUTURE ACTION | Z | 19 | 34 | EFFECT ON PLANT | Z | 20 | 35 | SHUTDOWN METHOD | Z | 21 | 36 | HOURS | 0 | 0 | 0 | 37 38 39 | ATTACHMENT SUBMITTED | N | 23 | 40 41 | NRRD-4 FORM SUB. | N | 24 | 42 | PRIME COMP. SUPPLIER | N | 25 | 43 | COMPONENT MANUFACTURER | F | 1 | 8 | 0 | 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | A shift in calibration of TM-68-2A and 2G resulted from elevated room temperature

1 1 | due to loss of control building air conditioning. Room temperature was returned to

1 2 | normal and TM-68-2A and TM-68-2G were recalibrated. The setpoint for instrumentation

1 3 | used to detect a rise in temperature has been decreased so that the operator can

1 4 | take immediate action to restore normal room temperature.

7 8 9

1 5 | FACILITY STATUS | B | 28 | 7 8 9 | % POWER | 0 | 3 | 0 | 29 | 10 11 12 | OTHER STATUS | N/A | 30 | 13 | METHOD OF DISCOVERY | B | 31 | 44 45 46 | DISCOVERY DESCRIPTION | Surveillance test | 32 | 47 48 49 50

1 6 | ACTIVITY CONTENT | Z | 33 | 7 8 9 | RELEASED OF RELEASE | Z | 34 | 10 11 | AMOUNT OF ACTIVITY | N/A | 35 | 12 | LOCATION OF RELEASE | N/A | 36 | 44 45 46 47 48 49 50

1 7 | PERSONNEL EXPOSURES | 0 | 0 | 0 | 37 | 7 8 9 | TYPE | Z | 38 | 10 11 | DESCRIPTION | N/A | 39 | 12 13

1 8 | PERSONNEL INJURIES | 0 | 0 | 0 | 40 | 7 8 9 | DESCRIPTION | N/A | 41 | 10 11 12

1 9 | LOSS OF OR DAMAGE TO FACILITY | Z | 42 | 7 8 9 | TYPE | N/A | 43 | 10 11 | DESCRIPTION | N/A | 44 | 12 13

2 0 | PUBLICITY ISSUED | N | 44 | 7 8 9 | DESCRIPTION | N/A | 45 | 10 11 12 13

NRC USE ONLY

Name of Preparer W. T. Cottle/A. M. Wilkey

Phone 615-842-8261

8012040 396