

# LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | A | L | B | R | F | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | \_\_\_\_\_ | 9  
7 8 9 14 15 25 26 30 37 CAT 38

CON'T  
01 | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 5 | 9 | 7 | 1 | 1 | 0 | 7 | 8 | 0 | 8 | 1 | 2 | 0 | 5 | 8 | 0 | 9  
7 8 60 61 68 69 74 75 80

### EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | During normal operation while performing SI 4.2.B.37, HPCI steam line space high  
03 | temperature switch TS-73-2E was found to trip at 235° F. (T.S.3.2.B). Limit is  
04 | 200° F. or less. There was no effect on the health or safety of the public.  
05 | Redundant switches were operable. Previous events: none

06 | \_\_\_\_\_  
07 | \_\_\_\_\_  
08 | \_\_\_\_\_

09 | I | E | 11 | X | 12 | Z | 13 | I | N | S | T | R | U | 14 | E | 15 | Z | 16 |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20  
17 | LFR RD REPORT NUMBER | 8 | 0 | 21 | 22 | 0 | 8 | 3 | 24 | 26 | 0 | 3 | 28 | 29 | I | 30 | 31 | 0 | 32 |  
18 | ACTION TAKEN | E | 18 | 33 | Z | 19 | 34 | Z | 20 | 35 | Z | 21 | 36 | 0 | 0 | 0 | 0 | 37 | 40 | Y | 23 | 41 | N | 24 | 42 | L | 25 | 43 | F | 0 | 8 | 0 | 44 |

### CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | Fenwal Model 17023-6 temperature switch had drifted. The switch was recalibrated  
11 | and functionally tested for repeatability. No recurrence control action is planned  
12 | due to low failure history.  
13 | \_\_\_\_\_  
14 | \_\_\_\_\_

15 | E | 28 | 0 | 9 | 8 | 29 | NA | 30 | B | 31 | Surveillance Testing | 37 |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80  
16 | Z | 33 | Z | 34 | NA | 35 | NA | 36 |

17 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39 |

18 | 0 | 0 | 0 | 40 | NA | 41 |

19 | Z | 42 | NA | 43 |

20 | N | 44 | NA | 45 |

LER SUPPLEMENTAL INFORMATION

BFRO-50- 259 / 8083 Technical Specification Involved T.S.3.2.B  
Reported Under Technical Specification 6.7.2.b(1)  
Date of Occurrence 11/7/80 Time of Occurrence 1000 Unit 1

Identification and Description of Occurrence:

While performing SI 4.2.B.37, HPCI steam line space high temperature switch TS-73-2E was found to trip at 235° F.

Conditions Prior to Occurrence:

Unit 1 at 98%  
Unit 2 refueling  
Unit 3 at 89%

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe. \_\_\_\_\_

None

Apparent Cause of Occurrence:

Instrument setpoint drift.

Analysis of Occurrence:

There was no effect on the public health or safety, no release of activity, no damage to plant equipment and no significant chain of events.

Corrective Action:

Recalibrated and functionally tested for repeatability.

Failure Data:

None

\*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

\*Revision: 