OPERATIONS SUMMARY

November 1980

At the beginning of the reporting period, the Oyster Creek Nuclear Generating Station was operating at 96.3% capacity (628 MWe). Load was limited by condensate demineralizer differential pressure. The ultimate cause of the differential pressure limitation was the inability of the New Radwaste System to process liquid and solid waste as designed.

Load was reduced temporarily on November 4, 1980 for an ABRO on a condensate demineralizer. On November 7, 1980 load was again reduced for maintenance on "C" feedwater string and \$4 turbine stop valve. After maintenance, full load was reached on November 10, 1980. The plant was shut down on November 21, 1980 for maintenance on "C" High Pressure Feedwater Heater and the North Feedwater Line Check Valve in the Trunion Room. The reactor was started up on November 28, 1980 but delayed through to November 29, 1980 due to problems with containment inerting. The generator came on line on November 29, 1980 and load was being increased at the end of the reporting period.

There were 9 Reportable Occurrences and 3 Non-Routine Environmental Operating Reports during the month:

RO# 80-47 occurred on November 1, 1980 when Core Spray High Drywell Pressure Switches R.V. 46 A, B, C, and D were found to have settings less conservative than Technical Specification requirements.

RO# 80-48 occurred on October 29, 1980 when snubber 23-7 failed functional testing.

RO# 80-49 occurred on November 5, 1980 when Isolation Condenser "B" vent valves were found to be inoperable and Isolation Condenser was inoperable.

RO# 80-50 occurred on November 6, 1980 when Containment Spray High Drywell Pressure Switches IP 15 A, B, C, and D were found to have settings less conservative than Technical Specification requirements.

RO# 80-51 occurred on November 8, 1980 when the daily surveillance for APLHGR, LLHGR, and MCPR was not performed.

RO# 80-52 occurred on November 18, 1980 when Reactor Triple Low Water Level Indicator Switches RE 18A and D were found to have settings less conservative than Technical Specification requirements.

RO# 80-53 occurred on November 30, 1980 when CRD Pumps A and B were made inoperable at separate times to repair a seal water leak.

RO# 80-54 occurred on November 30, 1980 when Core Spray Pumps A and C were temporarily inoperable at separate times when wet by leakage from the CRD pumps.

NREOR# 80-10 occurred on November 11, 1980 when less than two dilution pumps were operating for a period of 25 minutes with ambient intake water temperature less than 60.0°F.

NREOR# 80-11 occurred on November 18, 1980 when ambient intake water temperature dropped resulting in a corresponding drop in the discharge temperature which caused a tropical fish kill.

NRECR# 80-12 occurred on November 11, 1980 when the plant shut down and the resulting discharge temperature drop killed a number of fish in the surrounding waters.

OPERATING DATA REPORT

OFERATING STATUS

UNIT NAME CREEK

DOCKET NUMBER ... 59-219

UTILITY DATA PREPARED BY ... J.B. SKLAR 609-693-6013

REPORTING PERIOD ... November 1980

LICENSED THERMAL POWER (MWT) ... 1930

NAMEPLATE RATING (GROSS MWE) ... 650

DESIGN ELECTRICAL RATING(NET MWE) ... 650

MAXIMUM DEPENDABLE CAPACITY (GROSS MWE) ... 650

MAXIMUN DEPENDABLE CAPACITY(NET MWE) ... 620

IF CHANGES OCCUR IN CAPACITY RATING SINCE LAST REPORT, GIVE REASON...

POWER LEVEL TO WHICH RESTRICTED, IF ANY(NET MWE)... NO RESTRICTION REASON FOR RESTRICTION, IF ANY...
NO RESTRICTION

| HONTH | YEAR | CUMULATIVE |
|----------|--|---|
| 720.0 | 8039.0 | 95903.0 |
| 563.9 | 3046.3 | 71685.6 |
| 9.9 | 0.0 | 468.2 |
| 535.3 | 2918.5 | 79223.9 |
| 9.0 | 9.9 | 9.0 |
| 926688.0 | 4942321.2 | 118821480.5 |
| 369279.0 | 1593960.0 | 40476275.0 |
| 296410.0 | 1522558.0 | 39003571.0 |
| 74.3 | 36.3 | 73.2 |
| 74.3 | 36.3 | 73.2 |
| 66.4 | 30.5 | 67.1 |
| 63.3 | 29.1 | 62.6 |
| 25.7 | 12.2 | 6.7 |
| | '720.0 563.9 0.0 535.3 0.0 926688.0 309270.0 296410.0 74.3 74.3 66.4 63.3 | 720.0 8039.0 563.9 3046.3 0.0 0.0 535.3 2918.5 0.0 0.0 926688.0 4942321.2 309270.0 1593960.0 296410.0 1522558.0 74.3 36.3 74.3 36.3 66.4 30.5 63.3 29.1 |

THE NEXT SCHEDULED OUTAGE IS TO BEGIN ON SPRING OF 1981

AVERAGE DAILY POWER LEVEL

DOCKET \$..... 50-219 UNIT..... 0. C. \$1 REPORT DATE... December 10, 1980

COMPILED BY... J.B. SKLAR TELEPHONE.... 609-693-6013

MONTH November 1980

| DAY | MW | DAY | MW |
|-----|------|-----|------|
| 1. | 602. | 17. | 604. |
| 2. | 604. | 18. | 606. |
| 3. | 604. | 19. | 603. |
| 4. | 582. | 29. | 600. |
| 5. | 513. | 21. | 583. |
| 6. | 588. | 22. | 15. |
| 7. | 593. | 23. | 9. |
| 8. | 335. | 24. | Θ. |
| 9. | 453. | 25. | θ. |
| 10. | 579. | 26. | 0. |
| 11. | 602. | 27. | θ. |
| 12. | 602. | 28. | θ. |
| 13. | 603. | 29. | 9. |
| 14. | 602. | 30. | 302. |
| 15. | 604. | | |
| 16. | 604. | | |
| | | | |

UNIT SHUTDOWNS AND POWER REDUCTIONS

50-219 DOCKET NO. O.C. #1 UNITNAME DATE December 9, 1980 COMPLETED BY J. B. Sklar TELEPHONE __609-693-6013

REPORT MONTH Movember, 1980

| No. | Date | Type1 | Duration (Hours) | Reason | Method of Shurting Down Reactors | Licensee Event Report # | System Cude ⁴ | Component | Cause & Corrective Action to Prevent Recurrence |
|-----|----------|-------|---------------------|--------|--|-------------------------------|-----------------------------|-----------|--|
| 6 | 11-7-80 | F | 0.0 | В | 5 | N/A | ZZ | ZZZZZ | Leaking drain valves on "C" feedwater pump and a flow control valve were replaced. Maintenance was also performed on #4 Turbine stop valve and 1B2 moisture removal valve. |
| 7 | 11-21-80 | P | 184.75 | В | 1 | N/A | 22 | ZZZZZ | Plugged 27 leaking tubes in 1C3 HP Feedwater Heater and repaired seal weld on feed check valve check valve hinge pin. |

F: Forced S: Scheduled

Reason:

A-Equipment Failure (Explain) B-Maintenance of Test

C-Refueling

D-Regulatory Restriction E-Operator Training & License Examination

F-Administrative

G-Operational Error (Explain) II-Other (Explain)

Method: 1-Manual

2-Manual Scram.

3-Automatic Scrain.

4-Other (Explain)

Exhibit G - Instructions for Preparation of Data Entry Sheets for Licensee Event Report (LER) File (NUREG-

0161)

Exhibit 1 - Same Source

(9/77)

MONTHLY QASL MECHANICAL MAINTENANCE REPORT

| System | Malfunction | Corrective Action |
|--------------------------------------|--|---------------------------------|
| Emergency Diesel Generator #1 | Cooling air fan securing bolt failed from fatigue. | Replaced bolt. |
| A CRO Pump | Outboard Bearing oil leak | Repaired Oiler. |
| A CRD Filter | High ▲P across filter | Replaced Filter elements |
| CRD42-11 | V-106 valve leaks past seat | Installed new ball and packing. |
| CRD42-23 | V-106 valve leaks past seat | Installed new ball and packing. |
| CRD 42-07 | V-106 valve leaks past seat | Installed new ball and packing. |
| Emergency Condenser system | V-14-1, 5, 19, 20, 7, 3, 4, 8 packing leaks | Repacked all valves. |
| CRD 38-19 | Packing leak on V-107 | Adjusted packing. |
| CRD 02-27 | V-127 leaks past seat | Replaced disc. |
| CRD Hydraulic Control | V-15-26 and 25 packing leaks | Adjusted packing. |
| Reactor Recirculation Sample Line | V-24-29 diaphragm leaks | Replaced diaphragm |
| Emergency Condenser | V-14-30 packing leaks | Repacked valve |
| CRD 34-31 | V-127 leaking past seat | Replaced seat and gaskets |
| "B" CRD Filter | High ▲P | Replaced filters. |
| CRD 42-07 | V-111 malfunction | Replaced valve. |

NOVEMBER SUMMARY OF QASL ELECTRICAL MAINTENANCE

| Equipment | Malfunction | Corrective Action |
|---|---|--|
| Isolation Condenser Vent Valves | Failed to operate | Replaced valves, troubleshoot entire circuit and verified operability. |
| Core Spray Booster Pump Motors | Wiring entrances not water- proofed adequately | New gaskets for covers installed and waterproofing foam used to seal conduits. |
| Condensate Transfer Pump 1 - 2 | Contactor Chattering | Cleaned contactor and checked current through power leads. |
| Emergency Service Water Pump Motors | Corroded Filters | Replaced with stainless steel type filters. |
| Fire Protection Alarm | Defective ZH-30 Module | Replaced. |
| Diesel Generator 1 - 2 | Fuel transfer pump motor | Replaced motor starting switch (in motor) |
| Diesel Generator 1 - 2 | Voltage regulator rectifier stack assembly (CR5) faulty | Replaced rectifier. |
| Diesel Generator 1 - 2 Battery Charger | Relay STYA faulty | Replaced. |
| Diesel Generator 1 - 2 | Battery Charger | Cleaned burned contact on STYA relay. |
| Diesel Generator 1 - 2 | Battery Charger | Installed temporary charger. |
| Diesel Generator 1 - 1 | Mail breaker light indication out | Replaced light socket (open indication) |
| Service Water Pump 1 - 1 | Motor required replacement | Replaced. |
| Isolation Condenser Valve V-14-30 | Double Indication | Adjusted valve timing. |
| Main Steam Valves V-1-110 | Valve indicates full shut constantly | Torque switch replaced on V-1-110 |
| CRD Pump Motor | Trips out on overload | Replaced overload in breaker. |
| | | |

NOVEMBER SUMMARY OF QASL INSTRUMENT MAINTENANCE

| Equipment | Malfunction | Corrective Action |
|---|---|---|
| Drywell Ventillation Isolation Bypass | Received Alarm | Cleaned contacts of 6K60 and 6K61 |
| Fuel Pool Low Level Alarm | Alarm Indications | Adjusted Bubbler flow. |
| SRM Channel 23 | Period Indication failed | Replaced control module. |
| IRM Channel 14 | Recorder indication different than meter. | Adjusted recorder |
| APRM Channel 3 | Pegged downscale | Replaced a diode in trip aux. unit |
| Reactor Vessel Temp. Recorder | All points printed upscale | Stepping solenoid bearings cleaned and oiled. |
| Area Radiation Monitor - Containment Spray Heat Exchanger D | Failed upscale | Replaced faulty detector |
| Rod Position Indicator 14-11 | Missing pos. 42, 43, 46, and 47 due to open lead | Replaced problem and installed jumper |
| Isol Cond "B" press indicator | Out of calibration | Replaced and calibrated indicator |
| "A" Recirc Flow Indicator | Out of calibration | Replaced and calibrated indicator |
| Accoustic Safety & Relief Valve Indicator | No audible response from NR-108A and NR-28N | Tightened cable connector and replaced accelerometer respectively. |
| ERV-A | ERV-A opened @ approximately .800 psi | Found pressure switch would trip above and below 1000# (i.e., 1050# , and 865#) - Replaced pressure switch assembly. |
| | | |

REFUELING INFORMATION -

Name of Facility: Oyster Creek Station #1

Scheduled date for next refueling shutdown: November 28, 1981

Scheduled date for restart following refueling: May 31, 1982

Will refueling or resumption of operation thereafter require a Technical Specification change or other license amendment?

No Technical Specification change relative to the refueling is anticipated.

Scheduled date(s) for submitting proposed licensing action and supporting information:

No submittals are scheduled.

Important licensing considerations associated with refueling, e.g., new or different fuel design or supplier, unreviewed design or performance analysis methods, significant changes in fuel design, new operating procedures:

- General Electric fuel assemblies fuel design & performance analysis methods have been approved by the NRC. New operating procedures, if necessary, will be submitted at a later date.
- Exxon Fuel Assemblies No major changes have been made nor are there any anticipated.

The number of fuel assemblies (a) in the core - 560

(b) in the spent fuel storage pool - 781

The present licensed spent fuel pool storage capacity and the size of any increase in licensed storage capacity that has been requested or is planned, in number of fuel assemblies:

Present: 1,800 Planned: 2,600

The projected date of the last refueling that can be discharged to the spent fuel pool assuming the present licensed capacity:

The Spring 1987 Outage