

LICENSEE EVENT REPORT

EXHIBIT A

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

| | | | | | | | | | |
|---|--|--|--|--|--|--|--|--|--|
| CONTROL BLOCK | | | | | | | | | |
| AR ANO 2 00 - 0 0 0 0 0 0 - 0 0 1 1 1 1 4 5 | | | | | | | | | |
| L I C E N S E E C O D E L I C E N S E N U M B E R L I C E N S E T Y P E J O 5 7 C A T 5 8 | | | | | | | | | |
| CON'T REPORT SOURCE L 0 5 0 0 0 3 6 8 0 1 0 9 27 1 2 1 5 8 0 9 | | | | | | | | | |
| R E P O R T S O U R C E D O C K E T N U M B E R E V E N T D A T E R E P O R T D A T E | | | | | | | | | |
| E V E N T D E S C R I P T I O N A N D P R O B A B L E C O N S E Q U E N C E S | | | | | | | | | |
| During Power Escalation Testing, Mode 1 steady state operation, the "B" | | | | | | | | | |
| CPC Fail & CEAC indicators; LPD, DNBR, Low Pressurizer Pressure trips | | | | | | | | | |
| were received. Channel "B" CPC was declared inoperable & placed in | | | | | | | | | |
| bypass. The occurrence was coincident with a RS panel ground alarm | | | | | | | | | |
| feeding that PPS channel. Fault flags cleared upon resetting. There | | | | | | | | | |
| have been no similar occurrences. Reportable per T.S. 6.9.1.9.b. | | | | | | | | | |
| | | | | | | | | | |
| SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SURF ISSUE VALVE TAG CODE | | | | | | | | | |
| I A E E IN INSTRU Y Z | | | | | | | | | |
| EVENT YEAR SEQUENTIAL REPORT NO OCCURRENCE CODE HEIGHT TYPE REVISION | | | | | | | | | |
| 7 9 --- 0 0 6 / 0 3 X 1 | | | | | | | | | |
| ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED PERIOD FORV SUR PRIME COMPT SUPPLIER COMPONENT MANUFACTURER | | | | | | | | | |
| E Z Z Z 0 0 0 0 N N N C 4 9 0 | | | | | | | | | |
| CAUSE DESCRIPTION AND CORRECTIVE ACTIONS | | | | | | | | | |
| Requirements of Action Statement T.S. Table 3.3-1 #2 and #6 were met. | | | | | | | | | |
| Channel "B" CPC was returned to service after surveillance within 13 hours | | | | | | | | | |
| of the occurrence. Investigation revealed that the ground fault relays | | | | | | | | | |
| fall out on low bus voltage, not necessarily indicating a ground fault. | | | | | | | | | |
| Root cause could not be determined. Believed to be isolated occurrence related to a pre-operation test as problem has not recurred. | | | | | | | | | |
| FACILITY STATUS POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION | | | | | | | | | |
| B 0 2 0 Pwr. Esc. Test A NA | | | | | | | | | |
| ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE | | | | | | | | | |
| Z Z NA NA | | | | | | | | | |
| PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION | | | | | | | | | |
| 0 0 0 Z NA | | | | | | | | | |
| PERSONNEL INJURIES NUMBER DESCRIPTION | | | | | | | | | |
| 0 0 0 NA | | | | | | | | | |
| LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION | | | | | | | | | |
| Z NA | | | | | | | | | |
| PUBLICITY ISSUED DESCRIPTION | | | | | | | | | |
| N NA | | | | | | | | | |
| NAME OF PREPARER Chris N. Shively PHONE 501/968-2519 | | | | | | | | | |