

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	A	L	B	R	F	1	2	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4		5									
7	8	9	LICENSEE CODE														14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	37	38

CON'T

0	1	L	6	0	5	0	0	0	2	5	7	1	2	1	0	8	0	8	0	1	8	8	1	9			
7	8	REPORT SOURCE				60	61	DOCKET NUMBER					68	69	EVENT DATE					74	75	REPORT DATE					80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During normal operation, while performing SI 4.1.A-7, reactor water level switch LIS-3-203B switch 1 was found 0.43 percent out of T.S. table 3.1.A limit.

0 3

0 4 There was no effect on the health or safety of the public. Redundant switches

0 5 were operable. Previous events: 259/7322, 259/7341, 259/7333, 259/7824, 259/741,

0 6 260/804, 296/8028, and 260/8029.

0 7

0 8

0	9	I	A	X	Z	I	N	S	T	R	U	S	Z														
7	8	SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP SUBCODE		VALVE SUBCODE													
9	10	11	12	13	14	15	16																				
17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44
LEH RD REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.																	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB		PRIME COMP SUPPLIER		COMPONENT MANUFACTURER											
E		F		Z		Z		0000		Y		N		L		B08											

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The Barton Model 288 setpoint had drifted. The switch was inspected, recalibrated

1 1 and functionally tested for repeatability. This switch will be replaced by

1 2 an analog system by DCR 1398.

1 3

1 4

1	5	E	0	9	8	NA	B	Surveillance testing.			
7	8	FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
9	10	11	12	13	14	15	16	17	18	19	20
21	22	23	24	25	26	27	28	29	30	31	32
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE					
Z		Z		NA		NA					
1	7	0	0	0	Z	NA					
7	8	PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION			
9	10	11	12	13	14	15	16	17	18		
19	20	21	22	23	24	25	26	27	28		
PERSONNEL INJURIES		NUMBER		DESCRIPTION							
0		0		0							
1	9	Z	NA								
7	8	LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION					
9	10	11	12	13	14	15	16				
19	20	Z	NA								
7	8	PUBLICITY		ISSUED		DESCRIPTION					
9	10	11	12	13	14	15	16				
19	20	N	NA								

NAME OF PREPAREE _____

PHONE: _____

8102170395

LER SUPPLEMENTAL INFORMATION

BFRO-50- 259 / 8089 Technical Specification Involved Table 3.1.A

Reported Under Technical Specification 6.7.2.b(1)

Date of Occurrence 12/10/80 Time of Occurrence 1415 Unit 1

Identification and Description of Occurrence:

Reactor water level switch LIS-3-203B, operated 0.43% out of technical specification limit.

Conditions Prior to Occurrence:

Unit 1 at 98% power.

Unit 2 at 83% power.

Unit 3 at refueling.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

None

Apparent Cause of Occurrence:

Instrument drift

Analysis of Occurrence:

There was no damage to plant equipment. There was no activity release, no personnel exposure or injury and no danger to the health or safety of the public.

Corrective Action:

Inspected, recalibrated and functionally tested the switch for repeatability.

Failure Data:

259/7322, 259/7341, 259/7333, 259/7824, 259/741, 260/804, 296/8028 and 260/8029.

*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

*Revision: 