LICENSEE EVENT REPORT
CONTROL BLOCK: [ ] [ ] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 MA Y K R 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 6 1 57 CAT 58 5
CON'T  O 1 SOURCE LI GO S O O O O O 2 9 7 0 4 1 6 8 1 8 0 5 1 5 8 1 9  EVENT DESCRIPTION AND PROBABLE CONSEQUENCES TO  O 2 During normal operation, while performing steam generator water level full
ola inctional test Procedure OP-4604, No. 3 SGNR level bistable contact 6 & 8
old did not completely close. The action statement of T.S. 3.3.1 and table
0 5 3.3-1 were achered to during the event. This is the first event of this
[0]6 type. The contact was jumpered (placing a scram signal in one path of th
[0]7 [e logic circuit) and the other three channels remained operational. No a
dverse effect to the public health or safety resulted due to this event.
SYSTEM CAUSE CODE SUBCODE SUBC
LER/RO REPORT NO.  OR REPORT NO.  REPORT NO.  OR R
ion film on the contact surfaces resulting in a resistance of approximat
ely 200 ohms. The bistable is an ET-215 Model manufactured by Rochester
Instrument Systems Inc. The contact surfaces were cleaned. The new resis
tance was less than 1 ohm. No further corrective actions are necessary.
FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DISCOVERY DESCRIPTION 32  1 5 F 28 0 7 3 29 Coastdown B 31 Surveillance Test
7 8 9 10 12 13 44 45 46 80 RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) AMOUNT OF ACTIVITY (35) N/A LOCATION OF RELEASE (36) N/A 80
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)  [1 7 10 1 0 1 0 1 (37)] Z 1(38) N/A
7 8 9 11 12 13 80 PERSONNEL INJURIES (11)
1 8 0 0 0 40 N/A
LOSS OF OR DAMAGE TO FACILITY (43)  TYPE DESCRIPTION N/A  N/A
7 8 9 10 80
SSUED   DESCRIPTION (45)   N/A
8105200 339 EDWIN L. MAY PHONE (413) 625-6140 %