

U.S. NUCLEAR REGULATORY COMMISSION  
LICENSEE EVENT REPORT

/0/1/ CONTROL BLOCK / / / / / / / (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)  
/V/A/N/A/S/1/ (2) /0/0/-/0/0/0/0/0/-/0/0/ (3) /4/1/1/1/1 (4) / / / (5)  
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT  
/0/1/ REPORT SOURCE /L/ (6) /0/5/0/0/0/3/3/8/ (7) /0/4/1/4/8/1/ (8) /0/5/1/5/8/1/ (9)  
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
/0/2/ / On April 14, 1981, with the Unit in Mode 1, the fire damper between Unit 1 and 2 /  
/0/3/ / cable tunnels failed to shut during an operational inspection. Within one hour, /  
/0/4/ / the fire detectors were verified operational and a fire watch was posted. Hence, /  
/0/5/ / the health and safety of the general public were not affected. This Special /  
/0/6/ / Report is being submitted pursuant to T.S. 3.9.2 as called for by T.S. 3.7.15 /  
/0/7/ / (Unit 2) since the fire damper was not made operational within seven days. /  
/0/8/ /

SYSTEM CAUSE CAUSE COMP. VALVE  
CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCODE  
/0/9/ /A/B/ (11) /B/ (12) /A/ (13) /V/A/L/V/E/X/ (14) /X/ (15) /D/ (16)  
SEQUENTIAL OCCURRENCE REPORT REVISION  
LER/RO EVENT YEAR REPORT NO. CODE TYPE NO.  
(17) REPORT

NUMBER /8/1/ /-/ /0/3/1/ / \ / /0/3/ /L/ /-/ /0/  
ACTION FUTURE EFFECT SHUTDOWN ATTACHMENT NPRD-4 PRIME COMP. COMPONENT  
TAKEN ACTION ON PLANT METHOD HOURS SUBMITTED FORM SUB. SUPPLIER MANUFACTURER  
/Z/ (18) /F/ (19) /Z/ (20) Z/ (21) /0/0/0/0/ (22) /Y/ (23) /N/ (24) /L/ (25) /A/1/8/1/ (26)  
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

/1/0/ / The fire damper failed to shut due to binding of the trip cable and misalignment /  
/1/1/ / of the door within its track. An Engineering Work Request was initiated to pro- /  
/1/2/ / pose a solution to improve operability of the damper. The modification has not /  
/1/3/ / been incorporated at this time. /  
/1/4/ /

FACILITY STATUS %POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)  
/1/5/ /E/ (28) /1/0/0/ (29) / NA / (30) /A/ (31) / Fire Marshal Observation /  
ACTIVITY CONTENT  
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)  
/1/6/ /Z/ (33) /Z/ (34) / NA / / NA /  
PERSONNEL EXPOSURES  
NUMBER TYPE DESCRIPTION (39)  
/1/7/ /0/0/0/ (37) /Z/ (38) / NA /  
PERSONNEL INJURIES  
NUMBER DESCRIPTION (41)  
/1/8/ /0/0/0/ (40) / NA /  
LOSS OF OR DAMAGE TO FACILITY (43)  
TYPE DESCRIPTION  
/1/9/ /Z/ (42) / NA /  
PUBLICITY

ISSUED DESCRIPTION (45) NRC USE ONLY  
/2/0/ /N/ (44) / NA / / / / / / / / / / / / / / / / / /  
NAME OF PREPARER W. R. CARTWRIGHT PHONE (703) 894-5151

8105200294

Virginia Electric and Power Company  
North Anna Power Station, Unit 1  
Docket No. 50-338  
Report No. LER 81-031/03L-0

Attachment: Page 1 of 1

#### Description of Event

On April 14, 1981, with the unit in Mode 1, the fire damper between Unit 1 and 2 cable tunnels failed to shut during an operational inspection. Since the fire damper was not made operational within seven days, this Special Report is being submitted pursuant to T.S. 6.9.2 as called for by T.S. 3.7.15 (Unit 2).

#### Probable Consequences of Occurrence

The fire detectors within the cable vaults were verified operational within one hour and a fire watch was posted. Thus, the health and safety of the general public were not affected.

#### Cause of Event

The fire damper failed to shut due to binding of the trip cable and misalignment of the door within its track.

#### Immediate Corrective Action

As required by the action statement, the fire detectors in the area were verified operational and a fire watch was posted. A Maintenance Request was initiated which required an Engineering Work Request since Mechanical Maintenance could not assure that the damper would shut consistently.

#### Scheduled Corrective Action

The Engineering Work Request specifies that the trip wire connecting the damper to the CO<sub>2</sub> blow off for actuation should be flexible enough to pass through two pulleys without binding the damper. Further, the pulleys are rearranged and sized to pass the cable freely. Also, the gravity operated damper is to be weighted to provide more force for closing.

#### Actions Taken to Prevent Recurrence

No further actions are required at this time.

#### Generic Implications

There are no generic implications.