NRC FORM 366 (7-77)

LICENSEE EVENT REPORT
CONTROL BLOCK: [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 N E F C S 1 2 0 0 0 0 0 0 0 0 0 0 3 4 1 1 1 1 1 1 4 57 CAT 58 5
REPORT L 6 0 5 0 0 0 2 8 5 7 0 9 1 0 8 0 8 0 9 1 1 1 8 0 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 Transformer (T4) of DG-1 failed. This transformer feeds the control circuitry for the 15 kw diesel oil immersion heater as well as supplying power to alarm relays for the following items: low lube oil pressure, low lube oil level, high and/or low
o 4 lube oil temperature, water temperature, water level and water pressure. During
the time of the transformer failure, DG-2 as well as the 161 kv and 345 kv systems
were available and operable. In addition, DG-1 was considered inoperable only during
the time that the transformer and associated equipment were being changed out, i.e.
only while DG-1 was in "Local Maintenance".
SYSTEM CODE SUBCODE SU
A moveable armature located on the immersion heater contactor was loose on the plunger
shaft & therefore, causing a slight binding problem on the contactor. It is
postulated that this binding of the contactor caused the contactor control trans-
former to draw excessive current and eventually fail. The moveable armature was re-
paired and the diesel satisfactorily tested and returned to service.
FACILITY STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 1 5 E 28 1 0 0 29 NA LA 31 OPERATOR OBSERVATION 1 6 A 31 OPERATOR OBSERVATION 80
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA LOCATION OF RELEASE 36 NA NA NA NA NA NA NA
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) 1 7 0 0 0 37 Z 38 NA PERSONNEL INJURIES NUMBER DESCRIPTION (41) 1 8 0 0 0 40 NA
LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION NA
PUBLICITY
NAME OF PREPARER R. J. Mueller PHONE: 402-426-4011

LER 80-021 Omaha Public Power District Fort Calhoun Station Unit No. 1 Docket No. 05000285

ATTACHMENT NO. 1

Safety Analysis

The Fort Calhoun Station Unit No. 1 Engineered Safety Features System is so designed that no single failure can prevent the safe shutdown of the plant if necessary. During the time diesel generator DG-1 was inoperable, diesel generator DG-2 was operable as were the 161 KV and 345 KV supplies thus providing more than adequate capability for safe shutdown of the plant should the unlikely event of an accident occur.

It should be pointed out that DG-1 was considered inoperable only during the time that the transformer was being changed out since this transformer only feeds the oil immersion heater for DG-1 and associated annunciation. Should the need have arisen, DG-1 would still have automatically started per engineered safeguards and performed its design function as described in the Final Safety Analysis Report.

Lilling .

LER 80-021 Omaha Public Power District Fort Calhoun Station Unit No. 1 Docket No. 05000285

ATTACHMENT NO. 2

Corrective Action

M.O. #7057 was written to investigate possible causes for the failure of the control transformer. As a result, it was discovered that a moveable armature (moveable in the vertical direction) was loose on the immersion heater contactor's plunger shaft, thus allowing the armature to rotate from 0° to 360° horizontally with respect to the plunger shaft. Normally, when the contactor is picked up or energized the plunger shaft is drawn vertically via magnetic forces until the armature mates with a designated seating surface on the contactor and correspondingly the main contacts are completely closed. However, if the armature is allowed to rotate horizontally such that when the armature and plunger shaft are magnetically drawn upwards, the armature does not mate with its designated contactor seating surface; the result is armature binding and partial closure of the contact main contacts. Further the control transformer will draw excessive amps as it tries to fully close the contactor contacts.

To correct the problem, the armature was secured to the plunger shaft in such a position that proper seating between the armature and armature seating surface of the contact would be achieved.

As a further consequence of this problem, the remaining diesel control panel (DG-2) was inspected for a similar problem. However, the armature shaft was found to be firmly riveted to the plunger shaft.

The failed control transformer was replaced with an electrically equivalent transformer (See EEAR FC-80-101). Any wires or relays which may have been damaged by the transformer overheating were also replaced with identical equipment. The diesel was satisfactorily tested and returned to service.

No further action is planned or scheduled in conjunction with this event.

LER 80-021 Omaha Public Power District Fort Calhoun Station Unit No. 1 Docket NO. 05000285

ATTACHMENT NO. 3

Fai'ure Data

This is the second failure of this type at the Forc Calhoun Station. The first being documented per LER 80-014.