

# LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONTROL BLOCK: \_\_\_\_\_ (1)

0 1 | N C B E P 1 | 2 | 0 0 - 0 0 0 0 0 0 - 0 0 | 3 | 4 1 1 1 1 | 4 | \_\_\_\_\_ | 5  
7 8 9      14 15      25 26      57 CAT 58

CON'T  
0 1 | REPORT SOURCE | L | 6 | 0 5 0 - 0 3 2 5 | 7 | 0 9 1 4 8 0 | 8 | 1 0 0 7 8 0 | 9  
7 8      60 61      DOCKET NUMBER      68 69      EVENT DATE      74 75      REPORT DATE      80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During the performance of PT 2.6.5P, Primary Containment Leak Rate Testing on the  
0 3 | personnel interior and exterior doors, following a drywell entry at power, it was  
0 4 | found that the inner airlock door seals would not hold the required pressure for the  
0 5 | specified length of time. This event did not affect the health or safety of  
0 6 | the public.  
0 7 | \_\_\_\_\_

Technical Specifications 3.6.1.3, 6.9.1.9b

0 9 | SYSTEM CODE | S D | 11 | CAUSE CODE | E | 12 | CAUSE SUBCODE | B | 13 | COMPONENT CODE | P E N E T R | 14 | COMP. SUBCODE | A | 15 | VALVE SUBCODE | Z | 16  
7 8      9 10      11 12      13 14      18 19      20 21  
17 | LER/RO REPORT NUMBER | 8 0 | 21 22 | SEQUENTIAL REPORT NO. | 0 7 4 | 24 26 | OCCURRENCE CODE | / | 27 | REPORT TYPE | L | 30 | REVISION NO. | 0 | 32  
18 | ACTION TAKEN | X | 33 | FUTURE ACTION | X | 34 | EFFECT ON PLANT | Z | 35 | SHUTDOWN METHOD | Z | 36 | HOURS | 0 0 0 0 | 37 40 | ATTACHMENT SUBMITTED | N | 41 | NPRD-4 FORM SUB. | Y | 42 | PRIME COMP. SUPPLIER | N | 43 | COMPONENT MANUFACTURER | C 3 1 0 | 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | An investigation revealed that slight door misalignment prevented the door seal from  
1 1 | making proper contact with the sealing surfaces of the airlock. The door strongbacks  
1 2 | were installed to fully seat the door seals and the PT was successfully completed.  
1 3 | The outer airlock door was checked and found satisfactory. The inner door will be  
1 4 | inspected and repaired as necessary during the next available outage.

1 5 | FACILITY STATUS | C | 28 | % POWER | 0 1 1 | 29 | OTHER STATUS | NA | 30 | METHOD OF DISCOVERY | B | 31 | DISCOVERY DESCRIPTION | Periodic Test | 32  
7 8 9      10 12 13      44 45 46      80  
1 6 | ACTIVITY RELEASED | Z | 33 | CONTENT OF RELEASE | Z | 34 | AMOUNT OF ACTIVITY | NA | 35 | LOCATION OF RELEASE | NA | 36  
7 8 9      10 11      44 45      80  
1 7 | PERSONNEL EXPOSURES NUMBER | 0 0 0 | 37 | TYPE | Z | 38 | DESCRIPTION | NA | 39  
7 8 9      11 12      13      80  
1 8 | PERSONNEL INJURIES NUMBER | 0 0 0 | 40 | DESCRIPTION | NA | 41  
7 8 9      11 12      13      80  
1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE | Z | 42 | DESCRIPTION | NA | 43

POOR ORIGINAL

2 0 | PUBLICITY ISSUED | N | 44 | DESCRIPTION | 8010150 529 | 45 | NA | 46  
7 8 9      10      11      80  
NRC USE ONLY