

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | I | L | Q | A | D | 1 | 2 | 0 | 0 | 0 | 0 | - | 0 | 0 | 0 | - | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 1 | 4 | _____ | 5

01 | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 5 | 4 | 7 | 0 | 9 | 1 | 9 | 8 | 0 | 8 | 0 | 9 | 2 | 2 | 8 | 0 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | While performing the feedwater check valve Local Leak Rate Test, the leakage through
03 | feedwater check valve 1-220-62A was found to be excessive. The subvolume could not be
04 | pressurized. Consequently a leakage cannot be calculated, but leakage is in excess of
05 | the allowable limit of 18.36 scfh as specified by Technical Specification 4.7.A.2.i.2.
06 | Check valve 1-220-62A will be repaired and tested before unit startup. In line check
07 | valve 1-220-58A was found to have leakage within the allowable limit.

09 | C | H | 11 | E | 12 | B | 13 | V | A | L | V | E | X | 14 | C | 15 | D | 16

17 | 8 | 0 | - | 0 | 2 | 1 | 0 | 3 | L | - | 0

18 | Z | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | N | 23 | Y | 24 | N | 25 | C | 6 | 6 | 5 | 21

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | A final report will follow upon completion of leak rate testing.
11 | _____
12 | _____
13 | _____
14 | _____

15 | H | 26 | 0 | 0 | 0 | 29 | NA | 30 | B | 31 | Local Leak Rate Test | 32

16 | Z | 33 | Z | 34 | NA | 35 | NA | 36

17 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39

18 | 0 | 0 | 0 | 40 | NA | 41

19 | Z | 42 | NA | 43

20 | N | 44 | NA | 45