

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 N C R F P 2 2 0 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

CON'T 01 REPORT SOURCE L 6 0 5 0 - 0 3 2 4 7 0 4 1 0 8 1 8 0 5 0 7 8 1 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
02 During the performance of the RCIC System 1000 PSIG Flow Rate Test, PT 10.1.1, the
03 RCIC turbine tripped due to overspeed making the RCIC System inoperable. At the
04 time of this event, the HPCI System was operable. This event did not affect
05 the health and safety of the public.
06
07
08 Technical Specification 3.7.4, 6.9.1.9b

09 SYSTEM CODE C E 11 CAUSE CODE E 12 CAUSE SUBCODE F 13 COMPONENT CODE I N S T R U 14 COMP SUBCODE P 15 VALVE SUBCODE Z 16
17 LER NO REPORT NUMBER 8 1 0 3 9 0 3 L 0
ACTION TAKEN C 18 X 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 ATTACHMENT SUBMITTED Y 23 NPRD-4 FORM SUB. Y 24 PRIME COMP. SUPPLIER N 25 COMPONENT MANUFACTURER X 9 9 9 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10 An open voltage dropping resistor, R1, to the 48 vdc power supply in the RCIC turbine
11 Electronic Governor Module (EGM) caused a loss of turbine speed control and the
12 encountered overspeed trip. The resistor was replaced and the RCIC System was satis-
13 factorily tested and returned to service. Engineering Work Request (EWR) No. 81-129
14 has been submitted to evaluate this power supply and modify as required.

15 FACILITY STATUS F 28 % POWER 0 3 9 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Periodic Test 32

16 ACTIVITY CONTENT Z 33 Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36

17 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39

18 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43

20 PUBLICITY ISSUED N 44 DESCRIPTION 8 1 0 5 1 8 0 2 7 5 NA 45 NRC USE ONLY 68 69 80