LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 N Y J A F 1 2 0 0 - C 0 0 0 - 0 0 3 4 1 1 1 1 4 5 5 CAT 58
CON'T SOUNCE CON'T CON'
During normal startup operations, torus water level decreased to 0.15 inches below
the limit of Technical Specification 3.7.A.1.a. while containment inerting was in
progress. The actual volume of water in the torus had not decreased but the existance
of a positive differential pressure between torus and drywell caused a lower indicated
[0] [level. No significant hazard existed.
OB L
7 8 9 SYSTEM CAUSE CAUSE CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCODE
7 8 ZZZ 11 A 12 A 13 ZZZZZZ 14 ZZ 15 ZZ 16 SEQUENTIAL OCCURRENCE REPORT REVISION
LER RO EVENT YEAR SEQUENTIAL REPORT NO. 17 REPORT NUMBER 21 22 23 29 10 3 2
ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. COMPONENT TAKEN ACTION ON PLANT METHOD HOURS 22 SUBMITTED FORM SUB. SUPPLIER MANUFACTURER
X (8) Z (9) Z (20) Z (21) [0 0 0 0 0 N (23) N (24) Z (25) Z 9 9 9 (26)
Personnel error was the cause. Addition of water to the torus returned level to
[18] [18] [18] [18] [18] [18] [18] [18]
within Technical Specification Limits within a few minutes.
within Technical Specification Limits within a few minutes.
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
1 3 L 1 4 L 7 8 9 FACILITY SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32
TIZE
1 2 1 3 1 4 1 5 1 6 2 3 3 2 34 NA NA NA NA NA NA NA N
1 3
1 3 1 4 1 5 1 6 2 7 3 3 1 1 2 1 3 1 1 1 2 1 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
1 3
1 2
1 2 2 3 9 9 9 9 9 9 9 9 9
1 2 1 3 1 4 7 8 9 1 5