

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 A L B R F 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 14 15 25 26 30 37 CAT 38

CON'T
0 1 REPORT SOURCE L 6 0 5 0 0 0 2 5 9 7 0 2 2 6 8 1 8 0 3 0 9 8 1 9
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During planned operation, secondary containment integrity was lost when an
0 3 exterior equipment access door No. 229 was open for fuel receipt, and simultaneously
0 4 an interior personnel door No. 228 was open to perform maintenance on the door
0 5 itself. See Tech. Spec, 3.7.C.1. There was no hazard to the health or safety
0 6 of the public. No previous occurrences.
0 7
0 8

0 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
S D 11 X 12 Z 13 Z Z Z Z Z Z 14 Z 15 Z 16
7 8 9 10 11 12 13 18 19 20
17 LER/RO REPORT NUMBER EVENT YEAR SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRO-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
8 1 0 0 8 0 1 T 0
21 22 23 24 26 27 28 29 30 31 32
X 18 X 19 Z 20 Z 21 0 0 0 0 Y 23 N 24 Z 25 Z 9 9 9 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 There are no interlocks between the two doors to prevent them from being opened
1 1 simultaneously. A DCR has been submitted to ENDES to install interlocks.
1 2 As an interim measure, administrative controls have been established to prevent
1 3 the doors being opened simultaneously.
1 4

1 5 FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
E 28 0 9 8 29 NA B 31 NRC Inspector Observation
7 8 9 12 13 44 45 46 80
1 6 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
Z 33 Z 34 NA
7 8 9 10 11 44 45 80
1 7 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
0 0 0 37 Z 38 NA
7 8 9 11 12 13 80
1 8 PERSONNEL INJURIES NUMBER DESCRIPTION
0 0 0 40 NA
7 8 9 11 12 80
1 9 LOSS OF OR DAMAGE TO FACILITY TYP. DESCRIPTION
Z 42 NA
7 8 9 10 80
2 0 PUBLICITY ISSUED DESCRIPTION
Z 44 NA
7 8 9 10 80

8108160757

NRC USE ONLY

LER SUPPLEMENTAL INFORMATION

BPFC-50- 259 / 81008 Technical Specification Involved 3.7.C.1

Reported Under Technical Specification 6.7.2.A.6

Date of Occurrence 2/26/81 Time of Occurrence 0800 Unit common

Identification and Description of Occurrence:

Secondary containment integrity was lost when doors 228 and 229 were open simultaneously. Door 229 was open for fuel receipt and door 228 was open for the performance of maintenance on the door itself.

Conditions Prior to Occurrence:

Unit 1 at 1083 MWe.

Unit 2 shutdown.

Unit 3 shutdown.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

None

Apparent Cause of Occurrence:

Doors do not have interlocks.

Analysis of Occurrence:

There was no damage to plant equipment. There was no activity release, no personnel exposure or injury, and no danger to the health or safety of the public.

Corrective Action:

A DCR has been submitted to ENDES to install interlocks. As an interim measure, administrative controls have been established to prevent the doors 228 and 229 from being opened simultaneously. Door No. 232, located between door 228 and door 229, is being evaluated for acceptability as a secondary containment barrier.

Failure Data:

None

*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

*Revision: