



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION III  
799 ROOSEVELT ROAD  
GLEN ELLYN, ILLINOIS 60137

March 4, 1981

Gentlemen:

IE Bulletin No. 81-01 has been revised to change the identification of the power reactor facilities with construction permits to which the bulletin is applicable. This change does not affect your requirements with respect to the bulletin. As a result, the enclosed revised pages 5 and 6 are forwarded to you for information.

Should you have any questions regarding this bulletin revision, please contact this office.

Sincerely,

*A Bert Danner*

*for* James G. Keppler  
Director

Enclosure: IE Bulletin  
No. 81-01, Revision 1

8103160856

Q

Docket No. 50-440  
Docket No. 50-441

The Cleveland Electric Illuminating  
Company  
ATTN: Mr. Dalwyn R. Davidson  
Vice President - System  
Engineering and Construction  
Post Office Box 5000  
Cleveland, OH 44101

cc w/encl:  
✓ Central Files  
AD/Licensing  
AD/Operating Reactors  
PDR  
Local PDR  
NSIC  
TIC  
Harold W. Kohn, Power  
Siting Commission  
Daniel D. Wilt, Attorney  
Helen W. Evans, State of Ohio



SSINS No.: 6820  
Accession No.:  
8005050075

UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
OFFICE OF INSPECTION AND ENFORCEMENT  
WASHINGTON, D.C. 20555

IE Bulletin No. 81-01  
January 27, 1981  
Page 1 of 7

SURVEILLANCE OF MECHANICAL SNUBBERS

Description of Circumstances:

Several instances of failures of mechanical snubbers supplied by International Nuclear Safeguards Corporation (INC) have been identified that indicate possible deficiencies in these snubbers. A summary of the failures that have occurred is provided below:

1. On August 9, 1974, the Tennessee Valley Authority submitted event report BFAO-50-260/741W identifying 11 of 14 INC Model MSVA-1A snubbers that were found inoperable on Browns Ferry Nuclear Power Station Unit 2 and subsequently identified 5 of 14 inoperable units on Browns Ferry Nuclear Power Unit No 3. All of these units were found to be frozen, and the cause was attributed to a failure to lubricate the parts during assembly. The failed snubbers were replaced with new units produced by the same manufacturer.
2. On April 12, 1976, the St. Lucie Plant Unit 1 facility of Florida Power and Light Company submitted event report No. 50-335-76-9 wherein five INC Model MSVA-1 snubbers were identified as inoperable because they were found to be frozen. The failures were caused by oxidation on the internals and by improper assembly. All INC mechanical snubbers were replaced with units produced by another manufacturer.
3. On April 8, 1977, Iowa Electric Light and Power Company submitted event report No. 77-23 for the Duane Arnold Energy Center facility that identified 13 INC Model 1MSVA-1 Type AS snubbers to be frozen; the cause of failure was attributed to large amounts of interior oxidation. The units were replaced with those produced by another manufacturer.
4. On December 5, 1979, personnel from the Nuclear Regulatory Commission visited Department of Energy (DOE) facilities at Richland, Washington, to obtain information on DOE experience with INC snubbers at the Fast Flux Test Facility (FFTF). The DOE-owned 4,000 mechanical pipe restraints (snubbers) at the FFTF examined more than 800 of these

DUPLICATE DOCUMENT

Entire document previously  
entered into system under:

ANO 8005050075

No. of pages: 8