

### UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION II 101 MARIETTA ST., N.W., SUITE 3100 ATLANTA, GEORGIA 30303

MAR 1 1 1981

In Reply Refer To: RII:JPO 50-416 50-417

Mississippi Power and Light Company ATTN: N. L. Stampley Vice President of Production P. O. Box 1640 Jackson, MS 39205

Gentlemen:

The enclosed IE Information Notice No. 81-06 contains information that may be applicable to your facility regarding the failure of an ITE Model K-600 circuit breaker. No specific action or response is requested at this time; however, pending the results of NRC staff evaluations of this matter, further licensee actions may be requested.

Should you have any questions regarding this information notice, please contact this office.

Sincerely,

James P. O'Reilly

Director

Enclosures:

1. IE Information Notice No. 81-06

2. List of Recently Issued IE Information Notices

cc w/encl:

C. K. McCoy, Plant Manager

SSINS No.: 6835 Accession No.: 8011040269 IN 81-06

# DUPLICATE

# UNITED STATES NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT WASHINGTON, D.C. 20555

March 11, 1981

IE Information Notice No. 81-06: FAILURE OF ITE MODEL K-600 CIRCUIT BREAKER

#### Purpose:

The purpose of this information notice is to provide early notification of a matter that could adversely affect the safety of nuclear power plants. Toward this end, this information notice alerts holders of operating licenses and construction permits of a possibly generic deficiency involving Model K-600 circuit breakers manufactured by ITE.

#### Description of Circumstance:

By letter dated February 20, 1981, the Sacramento Municipal Utility District informed us that, while performing preventive maintenance on electrical circuit breakers at its Rancho Seco facility, an ITE Model K-600 breaker was observed not to trip. An investigation revealed that a tripping coil wire had slipped out of its terminal. Further examinations revealed that the coil wire size was AWG 20, whereas the mating lug was sized for AWG 16-14 wire. A check of other ITE electrical breakers indicated that the problem may be generic. Subsequent to the letter, the Sacramento Municipal Utility District informed us orally that ITE Model K-1600 breakers have the same deficiency and that Model K-3000 breakers may be similarly affected.

The information provided by the Sacramento Municipal Utility District is preliminary and will be followed by a complete report. Consequently, we have not yet evaluated the safety significance of this event. Nevertheless, the information herein is being provided as an early notification of a possibly significant event. Although no specific action or response is requested at this time, recipients should review the information for possible applicability to their facilities. If NRC evaluations so indicate, further licensee actions may be requested.

If you have any questions regarding the information contained herein, please contact the Director of the appropriate NRC Regional Office.

Attachment:

Recently issued IE Information Notices

## RECENTLY ISSUED IE INFORMATION NOTICES

| Information |  | Date of  |   |
|-------------|--|----------|---|
| Notice No.  | Subject  | Issue    | Issued to   |
| 81-05       | Degraded DC System at<br>Palisades   | 2/10/81  | All power reactor<br>facilities with an<br>OL or CP |
| 81-04       | Cracking in Main Steam<br>Lines  | 2/27/81  | All power reactor facilities with an OL             |
| 81-03       | Checklist for Licensees<br>Making Notifications of<br>Significant Events in<br>Accordance with 10<br>CFR 50.72 | 2/12/81  | All power reactor facilities with an OL             |
| 81-02       | Transportation of .<br>Radiography Devices   | 1/23/81  | All Radiography<br>licensees                        |
| 81-01       | Possible Failures of<br>General Electric Type<br>HFA Relays  | 1/16/81  | All power reactor facilities with an OL or CP.      |
| 80-45       | Potential Failure of<br>BWR Backup Manual Scram<br>Capability  | 12/17/80 | All PWR facilities with an OL or CP                 |
| 80-44       | Actuation of ECCS in the Recirculation Mode While in Hot Shutdown  | 12/16/80 | All PWR facilities with an OL or CP                 |
| 80-43       | Failures of the Continuous<br>Water Level Monitor for<br>the Scram Discharge Volume<br>at Dresden Unit No. 2   | 12/5/80  | All power reactor facilities with an OL or CP       |
| 80-42       | Effect of Radiation on<br>Hydraulic Snubber Fluid  | 11/24/80 | All power reactor<br>facilities with an<br>OL or CP |
| 80-41       | Failure of Swing Check<br>Valve in the Decay Heat<br>Removal System at Davis-<br>Besse Unit No. 1              | 11/10/80 | All power reactor<br>facilities with an<br>OL or CP |

OL = Operating Licenses CP = Construction Permits