LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK:
A R A N O 2 O O O O O O O O
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
[0] During Mode 1 operation, while performing a Containment Cooler monthly
[0,3] [Surveillance test, the Loop Two Service Water Header ESF Isolation Valve,]
2CV-1406-2, would not open from the Control Room. The valve was placed
[0]5 in its ES position, returning the Loop Two Service Water Header to oper-
[0]6 able status. Loop One remained operable. There have been no similar
[0]7 loccurrences. Reportable per T.S.6.9.1.9.b.
7 8 9
SYSTEM CAUSE CODE CODE SUBCODE COMPONENT CODE SUBCODE
1) REPORT VEAR
TAKEN ACTION ON PLANT SHUTTOWN HOURS 22 ATTACHMENT SUPPLIER COMPONENT MANUFACTURER B 18 2 9 12 20 1 0 0 0 0 N 23 N 24 A3 25 R 1 1 0 12 X
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) [1] Maintenance investigation revealed that the valve stem was binding, causing
[1] the valve operator to torque out. The valve was lubricated and exercised
[1]2 [and returned to service.
131
7 8 9 FACILITY STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32
1 E 3 LOI7 6 NA B Surveillance Test
ACTIVITY CONTENT 12 13 44 45 46 80 RELEASE OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
1 6 Z 3 Z 34 NA
17 0 0 0 0 0 X Z 38 NA
PERSONNEL INJURIES NUMBER DESCRIPTION 41
7 8 9 11 12 LOSS OF OR DAMAGE TO FACILITY (43)
1 9 Z 42 NA
PUBLICITY ISSUED DESCRIPTION (5) NRC USE ONLY
7 8 9 10 68 69 80
NAME OF PREPARER Chris N. Shively 501/968-2519